



Explanation

- Location of seismic profile shown on Plate 3b
- Time slice horizon
- Faults, soild where well located, dashed where inferred or approximately located, queried where uncertain, dotted where buried by more than 20 milliseconds of undeformed strata
- Syncline
- Anticline
- Monocline

Amplitude: High – Low

Note: Depth values on seismic profile assume a velocity of 1600 m/sec.

Principal structural elements in the northern part of the study area showing faults and folds in (a) 2D seismic-reflection profile 1399 and (b) on amplitude time slice map at 150 ms (TWTT)

DCPP 3D/2D Seismic-Reflection Investigation

Pacific Gas and Electric Company

Figure 19

File path: S:\13800\13838\13838.002\Figures\20120210_SITA\Figure_19.ai; Date: 07/09/2012; User: Jereme Chandler, LCI