

FIGURE 8.5-1
NOISE MONITORING AND RECEPTOR LOCATIONS
MID ELECTRIC GENERATION STATION

CH2MHILL

File Path: \\thor\cart1\rddgis\mid\megs_NOISE.mxd, Date: 04 15, 2003,