

State of California — The Resources Agency  
 DEPARTMENT OF PARKS AND RECREATION  
**PRIMARY RECORD**

Primary	
HRI #	
Trinomial	
NRHP Status Code	
Other	
Review Code	Reviewer
	Date

Page 1 of 3 \*Resource Name or #: (Assigned by Recorder) 6001 State Street

**P1. Other Identifier:** \_\_\_\_\_

**\*P2. Location:** Not for Publication  Unrestricted \*a. County Los Angeles

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad South Gate Date 1978 T 2S ; R 13W ; 1/4 of 1/4 of Sec 1 ; S.B. B.M  
 c. Address 6001 State Street City Huntington Park Zip 90255  
 d. UTM: (Give more than one for large and/or linear resources) Zone: 11 ; \_\_\_\_\_ mE/ \_\_\_\_\_ mN  
 e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc., as appropriate)  
 APN # 6310-024-001

**\*P3a. Description** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The structure consists of a single story rectangular retail auto service shop. The roof is flat and sealed with tar. Exterior walls are stucco over wood. The windows for the most part are asymmetrical. Windows on the State Street facing are one-over-one, single-hung sash, horizontal slide, and one large single pane. All windows are barred. One entry door (panel) is located between the window and two large sliding bay doors to the service area. The structure is in fair condition and has undergone renovations over the years.

The setting is a mix of small-scale residential and commercial/industrial. The building, which fronts on State Street, is located at the corner of Belgrave Ave. and State Street, surrounded by single- and multi-family residential dwellings, and commercial/industrial buildings.

**\*P3b. Resource Attributes:** (List attributes and codes) HP6 (1-3 story commercial building)

**\*P4. Resources present:**  Building  Structure  Object  Site  District  Element of District  Other (isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)

P5b. Description of Photo: (View, date, accession #)  
 View facing west.

**\*P6. Date Constructed/Age and Sources:**  Historic  
 Prehistoric  Both  
1948-1952

---

**\*P7. Owner and Address:**  
 Iglesias, Anastasio and Ana  
 6001 State Street  
 Huntington Park, CA 90255

**\*P8. Recorded by:** (Name, affiliation, and address)  
 Kelly Heidecker and Jeff Creighton  
 Parsons  
 2233 Watt Ave, Suite #330  
 Sacramento, CA 95825

---

**\*P9. Date Recorded:**  
**June 30, 2002**

**\*P10. Survey Type:** (Describe)  
 Intensive

**\*P11. Report Citation:** (Cite survey report and other sources, or enter "none.") Malburg Generating Station Project Cultural Resources Inventory Report

**\*Attachments:** NONE  Location Map  Sketch Map  Continuation Sheet  Building, Structure, and Object Record  
 Archaeological Record  District Record  Linear Feature Record  Milling Station Record  Rock Art Record  
 Artifact Record  Photograph Record  Other (List): \_\_\_\_\_