

-State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION PRIMARY RECORD		Primary	
		HRI #	
		Trinomial	
		NRHP Status Code	
Other			
Review Code		Reviewer	Date

Page 1 of 4 *Resource Name or #: (Assigned by Recorder) 6061 State Street

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted *a. County Los Angeles

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad South Gate Date 1978 T 2S; R 13W; 1/4 of 1/4 of Sec 1; S.B. B.M

c. Address 6061 State Street City Huntington Park Zip 90255

d. UTM: (Give more than one for large and/or linear resources) Zone: 11; _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc., as appropriate)
 APN # 6310-025-003

***P3a. Description** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)
 This structure is a rectangular shaped corrugated metal building with a concrete/masonry façade, typical of early American West architecture. The façade is topped by a flat cornice running the length of the façade. One set of cncasement windows adorns the front of the building, outlined by masonry molding. The front double doors and entryway are recessed approximately 18 inches. A rectangular transom is featured above the entry doors. The remaining structure is comprised of corrugated sheet metal, with a combination of single- and double-hung sash windows of various sizes. The structure is in poor condition and has been modified.

The setting is a mix of small-scale residential and commercial/industrial. The building fronts on State Street and is surrounded by commercial/industrial buildings and single- and multi-family residential dwellings.

***P3b. Resource Attributes:** (List attributes and codes) HP6 (1-3 story commercial building)

***P4. Resources present:** Building Structure Object Site District Element of District Other (isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)

See Continuation sheet for photos.

P5b. Description of Photo: (View, date, accession #)
 See Continuation sheet for photos.

***P6. Date Constructed/Age and Sources:** Historic
 Prehistoric Both
 1929

***P7. Owner and Address:**
Hector Gutierrez
6061 State Street
Huntington Park, CA 90255

***P8. Recorded by:** (Name, affiliation, and address)
 Kelly Heidecker and Jeff Creighton
 Parsons
 2233 Watt Ave, Suite #330
 Sacramento, CA 95825

***P9. Date Recorded:**
June 30, 2002

***P10. Survey Type:** (Describe)
 Intensive

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") Malburg Generating Station Project Cultural Resources Inventory Report

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____