

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

OWENS CORNING FIBERGLAS CORP (Continued)

1000319123

Gepaid: CAD009149485
 Tepaid: CAT000646117
 Gen County: Santa Clara
 Tsd County: Kings
 Tons: 16.8560
 Category: Unspecified sludge waste
 Disposal Method: Treatment, Tank
 Contact: OWENS CORNING WORLD HEADQTRS
 Telephone: (419) 248-8000
 Mailing Address: PO BOX 89
 SANTA CLARA, CA 95052 - 0089
 County: Santa Clara

The CA HAZNET database contains 80 additional records for this site.
 Please contact your EDR Account Executive for more information.

FID:

Facility ID:	43000096	Regulate ID:	CAD009149
Reg By:	Active Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(408) 727-3535
Status:	Active		
Mail To:	Not reported		
	FIBERGLAS TOWER		
	SANTA CLARA, CA 95050		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

SLIC Region 2:

Facility ID:	43S0208		
Region:	2		
Facility Status:	Active		Not reported
Staff:	VAC		Not reported
Last Site Update:	12/17/19		
NPL Status:	Not an NPL site	Discovery Date:	10/25/1983
Case List:	SLIC	Imaged:	No
Date Closed:	Not reported	Cost Recovery:	YES
Abate Method:	Not reported	Substance:	Not reported
Case Type:	TK	Sample Date:	02/15/1989
Contamination:	PETROL TANK & OFFSITE PLUME (SEE MONSANTO & CAMSI)		
Lead:	2189.8255 RWQCB		
Contamination Level:			NOT DETERMINED
Number of Municipal Wells Contaminated by Site:	0		
Number of Private Wells Contaminated by Site:	0		
Soil Removal Action Taken/Needed:	Yes		
Soil Removal or Contaminant Action Started:	12/19/1989		
Soil Removal or Contaminant Action Completed:			
On-Site Groundwater Extraction or Containment is Needed:	No		
On-Site Groundwater Extraction or Containment Started:			
Off-Site Groundwater Extraction or Containment is Needed:	Not Determined		
Off-Site Groundwater Extraction or Containment Started:			
Length of Contamination Plume (Feet):	0		
Depth of Contamination Plume (Feet):	0		
Wells Closed Due To Contamination of Site:			
Date of Wells Closure:			
Nearest Public or Private Drinking Water Well (Feet):	5280		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

OWENS CORNING FIBERGLAS CORP (Continued)

1000319123

Under Jurisdiction of Lead Agency Date: 10/1/83
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes
 Begun Remediation: No
 Completed Remediation: No
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: MANUFACTURING PLANT
 Comment: Not reported

UST HIST:

Facility ID: 1069	Container Num: 1
Tank Num: 1	Year Installed: 1980
Tank Capacity: 4000	
Tank Used for: PRODUCT	Tank Construction: .22 inches
Type of Fuel: UNLEADED	
Leak Detection: GW Monitoring Well	Telephone: (408) 727-3535
Contact Name: GERALD E. FULLER	Region: STATE
Total Tanks: 2	Other Type: MANUFACTURING
Facility Type: 2	
Facility ID: 1069	Container Num: 2
Tank Num: 2	Year Installed: 1980
Tank Capacity: 2000	
Tank Used for: PRODUCT	Tank Construction: 0.22 inches
Type of Fuel: Not Reported	
Leak Detection: GW Monitoring Well	Telephone: (408) 727-3535
Contact Name: GERALD E. FULLER	Region: STATE
Total Tanks: 2	Other Type: MANUFACTURING
Facility Type: 2	

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

OWENS CORNING FIBERGLAS CORP (Continued)

1000319123

AST:

Region: 2
Owner: OWENS CORNING SANTA CLARA PLAN

Q68
NNW
1/8-1/4
1098
Higher

SPRAYTRONICS INC
930 GEORGE ST
SANTA CLARA, CA 95054

HAZNET S102816141
N/A

Site 1 of 2 in cluster Q

HAZNET:

Gepaid: CAL000083346
Tepaid: CAD008302903
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 6.4218
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Recycler
Contact: STEVEN G PEREZ
Telephone: (408) 988-3636
Mailing Address: 3060 RAYMOND STREET
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAL000083346
Tepaid: ARD981057870
Gen County: Santa Clara
Tsd County: 99
Tons: 1.5470
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Contact: STEVEN G PEREZ
Telephone: (408) 988-3636
Mailing Address: 3060 RAYMOND STREET
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAL000083346
Tepaid: CAD008302903
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 6.5886
Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method: Recycler
Contact: STEVEN G PEREZ
Telephone: (408) 988-3636
Mailing Address: 3060 RAYMOND STREET
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAL000083346
Tepaid: CAD008302903
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 10.3832
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Recycler
Contact: STEVEN G PEREZ
Telephone: (408) 988-3636
Mailing Address: 3060 RAYMOND STREET

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SPRAYTRONICS INC (Continued)

S102816141

County SANTA CLARA, CA 95054
 Santa Clara
 Gepaid: CAL000083346
 Tepaid: CAT080014079
 Gen County: Santa Clara
 Tsd County: 7
 Tons: .8340
 Category: Unspecified organic liquid mixture
 Disposal Method: Transfer Station
 Contact: STEVEN G PEREZ
 Telephone: (408) 988-3636
 Mailing Address: 3060 RAYMOND STREET
 SANTA CLARA, CA 95054
 County Santa Clara

The CA HAZNET database contains 2 additional records for this site.
 Please contact your EDR Account Executive for more information.

O69
 North
 1/8-1/4
 1129
 Higher

BASCOM TRIM & UPHOLSTRY
3340 BASSETTS STREET
SANTA CLARA, CA 00000

HAZNET S103653660
N/A

Site 4 of 4 in cluster O

HAZNET:
 Gepaid: CAL000050109
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .1918
 Category: Unspecified solvent mixture Waste
 Disposal Method: Recycler
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 3340 BASSETTS STREET
 SANTA CLARA, CA 00000
 County Santa Clara

R70
 SW
 1/8-1/4
 1148
 Higher

ANALOG DEVICES
1201 COMSTOCK
SANTA CLARA, CA 95054

HAZNET S103625360
N/A

Site 1 of 2 in cluster R

HAZNET:
 Gepaid: CAC001371368
 Tepaid: CAD981382732
 Gen County: Santa Clara
 Tsd County: 1
 Tons: 12.6420
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: ANALOG DEVICES
 Telephone: (408) 562-7253
 Mailing Address: 1500 SPACE PARK DR
 SANTA CLARA, CA 95054
 County Santa Clara

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s) EDR ID Number
 EPA ID Number

Q71 **PAINTIN PLACE INC THE**
NNW **940 GEORGE ST**
1/8-1/4 **SANTA CLARA, CA 95050**
1149
Higher **Site 2 of 2 in cluster Q**

RCRIS-SQG **1000322413**
FINDS **CAD980694749**

RCRIS:

Owner: GARY VOGEL
 (415) 555-1212
 EPA ID: CAD980694749
 Contact: ENVIRONMENTAL MANAGER
 (415) 555-1212

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 National Emissions Trends (NET)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

72 **WASTE MANAGEMENT OF SANTA CLARA COUNTY**
SSE **715 COMSTOCK STREET**
1/8-1/4 **SANTA CLARA, CA 95054**
1154
Higher

HAZNET **S103670150**
 N/A

HAZNET:

Gepaid: CAD981396807
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .8131
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: COUNTY OF SANTA CLARA
 Telephone: (408) 845-5401
 Mailing Address: 715 COMSTOCK ST
 SANTA CLARA, CA 95054 - 3403
 County Santa Clara

 Gepaid: CAD981396807
 Tepaid: CAD980695761
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .0000
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Not reported
 Contact: COUNTY OF SANTA CLARA
 Telephone: (408) 845-5401
 Mailing Address: 715 COMSTOCK ST
 SANTA CLARA, CA 95054 - 3403
 County Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WASTE MANAGEMENT OF SANTA CLARA COUNTY (Continued)

S103670150

Gepaid: CAD981396807
Tepaid: CAD980695761
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .9174
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: COUNTY OF SANTA CLARA
Telephone: (408) 845-5401
Mailing Address: 715 COMSTOCK ST
SANTA CLARA, CA 95054 - 3403
County Santa Clara

Gepaid: CAD981396807
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .9174
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: COUNTY OF SANTA CLARA
Telephone: (408) 845-5401
Mailing Address: 715 COMSTOCK ST
SANTA CLARA, CA 95054 - 3403
County Santa Clara

Gepaid: CAD981396807
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .7923
Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Contact: COUNTY OF SANTA CLARA
Telephone: (408) 845-5401
Mailing Address: 715 COMSTOCK ST
SANTA CLARA, CA 95054 - 3403
County Santa Clara

The CA HAZNET database contains 10 additional records for this site.
Please contact your EDR Account Executive for more information.

S73
SSE
1/8-1/4
1168
Higher

SOBARTO DEVELOPMENT
800 CENTRAL EXPRESSWAY
SANTA CLARA, CA 95051

HAZNET S103988377
N/A

Site 1 of 3 in cluster S

HAZNET:
Gepaid: CAC001370528
Tepaid: CAD028409019
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 4.6354
Category: Other organic solids
Disposal Method: Transfer Station
Contact: SOBARTO DEVELOPMENT
Telephone: (408) 446-0700
Mailing Address: 10600 N DE ANZA

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SOBARTO DEVELOPMENT (Continued)

S103988377

CUPERTINO, CA 95014
 County Santa Clara

**S74
 SSE
 1/8-1/4
 1168
 Higher**

**APPLIED MATERIALS BLDG 77
 800 CENTRAL EXPRESSWAY
 SANTA CLARA, CA 95050**

**RCRIS-SQG 1000110117
 FINDS CAD982411688**

Site 2 of 3 in cluster S

RCRIS:

Owner: APPLIED MATERIALS INC
 (408) 727-5555
 EPA ID: CAD982411688
 Contact: SHREE DHARASKER
 (408) 563-6763

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

**S75
 SSE
 1/8-1/4
 1179
 Higher**

**SOBRATO DEVELOPMENT COMPANIES
 800 CENTRAL EXPWAY
 SANTA CLARA, CA 95050**

**CA SLIC S101542546
 N/A**

Site 3 of 3 in cluster S

SLIC Region 2:

Facility ID:	43S0694		
Region:	2		
Facility Status:	Inactive		Not reported
Staff:	Not reported		Not reported
Last Site Update:	08/17/19		
NPL Status:	Not an NPL site	Discovery Date:	Not reported
Case List:	SLIC	Imaged:	No
Date Closed:	Not reported	Cost Recovery:	No
Abate Method:	Not reported	Substance:	Not reported
Case Type:	NT	Sample Date:	12/13/1986
Contamination:	Not reported		
Lead:	RWQCB		

Contamination Level:

Number of Municipal Wells Contaminated by Site:	0
Number of Private Wells Contaminated by Site:	5
Soil Removal Action Taken/Needed:	0
Soil Removal or Contaminant Action Started:	
Soil Removal or Contaminant Action Completed:	0
On-Site Groundwater Extraction or Containment is Needed:	0
On-Site Groundwater Extraction or Containment Started:	
Off-Site Groundwater Extraction or Containment is Needed:	0
Off-Site Groundwater Extraction or Containment Started:	
Length of Contamination Plume (Feet):	0
Depth of Contamination Plume (Feet):	0

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SOBRATO DEVELOPMENT COMPANIES (Continued)

S101542546

Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 0 / 0
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : No
 Completed Characterization : No
 Begun Remediation: No
 Completed Remediation: No
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: FORMER CONCRETE-PIPE MANUFACTURING FACILITY
 Comment: Not reported

T76
 North
 1/8-1/4
 1194
 Higher

SILICON SERVICES INC
3400 BASSETT ST
SANTA CLARA, CA 95054

RCRIS-SQG 1000247353
FINDS CAD098530124

Site 1 of 2 in cluster T

RCRIS:
 Owner: SILICON SERVICES INC
 (415) 555-1212
 EPA ID: CAD098530124
 Contact: ENVIRONMENTAL MANAGER
 (408) 496-1147
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

R77
 SW
 1/8-1/4
 1197
 Higher

1025 COMSTOCK
SANTA CLARA, CA 95050
Site 2 of 2 in cluster R

CHMIRS S100275450
N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

(Continued)

S100275450

CHMIRS:

OES Control Number:	8910812	DOT ID:	Not reported
DOT Hazard Class:	Not Reported		
Chemical Name:	SILANE		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	10
Environmental Contamination:	Other	Property Use:	Manufacturing
Incident Date:	17-OCT-89	Date Completed:	17-OCT-89

T78
 North
 1/8-1/4
 1199
 Higher

REACTION TECHNOLOGY INC
3400 BASSET ST
SANTA CLARA, CA 90000

HAZNET S103653986
 N/A

Site 2 of 2 in cluster T

HAZNET:

Gepaid:	CAL000056570
Tepaid:	CAD044429835
Gen County:	Santa Clara
Tsd County:	Los Angeles
Tons:	.0583
Category:	Liquids with pH <UN-> 2
Disposal Method:	Disposal, Other
Contact:	Not reported
Telephone:	(000) 000-0000
Mailing Address:	3400 BASSET ST
	SANTA CLARA, CA 90000
County	Santa Clara
Gepaid:	CAL000187664
Tepaid:	WAD991281767
Gen County:	Santa Clara
Tsd County:	99
Tons:	.4000
Category:	Liquids with pH <UN-> 2
Disposal Method:	Treatment, Tank
Contact:	REACTION TECHNOLOGY INC
Telephone:	(408) 970-9601
Mailing Address:	3400 BASSETT ST
	SANTA CLARA, CA 95054
County	Santa Clara
Gepaid:	CAL000187664
Tepaid:	WAD991281767
Gen County:	Santa Clara
Tsd County:	99
Tons:	.3377
Category:	Liquids with pH <UN-> 2
Disposal Method:	Treatment, Tank
Contact:	REACTION TECHNOLOGY INC
Telephone:	(408) 970-9601
Mailing Address:	3400 BASSETT ST
	SANTA CLARA, CA 95054
County	Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

REACTION TECHNOLOGY INC (Continued)

S103653986

Gepaid: CAL000187664
Tepaid: WAD991281767
Gen County: Santa Clara
Tsd County: 99
Tons: .0792
Category: Laboratory waste chemicals
Disposal Method: Not reported
Contact: REACTION TECHNOLOGY INC
Telephone: (408) 970-9601
Mailing Address: 3400 BASSETT ST
SANTA CLARA, CA 95054
County Santa Clara

Gepaid: CAL000187664
Tepaid: WAD991281767
Gen County: Santa Clara
Tsd County: 99
Tons: .1000
Category: Liquids with pH <UN> 2
Disposal Method: Not reported
Contact: REACTION TECHNOLOGY INC
Telephone: (408) 970-9601
Mailing Address: 3400 BASSETT ST
SANTA CLARA, CA 95054
County Santa Clara

The CA HAZNET database contains 8 additional records for this site.
Please contact your EDR Account Executive for more information.

79
West
1/8-1/4
1236
Higher

FUEL CELL ENGINEERING
1255 SPACE PARK DR
SANTA CLARA, CA 95054

HAZNET S103626862
N/A

HAZNET:
Gepaid: CAL000175119
Tepaid: WAD991281767
Gen County: Santa Clara
Tsd County: 99
Tons: .1459
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: FUEL CELL ENGINEERING
Telephone: (000) 000-0000
Mailing Address: 1255 SPACE PARK DR
SANTA CLARA, CA 95054 - 3425
County Santa Clara
Gepaid: CAL000175119
Tepaid: CAD044429835
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .7500
Category: Other inorganic solid waste
Disposal Method: Disposal, Other
Contact: FUEL CELL ENGINEERING
Telephone: (000) 000-0000
Mailing Address: 1255 SPACE PARK DR

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

FUEL CELL ENGINEERING (Continued)

S103626862

County SANTA CLARA, CA 95054 - 3425
Santa Clara
Gepaid: CAL000175119
Tepaid: CAD044429835
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .7500
Category: Other inorganic solid waste
Disposal Method: Disposal, Other
Contact: FUEL CELL ENGINEERING
Telephone: (000) 000-0000
Mailing Address: 1255 SPACE PARK DR
SANTA CLARA, CA 95054 - 3425
County Santa Clara

80
NNW
1/8-1/4
1237
Higher

DPMS DBA DANCO MACHINE
950 GEORGE ST
SANTA CLARA, CA 95054

HAZNET S100934145
N/A

HAZNET:

Gepaid: CAL000043953
Tepaid: CAT080031628
Gen County: Santa Clara
Tsd County: Kern
Tons: 1.6054
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: DPMS
Telephone: (408) 988-5235
Mailing Address: 950 GEORGE ST
SANTA CLARA, CA 95054 - 2705
County Santa Clara

Gepaid: CAL000043953
Tepaid: CAT080031628
Gen County: Santa Clara
Tsd County: Kern
Tons: .0000
Category:
Disposal Method: Recycler
Contact: DPMS
Telephone: (408) 988-5235
Mailing Address: 950 GEORGE ST
SANTA CLARA, CA 95054 - 2705
County Santa Clara

Gepaid: CAL000043953
Tepaid: CAL000048571
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .6672
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: DPMS
Telephone: (408) 988-5235
Mailing Address: 950 GEORGE ST
SANTA CLARA, CA 95054 - 2705

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

DPMS DBA DANCO MACHINE (Continued)

S100934145

County Santa Clara
Gepaid: CAL000043953
Tepaid: CAT080031628
Gen County: Santa Clara
Tsd County: Kern
Tons: .5129
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: DPMS
Telephone: (408) 988-5235
Mailing Address: 950 GEORGE ST
SANTA CLARA, CA 95054 - 2705
County Santa Clara
Gepaid: CAL000043953
Tepaid: CAT080031628
Gen County: Santa Clara
Tsd County: Kern
Tons: .6588
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: DPMS
Telephone: (408) 988-5235
Mailing Address: 950 GEORGE ST
SANTA CLARA, CA 95054 - 2705
County Santa Clara

The CA HAZNET database contains 10 additional records for this site.
Please contact your EDR Account Executive for more information.

81
NW
1/8-1/4
1269
Higher

GUMBALL CO
1245 LAURELWOOD RD
SANTA CLARA, CA 95054

HAZNET S103966961
N/A

HAZNET:

Gepaid: CAL000179730
Tepaid: CAT080013352
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .2293
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: GUMBALL CO
Telephone: (000) 000-0000
Mailing Address: 1245 LAURELWOOD RD
SANTA CLARA, CA 95054
County Santa Clara
Gepaid: CAL000200365
Tepaid: CAT080033681
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .2293
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: ITT CANNON
Telephone: (408) 496-6181

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

GUMBALL CO (Continued)

S103966961

Mailing Address: 666 EAST DYER RD
 SANTA ANA, CA 92705
 County Santa Clara
 Gepaid: CAL000200365
 Tepaid: CAT080013352
 Gen County: Santa Clara
 Tsd County: Los Angeles
 Tons: .2293
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: ITT CANNON
 Telephone: (408) 496-6181
 Mailing Address: 666 EAST DYER RD
 SANTA ANA, CA 92705
 County Santa Clara

U82
 NE
 1/4-1/2
 1364
 Higher

ROMAN TIRE
800 LAURELWOOD RD
SANTA CLARA, CA 95054

HAZNET S101304263
 LUST N/A
 Cortese

Site 1 of 2 in cluster U

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	Not reported
Case Number	43-0509	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	43099		
Case Type:	Soil only		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Review Date:	Not reported		
Workplan:	Not reported		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	10/16/1995		
Release Date:	1/6/1993		
Cleanup Fund Id :	Not reported		
Discover Date :	1/6/1993		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	4/8/1993		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.		
Priority:	Not reported		
Local Case # :	06S1W26M03		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

ROMAN TIRE (Continued)

S101304263

Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 10/26/1995
Stop Date : 1/6/1993
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500554
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2921.1698204342943022388300565
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0509
Entered Date: 04/08/1993
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 34
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: S-31
Transfer Date: Not reported
Closed Date: 10/16/1995
SCVWD Id: 06S1W26M03f

HAZNET:

Gepaid: CAC000768904
Tepaid: CAT080033681
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .3500
Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Contact: ROMAN TIRE
Telephone: (408) 988-4242
Mailing Address: 800 LAURELWOOD RD
SANTA CLARA, CA 95054
County: Santa Clara

CORTESE:

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

ROMAN TIRE (Continued)

S101304263

Reg Id: 43-0509
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

U83
 NE
 1/4-1/2
 1364
 Higher

**ROMAN TIRES INC
 800 LAURELWOOD RD
 SANTA CLARA, CA**

SWF/LF

S101440907
 N/A

Site 2 of 2 in cluster U

LF:

Facility ID: 43-TI-0395
 Operator: Roman Tires Inc.
 Operator Phone: (408) 988-4242
 Operator Addr: 800 Laurelwood Road
 Santa Clara, CA 95054
 Owner: Manuel & Alicia Roman (Roman Tires Inc.)
 Owner Address: Not reported
 2169 Ashwood Lane

San Jose, CA 95132
 Owner Telephone: (408) 263-1692
 Activity: Tire Dealer
 Operator's Status: Active
 Regulation Status: Permitted
 Region: STATE
 Lat/Long: 37 / -122
 Permit Date: 9/4/98
 Accepted Waste: Tires, Passenger, Tires, Truck
 Permitted Throughput with Units: 4999
 Permitted Throughput with Units: 4999
 Permitted Throughput with Units: 4999
 Actual Throughput with Units: Tires
 Actual Capacity with Units: Not reported
 Permitted Capacity with Units: Not reported
 Remaining Capacity with Units: Tires
 Permitted Total Acreage: 1
 Inspection Frequency: 30 Months
 Landuse Name: Commercial
 GIS Source: Map
 Permit Status: Permitted
 Category: Waste Tire Site
 Unit Number: 01
 Last Waste Tire Inspection Count: Not reported
 Last Waste Tire Inspection Date: 8/28/01
 Original Waste Tire Count: 3000
 Original Waste Tire Count Date: 11/3/97
 Closure Date: / /
 Closure Type: Not reported
 Disposal Acreage: Not reported
 Remaining Capacity: Not reported

84
 NW
 1/4-1/2
 1465
 Higher

**HELLWIG FAMILY LIMITED
 1301 LAURELWOOD ROAD
 SANTA CLARA, CA**

LUST S105193368
 N/A

LUST Region SC:

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

Database(s)

EDR ID Number
EPA ID Number

HELLWIG FAMILY LIMITED (Continued)

S105193368

Region:	Santa Clara	Closed Date:	Not reported
Case Rank:	O3-1	SCVWD Id:	06S1W27J03f
Transfer Date:	Not reported		

**V85
WSW
1/4-1/2
1617
Higher**

**OWENS-CORNING FIBERGLAS CORP
960 CENTRAL EXPRESSWAY
SANTA CLARA, CA 95052**

**Cal-Sites S100941338
N/A**

Site 1 of 2 in cluster V

CAL-SITES:

Facility ID	43320042	
Status:	REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD	
Status Date:	03/14/1995	
Lead:	Not reported	
Region:	2 - BERKELEY	
Branch:	NC - NORTH COAST	
File Name:	Not reported	
Status Name:	PROPERTY/SITE REFERRED TO RWQCB	
Lead Agency:	N/A	Not reported
NPL:	Not reported	
SIC:	32 MANU - STONE, CLAY & GLASS PRODUCTS	
Facility Type:	N/A	
Type Name:	Not reported	
Staff Member Responsible for Site:	Not reported	
Supervisor Responsible for Site:	Not reported	
Region Water Control Board:	SF - SAN FRANCISCO BAY	
Access:	Not reported	
Cortese:	Not reported	
Hazardous Ranking Score:	Not reported	
Date Site Hazard Ranked:	Not reported	
Groundwater Contamination:	Not reported	
No. of Contamination Sources:	0	
Lat/Long:	0° 0' 0.00" / 0° 0' 0.00"	
Lat/long Method:	Not reported	
State Assembly District Code:	Not reported	
State Senate District:	Not reported	

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

**V86
WSW
1/4-1/2
1617
Higher**

**960 CENTRAL EXPRESSWAY
SANTA CLARA, CA 95050**

**CHMIRS S100275012
Cortese N/A**

Site 2 of 2 in cluster V

CORTESE:

Reg Id:	43-2274
Region:	CORTESE
Reg By:	Leaking Underground Storage Tanks
Reg Id:	2 438255N01
Region:	CORTESE
Reg By:	Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

(Continued)

S100275012

CHMIRS:

OES Control Number:	8906907	DOT ID:	1198
DOT Hazard Class:	Flammable liquid		
Chemical Name:	FORMALDEHYDE		
Extent of Release:	Not reported		
CAS Number:	50-00-0	Quantity Released:	4000
Environmental Contamination:	Ground	Property Use:	Manufacturing
Incident Date:	06-JUL-89	Date Completed:	06-JUL-89

W87
 North
 1/4-1/2
 1634
 Higher

PITTSBURGH-DES MOINES
3500 BASSETT AVENUE
SANTA CLARA, CA 95052

Cal-Sites S101482322
 CA SLIC N/A

Site 1 of 2 in cluster W

CAL-SITES:

Facility ID	43340056	
Status:	CERT - CERTIFIED AS HAVING BEEN REMEDIATED SATISFACTORILY UNDER DTSC OVERSIGHT	
Status Date:	01/01/1982	
Lead:	Not reported	
Region:	2 - BERKELEY	
Branch:	NC - NORTH COAST	
File Name:	Not reported	
Status Name:	CERTIFIED	
Lead Agency:	N/A	Not reported
NPL:	Not reported	
SIC:	34 MANU - FABRICATED METAL PRODUCTS	
Facility Type:	N/A	
Type Name:	Not reported	
Staff Member Responsible for Site:	Not reported	
Supervisor Responsible for Site:	Not reported	
Region Water Control Board:	SF - SAN FRANCISCO BAY	
Access:	Controlled	
Cortese:	C	
Hazardous Ranking Score:	Not reported	
Date Site Hazard Ranked:	Not reported	
Groundwater Contamination:	Not reported	
No. of Contamination Sources:	0	
Lat/Long:	0° 0' 0.00" / 0° 0' 0.00"	
Lat/long Method:	Not reported	
State Assembly District Code:	22	
State Senate District:	11	

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

SLIC Region 2:

Facility ID:	43S0774	
Region:	2	
Facility Status:	Closed - No Further Action	Not reported
Staff:	JEB	Not reported
Last Site Update:	03/03/19	
NPL Status:	Not an NPL site	Discovery Date: Not reported
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: No
Abate Method:	Not reported	Substance: Not reported
Case Type:	Not reported	Sample Date: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PITTSBURGH-DES MOINES (Continued)

S101482322

Contamination: Not reported
 Lead: RWQCB
 Contamination Level:
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: 0
 Soil Removal or Contaminant Action Started: 0
 Soil Removal or Contaminant Action Completed: 0
 On-Site Groundwater Extraction or Containment is Needed: 0
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed:
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 0
 Depth of Contamination Plume (Feet): 0
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Not reported
 Completed Characterization : Not reported
 Begun Remediation: Not reported
 Completed Remediation: Not reported
 Submitted Remediation Plan: Not reported
 Approved Remediation Plan: Not reported
 Begun Final Remedial Action: Not reported
 Completed Final Remedial Action: Not reported
 Facility Desc: STEEL WAREHOUSE
 Comment: Not reported

W88
 North
 1/4-1/2
 1634
 Higher

PDM STEEL INC
3500 BASSETT
SANTA CLARA, CA 95052
 Site 2 of 2 in cluster W

HAZNET S104571589
 Cortese N/A

HAZNET:
 Gepaid: CAC002198681
 Tepaid: CAL000161743
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: 1.3761
 Category: Unspecified oil-containing waste
 Disposal Method: Transfer Station
 Contact: PDM STEEL INC
 Telephone: (000) 000-0000
 Mailing Address: 3500 BASSETT
 SANTA CLARA, CA 95052
 County: Santa Clara

CORTESE:
 Reg Id: 43340056
 Region: CORTESE

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

PDM STEEL INC (Continued)

S104571589

Reg By: CALSI

X89
 West
 1/4-1/2
 1722
 Higher

BOURNS INC
1500 SPACE PARK DR
SANTA CLARA, CA 95050

CA SLIC S100942707
N/A

Site 1 of 6 in cluster X

SLIC Region 2:

Facility ID:	43S0491		
Region:	2		
Facility Status:	Active		Not reported
Staff:	VAC		Not reported
Last Site Update:	06/06/19		
NPL Status:	Not reported	Discovery Date:	Not reported
Case List:	SLIC	Imaged:	No
Date Closed:	Not reported	Cost Recovery:	YES
Abate Method:	13	Substance:	Solvents
Case Type:	TK	Sample Date:	Not reported
Contamination:	Not reported		
Lead:	2189.8137 RWQCB		
Contamination Level:			
Number of Municipal Wells Contaminated by Site:	0		
Number of Private Wells Contaminated by Site:	0		
Soil Removal Action Taken/Needed:	0		
Soil Removal or Contaminant Action Started:			
Soil Removal or Contaminant Action Completed:	0		
On-Site Groundwater Extraction or Containment is Needed:	0		
On-Site Groundwater Extraction or Containment Started:			
Off-Site Groundwater Extraction or Containment is Needed:			
Off-Site Groundwater Extraction or Containment Started:			
Length of Contamination Plume (Feet):	0		
Depth of Contamination Plume (Feet):	0		
Wells Closed Due To Contamination of Site:			
Date of Wells Closure:			
Nearest Public or Private Drinking Water Well (Feet):	0		
Under Jurisdiction of Lead Agency Date:			
Latitude/Longitude:	0 / 0		
Flow Rate:	0		
Flow Date:			
Percent of Contaminants Contained:	0		
Contaminant Type:			
EPA ID:			
Stages of Site Investigation Process Initiated:			
Begun Characterization :			Not reported
Completed Characterization :			Not reported
Begun Remediation:			Not reported
Completed Remediation:			Not reported
Submitted Remediation Plan:			Not reported
Approved Remediation Plan:			Not reported
Begun Final Remedial Action:			Not reported
Completed Final Remedial Action:			Not reported
Facility Desc:	Not reported		
Comment:	Not reported		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

X90
 West
 1/4-1/2
 1722
 Higher

PRECISION MONOLITHIC INC
1500 SPACE PARK DR
SANTA CLARA, CA 95050
 Site 2 of 6 in cluster X

LUST S101542343
 CA SLIC N/A

State LUST:

Cross Street: Not reported
 Qty Leaked: 0
 Case Number: 43S0097
 Reg Board: San Francisco Bay Region
 Chemical: Solvents
 Lead Agency: Regional Board
 Local Agency: 43099
 Case Type: Soil only
 Status: Remediation plan developed
 County: Santa Clara
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: 1/30/1994
 Remed Action: Not reported
 Close Date: Not reported
 Release Date: 5/1/1982
 Cleanup Fund Id: Not reported
 Discover Date: Not reported
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: Not reported
 Funding: Not reported
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Not reported
 Leak Cause: Unknown
 Leak Source: Unknown
 MTBE Date: Not reported
 Max MTBE GW: Not reported
 MTBE Tested: Not Required to be Tested.
 Priority: Not reported
 Local Case #: Not reported
 Beneficial: Not reported
 Staff: CTH
 GW Qualifies: Not reported
 Max MTBE Soil: Not reported
 Soil Qualifies: Not reported
 Hydr Basin #: Not reported
 Operator: Not reported
 Oversight Prgm: Local Oversight Program UST
 Oversight Prgm: LOP
 Review Date: Not reported
 Stop Date: Not reported
 Work Suspended: N
 Responsible Party: BLANK RP
 RP Address: Not reported
 Global Id: T0608591609
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 0
 Mtb Fuel: 0

Confirm Leak: Not reported
 Prelim Assess: Not reported
 Remed Plan: 1/30/1994
 Monitoring: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PRECISION MONOLITHIC INC (Continued)

S101542343

Water System Name: Not reported
 Well Name: Not reported
 Distance To Lust: 4719.2476247286391441347868578
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
 Facility Id: 43S0097
 Entered Date: / /
 Facility Status: Remediation plan developed
 Maximum Soil Concentration: 0
 Maximum Groundwater Impact: 0
 County : Santa Clara
 Current Benzene: 0
 MTBE Detected in GW: Not reported
 MTBE Detected in Soil: Not reported
 MTBE: 0
 MTBE Qualify: 0

SLIC Region 2:

Facility ID: 43S0097
 Region: 2
 Facility Status: Active Not reported
 Staff: RAD Not reported
 Last Site Update: 01/30/19
 NPL Status: Not an NPL site
 Discovery Date: 05/01/1982
 Case List: SLIC Imaged: No
 Date Closed: Not reported Cost Recovery: No
 Abate Method: Not reported Substance: Not reported
 Case Type: TK Sample Date: 08/24/1993
 Contamination: UNDRGRND ACID NEUTRALIZATION & WSTE SOLVENT TK LKS
 Lead: RWQCB 2189.8137
 Contamination Level: NT SMPLD;WELL BYND PLM BNDRY
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Yes
 Soil Removal or Contaminant Action Started: 12/27/1984
 Soil Removal or Contaminant Action Completed: 1/15/85
 On-Site Groundwater Extraction or Containment is Needed: Yes
 On-Site Groundwater Extraction or Containment Started: 09/01/1985
 Off-Site Groundwater Extraction or Containment is Needed: Yes
 Off-Site Groundwater Extraction or Containment Started: 12/10/87
 Length of Contamination Plume (Feet): 1200
 Depth of Contamination Plume (Feet): 45
 Wells Closed Due To Contamination of Site: NONE
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 5280
 Under Jurisdiction of Lead Agency Date: 1/24/83
 Latitude/Longitude: 37 / -122
 Flow Rate: 75
 Flow Date: 12/30/1987
 Percent of Contaminants Contained: 3
 Contaminant Type:
 EPA ID: T
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

PRECISION MONOLITHIC INC (Continued)

S101542343

Begun Remediation: Yes
 Completed Remediation: Yes
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: MANUFACTURES INTEGRATED CIRCUITS
 Comment: Not reported

X91
 West
 1/4-1/2
 1722
 Higher

ANALOG DEVICES INC
SPACE PARK DR
SANTA CLARA, CA 95052

Site 3 of 6 in cluster X

Cal-Sites 1000172364
 FINDS 95050PRCSN15
 HAZNET
 Cortese
 RCRIS-LQG
 TRIS
 CERC-NFRAP
 HIST UST

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported Federal Facility: Not a Federal Facility
 Non NPL Code: Status Not Specified
 Ownership Status: Unknown NPL Status: Removed from Proposed NPL
 Site Description: PRECISION MONOLITHIC INC MFGS LINEAR INTEGRATED CIRCUITS AT A PLT IN
 SANTA CLARA,CA.FACIL OCCUPIES 0.4 ACRES & IS SUR- ROUNDED BY
 RESID/INDUS AREAS.MONITORING WELLS ON-SITE CON- TAMINATED WITH
 SOLVENTS FR LEAKING TANKS.88,000 USE GRD WTR.

CERCLIS-NFRAP Assessment History:

Assessment:	DISCOVERY	Completed:	08/01/1980
Assessment:	PRELIMINARY ASSESSMENT	Completed:	07/01/1984
Assessment:	HRS PACKAGE	Completed:	08/01/1984
Assessment:	SITE INSPECTION	Completed:	08/01/1984
Assessment:	PROPOSAL TO NPL	Completed:	10/15/1984
Assessment:	REMOVED FROM THE PROPOSED NPL	Completed:	06/10/1986

CERCLIS-NFRAP Alias Name(s):
 PRECISION MONOLITHIC, INC.

RCRIS:

Owner: ANALOG DEVICES INC
 (617) 329-4700
 EPA ID: CAD069139376
 Contact: ENVIRONMENTAL MANAGER
 Classification: Large Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	4457.21	D002	2366.97
D004	8.00	D009	0.00
F002	520.00	F003	4190.56

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ANALOG DEVICES INC (Continued)

1000172364

Violation Status: No violations found

NY MANIFEST

Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRS Facility System (AIRS/AFS)
- Biennial Reporting System (BRS)
- Facility Registry System (FRS)
- National Emissions Trends (NET)
- National Toxics Inventory (NTI)
- Resource Conservation and Recovery Act Information system (RCRAINFO)
- Toxic Chemical Release Inventory System (TRIS)

CAL-SITES:

Facility ID 43380015
Status: REFRW - DOES NOT REQUIRE DTSC ID ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 08/09/1991
Lead: Not reported
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: Not reported
Status Name: PROPERTY/SITE REFERRED TO RWQCB
Lead Agency: N/A Not reported
NPL: Not reported
SIC: 38 MANU - INSTRUMENTS & RELATED PRODUCTS
Facility Type: N/A
Type Name: Not reported
Staff Member Responsible for Site: Not reported
Supervisor Responsible for Site: Not reported
Region Water Control Board: Not reported
Access: Not reported
Cortese: Not reported
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Not reported
No. of Contamination Sources: 0
Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
Lat/long Method: Not reported
State Assembly District Code: 22
State Senate District: 13

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

HAZNET:

Gepaid: CAD069139376
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: .1500
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: ANALOG DEVICES INC
Telephone: (714) 781-5008
Mailing Address: PO BOX 58020
SANTA CLARA, CA 95052 - 8020

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

ANALOG DEVICES INC (Continued)

1000172364

County Santa Clara
Gepaid: CAD069139376
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: 45.5112
Category: Other inorganic solid waste
Disposal Method: Disposal, Land Fill
Contact: ANALOG DEVICES INC
Telephone: (714) 781-5008
Mailing Address: PO BOX 58020
SANTA CLARA, CA 95052 - 8020

County Santa Clara
Gepaid: CAD069139376
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: 3.5000
Category: Other organic solids
Disposal Method: Disposal, Land Fill
Contact: ANALOG DEVICES INC
Telephone: (714) 781-5008
Mailing Address: PO BOX 58020
SANTA CLARA, CA 95052 - 8020

County Santa Clara
Gepaid: CAD069139376
Tepaid: CAD003963592
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .5000
Category: Other inorganic solid waste
Disposal Method: Recycler
Contact: ANALOG DEVICES INC
Telephone: (714) 781-5008
Mailing Address: PO BOX 58020
SANTA CLARA, CA 95052 - 8020

County Santa Clara
Gepaid: CAD069139376
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1775
Category:
Disposal Method: Transfer Station
Contact: ANALOG DEVICES INC
Telephone: (714) 781-5008
Mailing Address: PO BOX 58020
SANTA CLARA, CA 95052 - 8020

County Santa Clara

The CA HAZNET database contains 177 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:
Reg Id: 2 438137N02
Region: CORTESE

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ANALOG DEVICES INC (Continued)

1000172364

Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

UST HIST:

Facility ID: 14494
Tank Num: 1 Container Num: 1
Tank Capacity: 4200 Year Installed: 1975
Tank Used for: WASTE
Type of Fuel: Not Reported Tank Construction: Not reported
Leak Detection: Visual, GW Monitoring Well
Contact Name: DAVID SWAIN-V.P. OPERATIONS Telephone: (408) 727-9222
Total Tanks: 4 Region: STATE
Facility Type: 2 Other Type: INTEGRATED CIRCUITS

Facility ID: 14494
Tank Num: 2 Container Num: 2
Tank Capacity: 1200 Year Installed: 1969
Tank Used for: WASTE
Type of Fuel: Not Reported Tank Construction: Not reported
Leak Detection: GW Monitoring Well
Contact Name: DAVID SWAIN-V.P. OPERATIONS Telephone: (408) 727-9222
Total Tanks: 4 Region: STATE
Facility Type: 2 Other Type: INTEGRATED CIRCUITS

Facility ID: 14494
Tank Num: 3 Container Num: 3
Tank Capacity: 800 Year Installed: 1975
Tank Used for: WASTE
Type of Fuel: Not Reported Tank Construction: Not reported
Leak Detection: GW Monitoring Well
Contact Name: DAVID SWAIN-V.P. OPERATIONS Telephone: (408) 727-9222
Total Tanks: 4 Region: STATE
Facility Type: 2 Other Type: INTEGRATED CIRCUITS

Facility ID: 14494
Tank Num: 4 Container Num: 4
Tank Capacity: 1000 Year Installed: 1978
Tank Used for: WASTE
Type of Fuel: Not Reported Tank Construction: 10 gauge
Leak Detection: GW Monitoring Well
Contact Name: DAVID SWAIN-V.P. OPERATIONS Telephone: (408) 727-9222
Total Tanks: 4 Region: STATE
Facility Type: 2 Other Type: INTEGRATED CIRCUITS

X92
West
1/4-1/2
1722
Higher

1500 SPACE PARK DR.
SANTA CLARA, CA 95054

Site 4 of 6 in cluster X

CHMIRS S100280805
N/A

CHMIRS:

OES Control Number: 9991165 DOT ID: Not reported
DOT Hazard Class: Corrosives
Chemical Name: BURMAR NOPHENOL 922
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: 5
Environmental Contamination: None Reported Property Use: Manufacturing
Incident Date: 11-JUL-88 Date Completed: 11-JUL-88

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
X93	West	1/4-1/2	1722	Higher	1500 SPACE PARK DRIVE SANTA CLARA, CA 95052 Site 5 of 6 in cluster X	CHMIRS	S102519425	N/A
X94	West	1/4-1/2	1722	Higher	1500 SPACE PARK DRIVE SANTA CLARA, CA 95025 Site 6 of 6 in cluster X	CHMIRS	S100275375	N/A
CHMIRS: OES Control Number: 8910164 DOT ID: Not reported DOT Hazard Class: Not Reported Chemical Name: HYDROGEN CHLORIDE Extent of Release: Not reported CAS Number: Not reported Quantity Released: Not reported Environmental Contamination: Air Property Use: Manufacturing Incident Date: 27-FEB-89 Date Completed: 27-FEB-89								
95	NE	1/4-1/2	1793	Higher	3180 MOLINARD SANTA CLARA, CA 95054	CHMIRS	S100275186	N/A
CHMIRS: OES Control Number: 8908763 DOT ID: Not reported DOT Hazard Class: Not Reported Chemical Name: ALCOHOL, ISOPROPYL Extent of Release: Not reported CAS Number: Not reported Quantity Released: 55 Environmental Contamination: Ground Property Use: Manufacturing Incident Date: 07-NOV-89 Date Completed: 07-NOV-89								
96	NNE	1/4-1/2	2152	Higher	TORQUE & TENSION EQUIPMENT INC 625 NUTTMAN SANTA CLARA, CA 95054	HAZNET CA SLIC	S101542567	N/A
HAZNET: Gepaid: CAL000041554 Tepaid: CAL000027741 Gen County: Santa Clara Tsd County: 5 Tons: .8428 Category: Asbestos-containing waste Disposal Method: Disposal, Land Fill Contact: VOSSBRINCK DAVID Telephone: (000) 000-0000 Mailing Address: 625 NUTTMAN ST SANTA CLARA, CA 95054 County: Santa Clara SLIC Region 2: Facility ID: 43S0375								

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TORQUE & TENSION EQUIPMENT INC (Continued)

S101542567

Region: 2
 Facility Status: Inactive Not reported
 Staff: Not reported Not reported
 Last Site Update: 11/21/19
 NPL Status: Not an NPL site Discovery Date: 10/24/1991
 Case List: SLIC Imaged: No
 Date Closed: Not reported Cost Recovery: No
 Abate Method: 13 Substance: Solvents
 Case Type: NT Sample Date: Not reported
 Contamination: NO SAMPLING DONE OF SOIL OR GW.
 Lead: RWQCB
 Contamination Level: 0
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Not Determined
 Soil Removal or Contaminant Action Started:
 Soil Removal or Contaminant Action Completed:
 On-Site Groundwater Extraction or Containment is Needed: Not Determined
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed: Not Determined
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 0
 Depth of Contamination Plume (Feet): 0
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date: 10/24/91
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : No
 Completed Characterization : No
 Begun Remediation: No
 Completed Remediation: No
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: CONTROLLED BOLT TIGHTENING
 Comment: Not reported

Y97
 North
 1/4-1/2
 2222
 Higher

ROTTEN ROBBIE #33
3471 LAFAYETTE STREET
SANTA CLARA, CA 95050

Site 1 of 4 in cluster Y

HAZNET U001601811
LUST N/A
Cortese
UST
HIST UST

LUST Region SC:

Region: Santa Clara
 Case Rank: O433
 Transfer Date: Not reported

Closed Date: Not reported
 SCVWD Id: 06S1W27H01f

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ROTTEN ROBBIE #33 (Continued)

U001601811

HAZNET:

Gepaid: CAL000048162
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: 1.3761
Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method: Recycler
Contact: MISSION TRAIL OIL CO
Telephone: (000) 000-0000
Mailing Address: 4250 WILLIAMS RD
SAN JOSE, CA 95129
County: Santa Clara

Gepaid: CAL000048162
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: 1.2927
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: MISSION TRAIL OIL CO
Telephone: (000) 000-0000
Mailing Address: 4250 WILLIAMS RD
SAN JOSE, CA 95129
County: Santa Clara

Gepaid: CAC002297409
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .6880
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: MISSION TAIL OIL COMPANY
Telephone: (408) 257-2222
Mailing Address: 4250 WILLIAMS ROAD
SAN JOSE, CA 95129
County: Santa Clara

Gepaid: CAC002297409
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: 8.4280
Category: Other inorganic solid waste
Disposal Method: Disposal, Land Fill
Contact: MISSION TAIL OIL COMPANY
Telephone: (408) 257-2222
Mailing Address: 4250 WILLIAMS ROAD
SAN JOSE, CA 95129
County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ROTTEN ROBBIE #33 (Continued)

U001601811

Gepaid: CAC002297409
Tepaid: CAD028409019
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .3336
Category: Oil/water separation sludge
Disposal Method: Transfer Station
Contact: MISSION TAIL OIL COMPANY
Telephone: (408) 257-2222
Mailing Address: 4250 WILLIAMS ROAD
SAN JOSE, CA 95129
County: Santa Clara

The CA HAZNET database contains 5 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 43-1141
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

UST HIST:

Facility ID: 31248
Tank Num: 1
Tank Capacity: 12000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Leak Detection: Stock Inventor
Contact Name: TOM ROBINSON
Total Tanks: 6
Facility Type: 1
Container Num: 33-01
Year Installed: 1979
Tank Construction: 1/4 inches
Telephone: (408) 252-7720
Region: STATE
Other Type: Not reported

Facility ID: 31248
Tank Num: 2
Tank Capacity: 8000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Leak Detection: Stock Inventor
Contact Name: TOM ROBINSON
Total Tanks: 6
Facility Type: 1
Container Num: 33-02A
Year Installed: 1963
Tank Construction: 1/4 inches
Telephone: (408) 252-7720
Region: STATE
Other Type: Not reported

Facility ID: 31248
Tank Num: 3
Tank Capacity: 6000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Leak Detection: Stock Inventor
Contact Name: TOM ROBINSON
Total Tanks: 6
Facility Type: 1
Container Num: 33-02B
Year Installed: 1963
Tank Construction: 1/4 inches
Telephone: (408) 252-7720
Region: STATE
Other Type: Not reported

Facility ID: 31248
Tank Num: 4
Tank Capacity: 10000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Leak Detection: Stock Inventor
Container Num: 33-03
Year Installed: 1973
Tank Construction: 1/4 inches

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s)
 EDR ID Number
 EPA ID Number

ROTTEN ROBBIE #33 (Continued)

U001601811

Contact Name: TOM ROBINSON	Telephone: (408) 252-7720
Total Tanks: 6	Region: STATE
Facility Type: 1	Other Type: Not reported

Facility ID: 31248	Container Num: 33-05A
Tank Num: 5	Year Installed: 1973
Tank Capacity: 10000	
Tank Used for: PRODUCT	
Type of Fuel: DIESEL	Tank Construction: 1/4 inches

Leak Detection: Stock Inventor	Telephone: (408) 252-7720
Contact Name: TOM ROBINSON	Region: STATE
Total Tanks: 6	Other Type: Not reported
Facility Type: 1	

Facility ID: 31248	Container Num: 33-05B
Tank Num: 6	Year Installed: 1973
Tank Capacity: 10000	
Tank Used for: PRODUCT	
Type of Fuel: DIESEL	Tank Construction: 1/4 inches
Leak Detection: Stock Inventor	
Contact Name: TOM ROBINSON	Telephone: (408) 252-7720
Total Tanks: 6	Region: STATE
Facility Type: 1	Other Type: Not reported

State UST:
 Facility ID: 300366
 Total Tanks: 1
 Region: STATE
 Local Agency: Santa Clara, Santa Clara County

Y98
 North
 1/4-1/2
 2222
 Higher

ROTTEN ROBBIE #33
 3471 LAFAYETTE ST.
 SANTA CLARA, CA 95050

LUST S101625272
 CA FID UST N/A

Site 2 of 4 in cluster Y

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1141
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Remedial action (cleanup) in progress
 County: Santa Clara
 Abate Method: Remove Free Product - remove floating product from water table, Pump and Treat Ground Water - generally employed to remove dissolved contaminants

Review Date: Not reported	Confirm Leak: Not reported
Workplan: 11/20/1984	Prelim Assess: 11/20/1984
Pollution Char: 2/1/1989	Remed Plan: 2/1/1989
Remed Action: Not reported	Monitoring: Not reported
Close Date: Not reported	
Release Date: 5/9/1985	
Cleanup Fund Id: Not reported	
Discover Date: 11/14/1989	
Enforcement Dt: Not reported	

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ROTTEN ROBBIE #33 (Continued)

S101625272

Enf Type: Not reported
Enter Date : 5/19/1985
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : 1/2/1965
Max MTBE GW : 1600
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case # : 06S1W27H01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 11/25/1997
Stop Date : 11/14/1989
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608501131
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 1707.9603477554667607995428586
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1141
Entered Date: 05/19/1985
Facility Status: Remedial action (cleanup) in progress
Maximum Soil Concentration: 1
Maximum Groundwater Impact: 9999999
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 1600
MTBE Detected in Soil: Not reported
MTBE: 690
MTBE Qualify: Not reported

Y99 ROUSE & ASSOCIATES
North 3491 LAFAYETTE ST
1/4-1/2 SANTA CLARA, CA 95054
2282
Same Site 3 of 4 in cluster Y

LUST S101304261
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

ROUSE & ASSOCIATES (Continued)

S101304261

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-1149
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: No Action Taken - no action has as yet been taken at the site
Review Date: Not reported
Workplan: 1/30/1987
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 4/13/2000
Release Date: 8/12/1986
Cleanup Fund Id: Not reported
Discover Date: 8/18/1986
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 8/22/1986
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: 06S1W27H02
Beneficial: Not reported
Staff: CTH
GW Qualifies: Not reported
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 4/28/2000
Stop Date: 8/18/1986
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501139
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 1677.9911147896518512295633044

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ROUSE & ASSOCIATES (Continued)

S101304261

Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1149
Entered Date: 08/22/1986
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 1100
Maximum Groundwater Impact: 38000
County: Santa Clara
Current Benzene: 310
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O331
Transfer Date: Not reported
Closed Date: 04/13/2000
SCVWD Id: 06S1W27H02f

Y100
North
1/4-1/2
2282
Same

ROBBIE TERMINAL # 87
3491 LAFAYETTE
SANTA CLARA, CA 95050

HAZNET S103984841
Cortese N/A

Site 4 of 4 in cluster Y

HAZNET:

Gepaid: CAC001483200
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .0834
Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Contact: MISSION TRAIL OIL COMPANY
Telephone: (408) 252-7720
Mailing Address: 4250 WILLIAMS ROAD
SAN JOSE, CA 95129
County: Santa Clara

CORTESE:

Reg Id: 43-1149
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

101
East
1/4-1/2
2303
Higher

DIASONICS VINGMED ULTRASOUND
2860 DE LA CRUZ BLVD
SANTA CLARA, CA 95050

HAZNET S103649606
Cortese N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number

DIASONICS VINGMED ULTRASOUND (Continued)

S103649606

HAZNET:

Gepaid: CA0001009935
Tepaid: CAT080022148
Gen County: Santa Clara
Tsd County: San Bernardino
Tons: .2950
Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
Disposal Method: Transfer Station
Contact: GENERAL ELECTRIC ULTRASOUND
Telephone: (408) 922-1098
Mailing Address: 2155 MONTEREY HWY
SAN JOSE, CA 95112
County Santa Clara

Gepaid: CA0001009935
Tepaid: CAT080022148
Gen County: Santa Clara
Tsd County: San Bernardino
Tons: .2000
Category: Liquids with pH <UN> 2 with metals
Disposal Method: Transfer Station
Contact: GENERAL ELECTRIC ULTRASOUND
Telephone: (408) 922-1098
Mailing Address: 2155 MONTEREY HWY
SAN JOSE, CA 95112
County Santa Clara

Gepaid: CA0001009935
Tepaid: CAT080022148
Gen County: Santa Clara
Tsd County: San Bernardino
Tons: .4375
Category: Liquids with lead > 500 mg/l
Disposal Method: Transfer Station
Contact: GENERAL ELECTRIC ULTRASOUND
Telephone: (408) 922-1098
Mailing Address: 2155 MONTEREY HWY
SAN JOSE, CA 95112
County Santa Clara

Gepaid: CA0001009935
Tepaid: CAD003963592
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .2502
Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Contact: GENERAL ELECTRIC ULTRASOUND
Telephone: (408) 922-1098
Mailing Address: 2155 MONTEREY HWY
SAN JOSE, CA 95112
County Santa Clara

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

DIASONICS VINGMED ULTRASOUND (Continued)

S103649606

Gepaid: CA0001009935
Tepaid: WAD991281767
Gen County: Santa Clara
Tsd County: 99
Tons: .6672
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Treatment, Incineration
Contact: GENERAL ELECTRIC ULTRASOUND
Telephone: (408) 922-1098
Mailing Address: 2155 MONTEREY HWY
SAN JOSE, CA 95112
County: Santa Clara

The CA HAZNET database contains 19 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2496
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Z102
NE
1/4-1/2
2420
Higher

STEC TECH INC
605 LAURELWOOD RD
SANTA CLARA, CA 95054

RCRIS-SQG 1000165905
FINDS CAD981165228
LUST

Site 1 of 5 in cluster Z

RCRIS:

Owner: PHILLIP J STECKEL
(415) 555-1212
EPA ID: CAD981165228
Contact: ENVIRONMENTAL MANAGER
(408) 988-7777

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility Registry System (FRS)
- Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0979
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: Not reported Confirm Leak: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

STEC TECH INC (Continued)

1000165905

Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 11/13/1997
Release Date: 6/6/1985
Cleanup Fund Id : Not reported
Discover Date : 6/6/1985
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 5/14/1991
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case # : 06S1W26M01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 11/21/1997
Stop Date : 6/6/1985
Work Suspended N
Responsible Party BLANK RP
RP Address: Not reported
Global Id: T0608500978
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2722.5437301111321860802585701
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0979
Entered Date: 05/14/1991
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 450
Maximum Groundwater Impact: 8400
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

STEC TECH INC (Continued)

1000165905

MTBE: 0
 MTBE Qualify: Not reported
 LUST Region SC:
 Region: Santa Clara
 Case Rank: S-31
 Transfer Date: Not reported
 Closed Date: 11/13/1997
 SCVWD Id: 06S1W26M01f

Z103
 NE
 1/4-1/2
 2420
 Higher

AIR BORNE EXPRESS
 605 LAURELWOOD
 SANTA CLARA, CA 95054

HAZNET S103666564
 Cortese N/A

Site 2 of 5 in cluster Z

HAZNET:

Gepaid: CAL000173688
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .1251
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: WORK FORCE
 Telephone: (000) 000-0000
 Mailing Address: PO BOX 1527
 SANTA CRUZ, CA 95061 - 1527
 County: Santa Clara

Gepaid: CAL000173688
 Tepaid: CAD088838222
 Gen County: Santa Clara
 Tsd County: Santa Cruz
 Tons: .2293
 Category: Aqueous solution with 10% or more total organic residues
 Disposal Method: Recycler
 Contact: WORK FORCE
 Telephone: (000) 000-0000
 Mailing Address: PO BOX 1527
 SANTA CRUZ, CA 95061 - 1527
 County: Santa Clara

Gepaid: CAL000173688
 Tepaid: CAL000161743
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: 0.417
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Not reported
 Contact: WORK FORCE
 Telephone: (000) 000-0000
 Mailing Address: PO BOX 1527
 SANTA CRUZ, CA 95061 - 1527
 County: Santa Clara

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AIR BORNE EXPRESS (Continued)

S103666564

Gepaid: CAL000173688
 Tepaid: CAL000161743
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: 0.417
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Transfer Station
 Contact: WORK FORCE
 Telephone: (000) 000-0000
 Mailing Address: PO BOX 1527
 SANTA CRUZ, CA 95061 - 1527
 County: Santa Clara

CORTESE:
 Reg Id: 43-0979
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

AA104
 West
 1/4-1/2
 2490
 Higher

3100 ALFRED
 SANTA CLARA, CA 95054

CHMIRS S100216643
 N/A

Site 1 of 3 in cluster AA

CHMIRS:
 OES Control Number: 8804322 DOT ID: 1050
 DOT Hazard Class: Gases
 Chemical Name: ACID, HYDROCHLORIC
 Extent of Release: Not reported
 CAS Number: 7647-01-0 Quantity Released: Not reported
 Environmental Contamination: None Reported Property Use: Manufacturing
 Incident Date: 19-DEC-88 Date Completed: 19-DEC-88

AA105
 West
 1/4-1/2
 2490
 Higher

FAIRCHILD MICROPOWER
 3100 ALFRED ST
 SANTA CLARA, CA 95050

CA SLIC S103393941
 N/A

Site 2 of 3 in cluster AA

SLIC Region 2:
 Facility ID: 43S0492
 Region: 2
 Facility Status: Active Not reported
 Staff: VAC Not reported
 Last Site Update: 06/06/19
 NPL Status: Not reported Discovery Date: Not reported
 Case List: SLIC Imaged: No
 Date Closed: Not reported Cost Recovery: No
 Abate Method: 13 Substance: Solvents
 Case Type: NT Sample Date: Not reported
 Contamination: Not reported
 Lead: 2189.8191 RWQCB
 Contamination Level:
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: 0
 Soil Removal or Contaminant Action Started:

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

FAIRCHILD MICROPOWER (Continued)

S103393941

Soil Removal or Contaminant Action Completed: 0
 On-Site Groundwater Extraction or Containment is Needed: 0
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed:
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 0
 Depth of Contamination Plume (Feet): 0
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 0 / 0
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Not reported
 Completed Characterization : Not reported
 Begun Remediation: Not reported
 Completed Remediation: Not reported
 Submitted Remediation Plan: Not reported
 Approved Remediation Plan: Not reported
 Begun Final Remedial Action: Not reported
 Completed Final Remedial Action: Not reported
 Facility Desc: Not reported
 Comment: Not reported

AA106
 West
 1/4-1/2
 2492
 Higher

3105 ALFRED ST.
 SANTA CLARA, CA 95050

Site 3 of 3 in cluster AA

CHMIRS S100274846
 N/A

CHMIRS:
 OES Control Number: 8905286 DOT ID: 2203
 DOT Hazard Class: Gases
 Chemical Name: SILANE
 Extent of Release: Not reported
 CAS Number: 7803-62-5 Quantity Released: 1
 Environmental Contamination: None Reported Property Use: Manufacturing
 Incident Date: 16-MAR-89 Date Completed: 16-MAR-89

Z107
 NE
 1/4-1/2
 2514
 Higher

EA HATHAWAY & COMPANY
 565 LAURELWOOD RD
 SANTA CLARA, CA 95050

Site 3 of 5 in cluster Z

Cortese S101304266
 N/A

CORTESE:
 Reg Id: 43-0681
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

Z108
NE
1/4-1/2
2514
Higher

E.A. HATHAWAY & CO.
565 LAURELWOOD RD
SANTA CLARA, CA

LUST **S103880727**
 N/A

Site 4 of 5 in cluster Z

LUST Region SC:

Region: Santa Clara
 Case Rank: O331
 Transfer Date: Not reported

Closed Date: 10/15/1997
 SCVWD Id: 06S1W26L01f

Z109
NE
1/4-1/2
2514
Higher

EA HATHAWAY & COMPANY
565 LAURELWOOD RD
SANTA CLARA, CA 95054

LUST **S103473150**
 N/A

Site 5 of 5 in cluster Z

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number 43-0681
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming), Pump and Treat Ground Water - generally employed to remove dissolved contaminants

Review Date:	Not reported	Confirm Leak:	Not reported
Workplan:	7/2/1990	Prelim Assess:	7/2/1990
Pollution Char:	12/12/1990	Remed Plan:	12/12/1990
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	10/15/1997		
Release Date:	11/20/1989		
Cleanup Fund Id :	Not reported		
Discover Date :	12/11/1989		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	1/22/1990		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	1/2/1965		
Max MTBE GW :	17		
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected		
Priority:	Not reported		
Local Case # :	06S1W26L01		
Beneficial:	Not reported		
Staff :	CTH		
GW Qualifies :	Not reported		
Max MTBE Soil :	Not reported		
Soil Qualifies :	Not reported		
Hydr Basin #:	Not reported		
Operator :	Not reported		
Oversight Prgm:	Local Oversight Program UST		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

EA HATHAWAY & COMPANY (Continued)

S103473150

Oversight Prgm : LOP
 Review Date : 11/21/1997
 Stop Date : 12/11/1989
 Work Suspended : N
 Responsible Party: BLANK RP
 RP Address: Not reported
 Global Id: T0608500712
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 1
 Mibe Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To LUST: 2733.2909651338285289177654635
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
 Facility Id: 43-0681
 Entered Date: 01/22/1990
 Facility Status: Signed off, remedial action completed or deemed unnecessary
 Maximum Soil Concentration: 2900
 Maximum Groundwater Impact: 59000
 County : Santa Clara
 Current Benzene: 1
 MTBE Detected in GW: 17
 MTBE Detected in Soil: Not reported
 MTBE: 17
 MTBE Qualify: Not reported

**AB110
 West
 1/4-1/2
 2531
 Higher**

**FAIRCHILD MICRO POWER
 3080/3100 ALFRED ST
 SANTA CLARA, CA 95050**

**CA SLIC S101542288
 N/A**

Site 1 of 3 in cluster AB

SLIC Region 2:

Facility ID: 43S0152
 Region: 2
 Facility Status: Active Not reported
 Staff: RAD Not reported
 Last Site Update: 01/30/19
 NPL Status: Not an NPL site
 Case List: SLIC
 Date Closed: Not reported
 Abate Method: Not reported
 Case Type: ND
 Contamination: SUSPECTED SOLVENT RELEASES FROM UNDERGROUND SUMPS
 Lead: 2189.8191 RWQCB
 Contamination Level: INACTIVE, NOT SAMPLED
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: No
 Soil Removal or Contaminant Action Started:
 Soil Removal or Contaminant Action Completed:
 On-Site Groundwater Extraction or Containment is Needed: Yes
 On-Site Groundwater Extraction or Containment Started: 02/25/1988
 Off-Site Groundwater Extraction or Containment is Needed: Yes

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

FAIRCHILD MICRO POWER (Continued)

S101542288

Off-Site Groundwater Extraction or Containment Started: 2/25/88
 Length of Contamination Plume (Feet): 600
 Depth of Contamination Plume (Feet): 30
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 500
 Under Jurisdiction of Lead Agency Date: 3/30/82
 Latitude/Longitude: 37 / -122
 Flow Rate: 40
 Flow Date: 06/01/1988
 Percent of Contaminants Contained: 2
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes
 Begun Remediation: Yes
 Completed Remediation: Yes
 Submitted Remediation Plan: Yes
 Approved Remediation Plan: Yes
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: ELECTRONIC INDUSTRY, MICROPOWER SYSTEMS
 Comment: Not reported

AB111
 West
 1/4-1/2
 2531
 Higher

SCR-FAIRCHILD/MICROPOWER
3100/3080 ALFRED ST
SANTA CLARA, CA 95054
Site 2 of 3 in cluster AB

Cortese S103618003
CA WDS N/A

CORTESE:

Reg Id: 2 438191N01
 Region: CORTESE
 Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

WDS:

Facility ID: San Francisco Bay 438191002
 Facility Contact: DENNIS CURRAN
 SIC Code: Not reported
 Agency Name: EXAR CORP
 Agency Address: 2222 QUME DR
 SAN JOSE 95161
 Agency Contact: XOCHILL MONLEON
 Design Flow: 0 Million Gal/Day
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
 Agency Type: Private
 Waste Type: Contaminated Ground Water - Hazardous/Influent or Solid Wastes that contain toxic, corrosive, ignitable or reactive substances and must be managed according to applicable DOHS standards.
 Threat to Water: N
 Complexity: Category B - Any facility having a physical, chemical, or biological waste treatment system (except for septic systems with subsurface disposal), or any Class II or III

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SCR-FAIRCHILD/MICROPOWER (Continued)

S103618003

disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum products, solid wastes, and sewage pump out facilities.

Reclamation: No reclamation requirements associated with this facility.
 POTW: VAC
 NPDES Number: CAG912003 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board

Subregion: 2
 Frequency of Reporting to Regional Board: Quarterly Submittal
 Resource Conservation and Recovery Act (RCRA) Facility: No
 Project Official's Initials: 2

**AB112
 West
 1/4-1/2
 2531
 Higher**

**FAIRCHILD/MICROPOWER
 3080/3100 ALFRED STREET
 SANTA CLARA, CA 95054**

**Cal-Sites S101482369
 N/A**

Site 3 of 3 in cluster AB

CAL-SITES:

Facility ID: 43360125
 Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD

Status Date: 02/26/1993
 Lead: Not reported
 Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 36 MANU - ELECTRONIC & OTHER ELECTRIC EQUIP

Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: Not reported
 Access: Controlled
 Cortese: C
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Confirmed
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

**113
 NW
 1/4-1/2
 2564
 Higher**

**SANTA CLARA TECHNOLOGY PARK
 3301-3501 LEONARD CT
 SANTA CLARA, CA 95050**

**CA SLIC S103454501
 N/A**

SLIC Region 2:

Facility ID: 43S0729
 Region: 2

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s)
 EDR ID Number
 EPA ID Number

SANTA CLARA TECHNOLOGY PARK (Continued)

S103454501

Facility Status:	Closed - No Further Action	Not reported
Staff:	Not reported	Not reported
Last Site Update:	07/24/19	
NPL Status:	Not an NPL site	Discovery Date: Not reported
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: No
Abate Method:	Not reported	Substance: Not reported
Case Type:	NT	Sample Date: 05/04/1988
Contamination:	HAZARDOUS CHEMICALS	
Lead:	RWQCB	
Contamination Level:		
Number of Municipal Wells Contaminated by Site:	0	
Number of Private Wells Contaminated by Site:	3	
Soil Removal Action Taken/Needed:	0	
Soil Removal or Contaminant Action Started:		
Soil Removal or Contaminant Action Completed:	0	
On-Site Groundwater Extraction or Containment is Needed:	0	
On-Site Groundwater Extraction or Containment Started:		
Off-Site Groundwater Extraction or Containment is Needed:		
Off-Site Groundwater Extraction or Containment Started:		
Length of Contamination Plume (Feet):	0	
Depth of Contamination Plume (Feet):	0	
Wells Closed Due To Contamination of Site:		
Date of Wells Closure:		
Nearest Public or Private Drinking Water Well (Feet):	0	
Under Jurisdiction of Lead Agency Date:		
Latitude/Longitude:	0 / 0	
Flow Rate:	0	
Flow Date:		
Percent of Contaminants Contained:	0	
Contaminant Type:		
EPA ID:		
Stages of Site Investigation Process Initiated:		
Began Characterization :		Not reported
Completed Characterization :		Not reported
Began Remediation:		Not reported
Completed Remediation:		Not reported
Submitted Remediation Plan:		Not reported
Approved Remediation Plan:		Not reported
Began Final Remedial Action:		Not reported
Completed Final Remedial Action:		Not reported
Facility Desc:	INDUSTRIAL AREA	
Comment:	Not reported	

AC114
 NNE
 1/4-1/2
 2567
 Higher

WILLIG FREIGHT LINES
751 NUTTMAN ST
SANTA CLARA, CA 95050

LUST U001601844
HIST UST N/A

Site 1 of 3 in cluster AC

LUST Region SC:

Region: Santa Clara
 Case Rank: O432
 Transfer Date: Not reported

Closed Date: 04/12/2001
 SCVWD Id: 06S1W26E04f

UST HIST:

Facility ID: 13431
 Tank Num: 1
 Tank Capacity: 1000

Container Num: #1
 Year Installed: 1974

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WILLIG FREIGHT LINES (Continued)

U001601844

Tank Used for:	PRODUCT	Tank Construction:	10 gauge
Type of Fuel:	Not Reported	Telephone:	(408) 988-4363
Leak Detection:	Stock Inventor	Region:	STATE
Contact Name:	J. NUUHIWA	Other Type:	TRUCKING
Total Tanks:	5		
Facility Type:	2		
Facility ID:	13431	Container Num:	#2
Tank Num:	2	Year Installed:	1974
Tank Capacity:	10000	Tank Construction:	1/4 inches
Tank Used for:	PRODUCT	Telephone:	(408) 988-4363
Type of Fuel:	REGULAR	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	TRUCKING
Contact Name:	J. NUUHIWA		
Total Tanks:	5	Container Num:	#3
Facility Type:	2	Year Installed:	1974
Facility ID:	13431	Tank Construction:	1/4 inches
Tank Num:	3	Telephone:	(408) 988-4363
Tank Capacity:	10000	Region:	STATE
Tank Used for:	PRODUCT	Other Type:	TRUCKING
Type of Fuel:	DIESEL		
Leak Detection:	Stock Inventor	Container Num:	#4
Contact Name:	J. NUUHIWA	Year Installed:	1974
Total Tanks:	5	Tank Construction:	1/4 inches
Facility Type:	2	Telephone:	(408) 988-4363
Facility ID:	13431	Region:	STATE
Tank Num:	4	Other Type:	TRUCKING
Tank Capacity:	10000		
Tank Used for:	PRODUCT	Container Num:	#5
Type of Fuel:	DIESEL	Year Installed:	1974
Leak Detection:	Stock Inventor	Tank Construction:	10 gauge
Contact Name:	J. NUUHIWA	Telephone:	(408) 988-4363
Total Tanks:	5	Region:	STATE
Facility Type:	2	Other Type:	TRUCKING
Facility ID:	13431		
Tank Num:	5	Container Num:	#5
Tank Capacity:	1000	Year Installed:	1974
Tank Used for:	WASTE	Tank Construction:	10 gauge
Type of Fuel:	WASTE OIL	Telephone:	(408) 988-4363
Leak Detection:	None	Region:	STATE
Contact Name:	J. NUUHIWA	Other Type:	TRUCKING
Total Tanks:	5		
Facility Type:	2		

AC115 WILLIG FREIGHT LINES
NNE 751 NUTTMAN STREET
1/4-1/2 SANTA CLARA, CA 95050
2567
Higher Site 2 of 3 in cluster AC

HAZNET S105033479
Cortese N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

WILLIG FREIGHT LINES (Continued)

S105033479

HAZNET:

Gepaid: CAL920796364
 Tepaid: CAD000628149
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: .1251
 Category: Other organic solids
 Disposal Method: Transfer Station
 Contact: WILLIG FREIGHT LINES
 Telephone: (415) 824-5309
 Mailing Address: 751 NUTTMAN STREET
 SANTA CLARA, CA 95050
 County: Santa Clara

CORTESE:

Reg Id: 43-0602
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AC116
 NNE
 1/4-1/2
 2567
 Higher**

**WILLIG FREIGHT LINES
 751 NUTTMAN STREET
 SANTA CLARA, CA 95050**

**LUST S101630458
 CA FID UST N/A**

Site 3 of 3 in cluster AC

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0602
 Reg Board: San Francisco Bay Region
 Chemical: Diesel
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Remove Free Product - remove floating product from water table
 Review Date: Not reported
 Workplan: 5/5/1993
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 4/11/2001
 Release Date: 5/4/1992
 Cleanup Fund Id : Not reported
 Discover Date : 6/15/1992
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 5/20/1992
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : 1/2/1965
 Max MTBE GW : 5
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WILLIG FREIGHT LINES (Continued)

S101630458

Priority: Not reported
Local Case #: 06S1W26E04
Beneficial: Not reported
Staff: CTH
GW Qualifies: <
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 6/19/2001
Stop Date: 6/15/1992
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500638
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 1854.6261971102489858941667
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0602
Entered Date: 05/20/1992
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 60
Maximum Groundwater Impact: 9999999
County: Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 5
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Quality: Not reported

AD117 CAMSI IV PROPERTY
South 2710 LAFAYETTE
1/4-1/2 SANTA CLARA, CA 95050
2572
Higher Site 1 of 2 in cluster AD

Cal-Sites S100351761
Cortese N/A
CA SLIC

CAL-SITES:

Facility ID 43390002
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 05/03/1994
Lead: Not reported
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: CAMSI IV PROPERTY
Status Name: PROPERTY/SITE REFERRED TO RWQCB
Lead Agency: N/A Not reported
NPL: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

CAMSI IV PROPERTY (Continued)

S100351761

SIC: 39 MISCELLANEOUS MANUFACTURING INDUSTRIES
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: SF - SAN FRANCISCO BAY
 Access: Controlled
 Cortese: C
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Confirmed
 No. of Contamination Sources: 1
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: 22
 State Senate District: 13

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2 438284N01
 Region: CORTESE
 Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

SLIC Region 2:

Facility ID: 43S0231
 Region: 2
 Facility Status: Active Not reported
 Staff: DIB Not reported
 Last Site Update: 12/17/19
 NPL Status: Not an NPL site Discovery Date: 01/01/1982
 Case List: SLIC Imaged: No
 Date Closed: Not reported Cost Recovery: YES
 Abate Method: Not reported Substance: Not reported
 Case Type: NT Sample Date: 12/08/1992
 Contamination: WASTE BURIED IN TRENCHES/BACKWASH DISP ON GROUND
 Lead: 2189.8284 RWQCB
 Contamination Level: 0
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Yes
 Soil Removal or Contaminant Action Started: 04/01/1988
 Soil Removal or Contaminant Action Completed:
 On-Site Groundwater Extraction or Containment is Needed: Yes
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed: Yes
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 700
 Depth of Contamination Plume (Feet): 25
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

CAMSI IV PROPERTY (Continued)

S100351761

Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : No
 Begun Remediation: Yes
 Completed Remediation: No
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: OPEN FIELD
 Comment: Not reported

AD118
 South
 1/4-1/2
 2572
 Higher

MONSANTO CHEM CO
2710 LAFAYETTE ST
SANTA CLARA, CA 95050

RCRIS-SQG 1000376913
FINDS CAD009156290
LUST
CA SLIC
CERC-NFRAP

Site 2 of 2 in cluster AD

CERCLIS-NFRAP Classification Data:
 Site Incident Category: Not reported
 Non NPL Code: NFRAP
 Ownership Status: Unknown
 CERCLIS-NFRAP Assessment History:
 Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: SITE INSPECTION
 Federal Facility: Not a Federal Facility
 NPL Status: Not on the NPL
 Completed: 11/01/1979
 Completed: 04/01/1980
 Completed: 09/01/1988
 Completed: 05/16/1990

RCRIS:
 Owner: MONSANTO COMPANY
 (415) 555-1212
 EPA ID: CAD009156290
 Contact: ENVIRONMENTAL MANAGER
 (408) 727-0414

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:
 Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:
 Cross Street: Not reported
 Qty Leaked: 0
 Case Number: 43S0496
 Reg Board: San Francisco Bay Region
 Chemical: Solvents
 Lead Agency: Regional Board
 Local Agency : 43099
 Case Type: Undefined
 Status: Leak being confirmed
 County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MONSANTO CHEM CO (Continued)

1000376913

Review Date: 7/14/1985 Confirm Leak: 7/14/1985
Workplan: Not reported Prelim Assess: Not reported
Pollution Char: Not reported Remed Plan: Not reported
Remed Action: Not reported Monitoring: Not reported
Close Date: Not reported
Release Date: 7/30/1994
Cleanup Fund Id : Not reported
Discover Date : Not reported
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : Not reported
Funding: Not reported
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Not reported
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case # : Not reported
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : Not reported
Stop Date : Not reported
Work Suspended :N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608591651
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 5280.8691007372939081660373894
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43S0496
Entered Date: / /
Facility Status: Leak being confirmed
Maximum Soil Concentration: 0
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s)
 EDR ID Number
 EPA ID Number

MONSANTO CHEM CO (Continued)

1000376913

MTBE Detected in Soil:	Not reported	
MTBE:	0	
MTBE Qualify:	0	
SLIC Region 2:		
Facility ID:	43S0496	
Region:	2	
Facility Status:	Active	Not reported
Staff:	VAC	Not reported
Last Site Update:	06/06/19	
NPL Status:	Not reported	Discovery Date: Not reported
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: No
Abate Method:	13	Substance: Solvents
Case Type:	TK	Sample Date: Not reported
Contamination:	Not reported	
Lead:	RWQCB 2189.8284	
Contamination Level:		
Number of Municipal Wells Contaminated by Site:	0	
Number of Private Wells Contaminated by Site:	0	
Soil Removal Action Taken/Needed:	0	
Soil Removal or Contaminant Action Started:		
Soil Removal or Contaminant Action Completed:	0	
On-Site Groundwater Extraction or Containment is Needed:	0	
On-Site Groundwater Extraction or Containment Started:		
Off-Site Groundwater Extraction or Containment is Needed:		
Off-Site Groundwater Extraction or Containment Started:		
Length of Contamination Plume (Feet):	0	
Depth of Contamination Plume (Feet):	0	
Wells Closed Due To Contamination of Site:		
Date of Wells Closure:		
Nearest Public or Private Drinking Water Well (Feet):	0	
Under Jurisdiction of Lead Agency Date:		
Latitude/Longitude:	0 / 0	
Flow Rate:	0	
Flow Date:		
Percent of Contaminants Contained:	0	
Contaminant Type:		
EPA ID:		
Stages of Site Investigation Process Initiated:		
Begun Characterization :		Not reported
Completed Characterization :		Not reported
Begun Remediation:		Not reported
Completed Remediation:		Not reported
Submitted Remediation Plan:		Not reported
Approved Remediation Plan:		Not reported
Begun Final Remedial Action:		Not reported
Completed Final Remedial Action:		Not reported
Facility Desc:	Not reported	
Comment:	Not reported	

AE119
SE
1/4-1/2
2586
Higher

CONTAINER CORP
2600 DE LA CRUZ BLVD
SANTA CLARA, CA 95050

Site 1 of 4 in cluster AE

LUST S105032961
Cortese N/A

LUST Region SC:
 Region: Santa Clara

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

CONTAINER CORP (Continued)

S105032961

Case Rank: O222 Closed Date: 01/26/1996
 Transfer Date: Not reported SCVWD Id: 06S1E08D01f

CORTESE:

Reg Id: 43-0408
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AE120
 SE
 1/4-1/2
 2592
 Higher**

**CONTAINER CORP.
 2600 DE LA CRUZ BLVD
 SANTA CLARA, CA**

**LUST S103880770
 N/A**

Site 2 of 4 in cluster AE

LUST Region SC:

Region: Santa Clara
 Case Rank: O432 Closed Date: 09/27/2000
 Transfer Date: Not reported SCVWD Id: 06S1W35F01f

**AE121
 SE
 1/4-1/2
 2592
 Higher**

**CONTAINER CORP. OF AMERICA
 2600 DE LA CRUZ BLVD.
 SANTA CLARA, CA 95050**

**LUST 1000897852
 CA FID UST N/A**

Site 3 of 4 in cluster AE

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0408
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Remove Free Product - remove floating product from water table
 Review Date: Not reported Confirm Leak: Not reported
 Workplan: 12/31/1982 Prelim Assess: 12/31/1982
 Pollution Char: Not reported Remed Plan: Not reported
 Remed Action: Not reported Monitoring: Not reported
 Close Date: 9/27/2000
 Release Date: 5/8/1985
 Cleanup Fund Id: Not reported
 Discover Date: 9/27/1984
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 5/18/1985
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: 1/2/1965
 Max MTBE GW: 140
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

CONTAINER CORP. OF AMERICA (Continued)

1000897852

Local Case # : 06S1W35F01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 11/14/2000
Stop Date : 9/27/1984
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500459
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3729.9407786459042857239418686
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:
Region: 2
Facility Id: 43-0408
Entered Date: 05/18/1985
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 3600
Maximum Groundwater Impact: 9999999
County : Santa Clara
Current Benzene: 430
MTBE Detected in GW: 140
MTBE Detected in Soil: Not reported
MTBE: 8
MTBE Qualify: Not reported

FID:
Facility ID: 43000593 Regulate ID: CAD982033
Reg By: Inactive Underground Storage Tank Location
Cortese Code: Not reported SIC Code: Not reported
Status: Inactive Facility Tel: (408) 496-5118
Mail To: Not reported
401 ALTON STREET
SANTA CLARA, CA 95050
Contact: Not reported Contact Tel: Not reported
DUNs No: Not reported NPDES No: Not reported
Creation: 10/22/93 Modified: 00/00/00
EPA ID: Not reported
Comments: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

CONTAINER CORP. OF AMERICA (Continued)

1000897852

Facility ID:	43000593	Regulate ID:	CAD982033
Reg By:	Active Underground Storage Tank Location		
Cortese Code:	Not reported	SIC Code:	Not reported
Status:	Active	Facility Tel:	(415) 685-1230
Mail To:	Not reported		
	500 COURT ST		
	PLEASANT HILL, CA 94523		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

AE122
 SE
 1/4-1/2
 2592
 Higher

**2600 DE LA CRUZ BLVD.
 SANTA CLARA, CA 95050**

CHMIRS S100279274
 N/A

Site 4 of 4 in cluster AE

CHMIRS:

OES Control Number:	8905644	DOT ID:	1993
DOT Hazard Class:	Flammable liquid		
Chemical Name:	DIESEL FUEL		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	75
Environmental Contamination:	Ground	Property Use:	Manufacturing
Incident Date:	07-APR-89	Date Completed:	07-APR-89

AF123
 South
 1/4-1/2
 2602
 Higher

**BARNHART CONSTRUCTION
 785 WALSH AVE
 SANTA CLARA, CA 95050**

LUST S103473171
 Cortese N/A

Site 1 of 2 in cluster AF

State LUST:

Cross Street:	Not reported		
Qty Leaked:	Not reported		
Case Number	43-0864		
Reg Board:	San Francisco Bay Region		
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	43099		
Case Type:	Other ground water affected		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site, Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Review Date:	Not reported	Confirm Leak:	Not reported
Workplan:	5/14/1990	Prelim Assess:	5/14/1990
Pollution Char:	Not reported	Remed Plan:	Not reported
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	6/25/1996		
Release Date:	2/18/1985		
Cleanup Fund Id :	Not reported		
Discover Date :	2/26/1985		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BARNHART CONSTRUCTION (Continued)

S103473171

Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 2/28/1985
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case # : 06S1W35D01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 7/2/1996
Stop Date : 2/26/1985
Work Suspended : N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500875
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 5366.8473844723257678401332136
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0864
Entered Date: 02/28/1985
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 2000
Maximum Groundwater Impact: 120000
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: 06/25/1996
SCVWD Id: 06S1W35D01f

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ACI GLASS PRODUCTS (Continued)

S100928868

Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500097
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mibe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 5277.175269453637246975775577
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0026
Entered Date: 01/03/1991
Facility Status: Pollution characterization
Maximum Soil Concentration: 2500
Maximum Groundwater Impact: 85000
County: Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 800
MTBE Detected in Soil: Not reported
MTBE: 280
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O441
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W35E04f

CORTESE:

Reg Id: 43-0026
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

125
West
1/4-1/2
2618
Higher

PACIFIC BELL
1700 SPACE PARK DRIVE
SANTA CLARA, CA 95050

RCRIS-SQG 1000251358
FINDS CAT080022015
HAZNET
LUST
Cortese
UST
HIST UST

RCRIS:

Owner: THE PACIFIC TELEPHONE AND TELEGRAPH CO
(415) 555-1212
EPA ID: CAT080022015
Contact: ENVIRONMENTAL MANAGER
(408) 491-6029

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC BELL (Continued)

1000251358

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-1746
Reg Board: San Francisco Bay Region
Chemical: Diesel
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: 9/22/1993
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 11/19/1996
Release Date: 9/30/1993
Cleanup Fund Id: Not reported
Discover Date: 9/22/1993
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 10/14/1993
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case #: 06S1W27Q01
Beneficial: Not reported
Staff: CTH
GW Qualifies: Not reported
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 11/26/1996
Stop Date: 9/22/1993
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported

Confirm Leak: 9/22/1993
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC BELL (Continued)

1000251358

Global Id: T0608501682
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mibe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 5268.1440796583311433459540282
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1746
Entered Date: 10/14/1993
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 4100
Maximum Groundwater Impact: 100
County: Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O332
Transfer Date: Not reported
Closed Date: 11/19/1996
SCVWD Id: 06S1W27Q01f

HAZNET:

Gepaid: CAT080022015
Tepaid: CAD050806850
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .2479
Category: Polychlorinated biphenyls and material containing PCB's
Disposal Method: Transfer Station
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County: Santa Clara

Gepaid: CAT080022015
Tepaid: CAD981388952
Gen County: Santa Clara
Tsd County: Shasta
Tons: .1095
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC BELL (Continued)

1000251358

Gepaid: CAT080022015
Tepaid: CAD981382732
Gen County: Santa Clara
Tsd County: 1
Tons: 3.3712
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

Gepaid: CAT080022015
Tepaid: CAD981388952
Gen County: Santa Clara
Tsd County: Shasta
Tons: .0150
Category: Asbestos-containing waste
Disposal Method: Not reported
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

Gepaid: CAT080022015
Tepaid: CAD981388952
Gen County: Santa Clara
Tsd County: Shasta
Tons: .0450
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

The CA HAZNET database contains 17 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:
Reg Id: 43-1746
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

UST HIST:
Facility ID: 57698
Tank Num: 1
Tank Capacity: 25000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Leak Detection: None
Contact Name: E.J. KOEHLER
Total Tanks: 1
Facility Type: 2
Container Num: 1
Year Installed: 1972
Tank Construction: Not reported
Telephone: (415) 542-6758
Region: STATE
Other Type: SIC 4800

State UST:

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

PACIFIC BELL (Continued)

EDR ID Number
 EPA ID Number

1000251358

Facility ID: 300640
 Total Tanks: 1
 Region: STATE
 Local Agency: Santa Clara, Santa Clara County

126
 NE
 1/4-1/2
 2638
 Higher

**JACK HORTON DRYWALL
 505 LAURELWOOD
 SANTA CLARA, CA 95054**

**HAZNET S105036363
 LUST N/A
 Cortese**

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0595
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Vent Soil - bore holes in soil to allow volatilization of contaminants

Review Date:	Not reported	Confirm Leak:	Not reported
Workplan:	Not reported	Prelim Assess:	Not reported
Pollution Char:	Not reported	Remed Plan:	Not reported
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	11/19/1997		
Release Date:	6/18/1992		
Cleanup Fund Id:	Not reported		
Discover Date:	4/2/1992		
Enforcement Dt:	Not reported		
Enf Type:	Not reported		
Enter Date:	11/12/1992		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim:	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date:	1/2/1965		
Max MTBE GW:	0		
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected		
Priority:	2A4		
Local Case #:	06S1W26F01		
Beneficial:	Not reported		
Staff:	CTH		
GW Qualifies:	Not reported		
Max MTBE Soil:	Not reported		
Soil Qualifies:	Not reported		
Hydr Basin #:	Not reported		
Operator:	Not reported		
Oversight Prgm:	Local Oversight Program UST		
Oversight Prgm:	LOP		
Review Date:	3/2/1993		
Stop Date:	4/2/1992		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

JACK HORTON DRYWALL (Continued)

S105036363

Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500631
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2754.5304565934675057770897896
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0595
Entered Date: 11/12/1992
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 454
Maximum Groundwater Impact: 100000
County : Santa Clara
Current Benzene: 1
MTBE Detected in GW: No
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: ND

LUST Region SC:

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: 11/19/1997
SCVWD Id: 06S1W26F01f

HAZNET:

Gepaid: CAC001207152
Tepaid: WAD009477175
Gen County: Santa Clara
Tsd County: 99
Tons: 1.0500
Category: Other organic solids
Disposal Method: Recycler
Contact: JACK HORTON
Telephone: (415) 665-2220
Mailing Address: 505 LAURELWOOD
SANTA CLARA, CA 95054 - 2419
County Santa Clara

CORTESE:

Reg Id: 43-0595
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AG127
SSE
1/4-1/2
2639
Higher

BERRYMAN ELECTRO PLATING
650 WALSH
SANTA CLARA, CA 95050
Site 1 of 5 in cluster AG

Cal-Sites S100714740
N/A

CAL-SITES:

Facility ID 43340037
Status: REFOA - DOES NOT REQUIRE DTSC ACTION OR OVERSITE ACTIVITY. REFERED TO

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

BERRYMAN ELECTRO PLATING (Continued)

S100714740

Status Date: OTHER AGENCY LEAD
 Status Date: 01/12/1989
 Lead: Not reported
 Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO ANOTHER AGENCY
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 34 MANU - FABRICATED METAL PRODUCTS
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: SF - SAN FRANCISCO BAY
 Access: Uncontrolled
 Cortese: U
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/Long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

**AG128
 SSE
 1/4-1/2
 2639
 Higher**

**KEYSTONE WIRE GALVANIZING FAC
 651 WALSH AVE
 SANTA CLARA, CA 95050**

**CA SLIC S100865726
 N/A**

Site 2 of 5 in cluster AG

SLIC Region 2:
 Facility ID: 43S0665
 Region: 2
 Facility Status: Inactive Not reported
 Staff: Not reported Not reported
 Last Site Update: 11/30/19
 NPL Status: Not an NPL site Discovery Date: Not reported
 Case List: SLIC Imaged: No
 Date Closed: Not reported Cost Recovery: No
 Abate Method: Not reported Substance: Not reported
 Case Type: NT Sample Date: Not reported
 Contamination: WASTE WATER FROM WIRE PROCESSING OPERATIONS
 Lead: RWQCB
 Contamination Level:
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: 0
 Soil Removal or Contaminant Action Started:
 Soil Removal or Contaminant Action Completed: 0
 On-Site Groundwater Extraction or Containment is Needed: 0
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed:
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 0

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

KEYSTONE WIRE GALVANIZING FAC (Continued)

S100865726

Depth of Contamination Plume (Feet): 0
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : No
 Completed Characterization : No
 Begun Remediation: No
 Completed Remediation: No
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: WIRE PROCESSING FACILITY
 Comment: Not reported

**AG129
 SSE
 1/4-1/2
 2639
 Higher**

**KEYSTONE GROUP - SANTA CLARA PLANT
 651 WALSH AVE
 SANTA CLARA, CA 95050
 Site 3 of 5 in cluster AG**

**Cal-Sites 1000389778
 RCRIS-SQG CAD009141433
 FINDS
 CERC-NFRAP**

CERCLIS-NFRAP Classification Data:
 Site Incident Category: Not reported Federal Facility: Not a Federal Facility
 Non NPL Code: NFRAP NPL Status: Not on the NPL
 Ownership Status: Unknown
 CERCLIS-NFRAP Assessment History:
 Assessment: DISCOVERY Completed: 12/01/1987
 Assessment: PRELIMINARY ASSESSMENT Completed: 07/24/1989
 Assessment: SITE INSPECTION Completed: 03/26/1991
 CERCLIS-NFRAP Alias Name(s):
 BERRYMAN ELECTRO PLATING
 BERRYMAN ELECTRO PLATING
 PREVIOUS NAME BERRYMAN ELECTRO PLATING
 BERRYMAN ELECTRO PLATING
 RCRIS:
 Owner: NOT REQUIRED
 (415) 555-1212
 EPA ID: CAD009141433
 Contact: ENVIRONMENTAL MANAGER
 (309) 697-7552
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

KEYSTONE GROUP - SANTA CLARA PLANT (Continued)

1000389778

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CAL-SITES:

Facility ID: 43330028
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 03/31/1995
Lead: Not reported
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: Not reported
Status Name: PROPERTY/SITE REFERRED TO RWQCB
Lead Agency: N/A Not reported
NPL: Not reported
SIC: 33 MANU - PRIMARY METAL INDUSTRIES
Facility Type: N/A
Type Name: Not reported
Staff Member Responsible for Site: Not reported
Supervisor Responsible for Site: Not reported
Region Water Control Board: Not reported
Access: Controlled
Cortese: C
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Not reported
No. of Contamination Sources: 0
Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
Lat/long Method: Not reported
State Assembly District Code: Not reported
State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

130
NNW
1/2-1
2641
Same

3610 BASSETT
SANTA CLARA, CA 95054

CHMIRS S100274869
N/A

CHMIRS:

OES Control Number: 8905480 DOT ID: 1830
DOT Hazard Class: Corrosives
Chemical Name: ACID, SULFURIC
Extent of Release: Not reported
CAS Number: 7664-93-9 Quantity Released: .5
Environmental Contamination: Air Property Use: Manufacturing
Incident Date: 22-MAR-89 Date Completed: 22-MAR-89

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

131
 South
 1/2-1
 2646
 Higher

TECHNICAL COATINGS CO
WALSH AVE
SANTA CLARA, CA 95050

Cal-Sites 1000243110
FINDS 95050TCHNC10
HAZNET
Cortese
RCRIS-LQG
TRIS
UST
CA SLIC
CA FID UST
CERC-NFRAP
HIST UST

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
 Non NPL Code: NFRAP
 Ownership Status: Unknown

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: SITE INSPECTION

Completed: 05/01/1986
 Completed: 05/01/1987
 Completed: 07/01/1988
 Completed: 05/03/1990

RCRIS:

Owner: TECHNICAL COATINGS CO
 (408) 727-3400
 EPA ID: CAD009118506
 Contact: ENVIRONMENTAL MANAGER
 (408) 727-3400

Classification: Large Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
F003	7578.26	F005	7578.26

Violation Status: Violations exist

Regulation Violated: Not reported
 Area of Violation: GENERATOR-GENERAL REQUIREMENTS
 Date Violation Determined: 08/26/1994
 Actual Date Achieved Compliance: 19-SEP-94

There are 1 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	19-SEP-94

FINDS:

- Other Pertinent Environmental Activity Identified at Site:
- AIRS Facility System (AIRS/AFS)
 - Biennial Reporting System (BRS)
 - Facility Registry System (FRS)
 - National Compliance Database (NCDB)
 - National Emissions Trends (NET)
 - National Toxics Inventory (NTI)
 - Resource Conservation and Recovery Act Information system (RCRAINFO)

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

TECHNICAL COATINGS CO (Continued)

1000243110

Toxic Chemical Release Inventory System (TRIS)

CAL-SITES:

Facility ID: 43280010
Status: REFOA - DOES NOT REQUIRE DTSC ACTION OR OVERSITE ACTIVITY. REFERED TO OTHER AGENCY LEAD
Status Date: 06/18/1987
Lead: Not reported
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: Not reported
Status Name: PROPERTY/SITE REFERRED TO ANOTHER AGENCY
Lead Agency: N/A Not reported
NPL: Not reported
SIC: 28 MANU - CHEMICALS & ALLIED PRODUCTS
Facility Type: N/A
Type Name: Not reported
Staff Member Responsible for Site: Not reported
Supervisor Responsible for Site: Not reported
Region Water Control Board: NC - NORTH COAST
Access: Controlled
Cortese: C
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Not reported
No. of Contamination Sources: 0
Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
Lat/long Method: Not reported
State Assembly District Code: Not reported
State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

HAZNET:

Gepaid: CAD009118506
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .0000
Category:
Disposal Method: Recycler
Contact: BENJAMIN MOORE & CO
Telephone: (201) 573-9600
Mailing Address: 1000 WALSH AVE
SANTA CLARA, CA 95050 - 2615
County: Santa Clara
Gepaid: CAD009118506
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: 27.7930
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Contact: BENJAMIN MOORE & CO
Telephone: (201) 573-9600
Mailing Address: 1000 WALSH AVE
SANTA CLARA, CA 95050 - 2615

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TECHNICAL COATINGS CO (Continued)

1000243110

County Santa Clara
Gepaid: CAD009118506
Tepaid: Not reported
Gen County: Santa Clara
Tsd County: 0
Tons: 2.0000
Category: Other organic solids
Disposal Method: Treatment, Incineration
Contact: BENJAMIN MOORE & CO
Telephone: (201) 573-9600
Mailing Address: 1000 WALSH AVE
SANTA CLARA, CA 95050 - 2615
County Santa Clara
Gepaid: CAD009118506
Tepaid: AZD982441263
Gen County: Santa Clara
Tsd County: 99
Tons: 8.0000
Category: Other organic solids
Disposal Method: Treatment, Incineration
Contact: BENJAMIN MOORE & CO
Telephone: (201) 573-9600
Mailing Address: 1000 WALSH AVE
SANTA CLARA, CA 95050 - 2615
County Santa Clara
Gepaid: CAD009118506
Tepaid: AZD982441263
Gen County: Santa Clara
Tsd County: 99
Tons: 6.3500
Category: Other organic solids
Disposal Method: Not reported
Contact: BENJAMIN MOORE & CO
Telephone: (201) 573-9600
Mailing Address: 1000 WALSH AVE
SANTA CLARA, CA 95050 - 2615
County Santa Clara

The CA HAZNET database contains 47 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2 438134N01
Region: CORTESE
Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TECHNICAL COATINGS CO (Continued)

1000243110

FID:

Facility ID:	43006298	Regulate ID:	Not reported
Reg By:	Active Underground Storage Tank Location		
Cortese Code:	Not reported	SIC Code:	Not reported
Status:	Active	Facility Tel:	(408) 727-3400
Mail To:	Not reported		
	1000 WALSH AVENUE		
	SANTA CLARA, CA 95050		
Contact:	Not reported	Contact Tel:	Not reported
DUNS No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

SLIC Region 2:

Facility ID:	43S0127		
Region:	2		
Facility Status:	Active		Not reported
Staff:	VAC		Not reported
Last Site Update:	12/17/19		
NPL Status:	Not an NPL site	Discovery Date:	04/30/1982
Case List:	SLIC	Imaged:	No
Date Closed:	Not reported	Cost Recovery:	YES
Abate Method:	Not reported	Substance:	Not reported
Case Type:	TK	Sample Date:	05/24/1990
Contamination:	LEAKS AND SPILLS FROM 15 UNDERGROUND STORAGE UNITS		
Lead:	2189.8134 RWQCB		
Contamination Level:		5280	
Number of Municipal Wells Contaminated by Site:		0	
Number of Private Wells Contaminated by Site:		0	
Soil Removal Action Taken/Needed:		Yes	
Soil Removal or Contaminant Action Started:			
Soil Removal or Contaminant Action Completed:		10/31/85	
On-Site Groundwater Extraction or Containment is Needed:		Yes	
On-Site Groundwater Extraction or Containment Started:		03/10/1987	
Off-Site Groundwater Extraction or Containment is Needed:		Not Determined	
Off-Site Groundwater Extraction or Containment Started:			
Length of Contamination Plume (Feet):		400	
Depth of Contamination Plume (Feet):		31	
Wells Closed Due To Contamination of Site:			
Date of Wells Closure:			
Nearest Public or Private Drinking Water Well (Feet):		0	
Under Jurisdiction of Lead Agency Date:		9/1/82	
Latitude/Longitude:		37 / -122	
Flow Rate:		2	
Flow Date:		01/05/1989	
Percent of Contaminants Contained:		1	
Contaminant Type:		T	
EPA ID:			
Stages of Site Investigation Process Initiated:			
Begun Characterization :		Yes	
Completed Characterization :		Yes	
Begun Remediation:		Yes	
Completed Remediation:		No	
Submitted Remediation Plan:		No	
Approved Remediation Plan:		No	
Begun Final Remedial Action:		No	

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TECHNICAL COATINGS CO (Continued)

1000243110

Completed Final Remedial Action:		No
Facility Desc:	MANUFACTURES PAINTS	
Comment:	Not reported	
UST HIST:		
Facility ID:	47994	
Tank Num:	1	Container Num: 11
Tank Capacity:	4000	Year Installed: Not reported
Tank Used for:	PRODUCT	
Type of Fuel:	Not Reported	Tank Construction: Not reported
Leak Detection:	None	
Contact Name:	JOHN MEYER	Telephone: (408) 727-3400
Total Tanks:	15	Region: STATE
Facility Type:	Not reported	Other Type: Not reported
Facility ID:	47994	
Tank Num:	2	Container Num: 1
Tank Capacity:	1500	Year Installed: 1971
Tank Used for:	WASTE	
Type of Fuel:	Not Reported	Tank Construction: Not reported
Leak Detection:	None	
Contact Name:	JOHN MEYER	Telephone: (408) 727-3400
Total Tanks:	15	Region: STATE
Facility Type:	Not reported	Other Type: Not reported
Facility ID:	47994	
Tank Num:	3	Container Num: 2
Tank Capacity:	550	Year Installed: Not reported
Tank Used for:	PRODUCT	
Type of Fuel:	DIESEL	Tank Construction: Not reported
Leak Detection:	None	
Contact Name:	JOHN MEYER	Telephone: (408) 727-3400
Total Tanks:	15	Region: STATE
Facility Type:	Not reported	Other Type: Not reported
Facility ID:	47994	
Tank Num:	4	Container Num: 3
Tank Capacity:	4000	Year Installed: Not reported
Tank Used for:	PRODUCT	
Type of Fuel:	Not Reported	Tank Construction: Not reported
Leak Detection:	None	
Contact Name:	JOHN MEYER	Telephone: (408) 727-3400
Total Tanks:	15	Region: STATE
Facility Type:	Not reported	Other Type: Not reported
Facility ID:	47994	
Tank Num:	5	Container Num: 4
Tank Capacity:	4000	Year Installed: 1968
Tank Used for:	PRODUCT	
Type of Fuel:	Not Reported	Tank Construction: Not reported
Leak Detection:	None	
Contact Name:	JOHN MEYER	Telephone: (408) 727-3400
Total Tanks:	15	Region: STATE
Facility Type:	Not reported	Other Type: Not reported
Facility ID:	47994	
Tank Num:	6	Container Num: 5
Tank Capacity:	4000	Year Installed: 1968

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TECHNICAL COATINGS CO (Continued)

100243110

Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 7
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Container Num: 6
Year Installed: 1968

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 8
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Container Num: 7
Year Installed: 1968

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 9
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Container Num: 8
Year Installed: Not reported

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 10
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Container Num: 9
Year Installed: Not reported

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 11
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported

Container Num: 10
Year Installed: Not reported

Tank Construction: Not reported

Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

TECHNICAL COATINGS CO (Continued)

1000243110

Facility ID: 47994
Tank Num: 12
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported
Container Num: 12
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 13
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported
Container Num: 13
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 14
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported
Container Num: 14
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

Facility ID: 47994
Tank Num: 15
Tank Capacity: 4000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: JOHN MEYER
Total Tanks: 15
Facility Type: Not reported
Container Num: 15
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 727-3400
Region: STATE
Other Type: Not reported

State UST:
Facility ID: 300691
Total Tanks: 1
Region: STATE
Local Agency: Santa Clara, Santa Clara County

AG132
SSE
1/2-1
2651
Higher

631 WALSH AVE
SANTA CLARA, CA 95050
Site 4 of 5 in cluster AG

CHMIRS S100275032
N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

(Continued)

S100275032

CHMIRS:
 OES Control Number: 8907095 DOT ID: 1830
 DOT Hazard Class: Corrosives
 Chemical Name: ACID, SULFURIC
 Extent of Release: Not reported
 CAS Number: 7664-93-9 Quantity Released: 5
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 18-JUL-89 Date Completed: 18-JUL-89

AG133
 SSE 630 WALSH
 1/2-1 SANTA CLARA, CA 95050
 2651
 Higher Site 5 of 5 in cluster AG

CHMIRS S100274785
 Cortese N/A

CORTESE:
 Reg Id: 43-0515
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

CHMIRS:
 OES Control Number: 8904544 DOT ID: 1897
 DOT Hazard Class: Not Reported
 Chemical Name: TETRACHLOROETHYLENE
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: Not reported
 Environmental Contamination: Ground Property Use: Industrial, Utility
 Incident Date: 20-JAN-89 Date Completed: 20-JAN-89

AH134
 South 1056 WALSH AVE.
 1/2-1 SANTA CLARA, CA 95050
 2665
 Higher Site 1 of 3 in cluster AH

CHMIRS S100274800
 N/A

CHMIRS:
 OES Control Number: 8904731 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: UNKNOWN
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 50
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 17-JAN-89 Date Completed: 17-JAN-89

AH135
 South 1056 WALSH
 1/2-1 SANTA CLARA, CA 95050
 2665
 Higher Site 2 of 3 in cluster AH

CHMIRS S100274926
 N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

(Continued)

S100274926

CHMIRS:
 OES Control Number: 8906074 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: PAINT
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 25
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 20-APR-89 Date Completed: 20-APR-89

AH136 FELTON ALUMINUM COMPANY
 South 1090 WALSH AVE
 1/2-1 SANTA CLARA, CA 95050
 2679
 Higher Site 3 of 3 in cluster AH

LUST S104162746
 Cortese N/A

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number 43-0570
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Regional Board
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: No Action Taken - no action has as yet been taken at the site
 Review Date: Not reported Confirm Leak: Not reported
 Workplan: Not reported Prelim Assess: Not reported
 Pollution Char: Not reported Remed Plan: Not reported
 Remed Action: Not reported Monitoring: Not reported
 Close Date: 5/15/1996
 Release Date: 1/23/1985
 Cleanup Fund Id : Not reported
 Discover Date : 2/25/1985
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 2/3/1985
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : No
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : Not reported
 Max MTBE GW : Not reported
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
 Priority: Not reported
 Local Case # : 06S1W34H01
 Beneficial: Not reported
 Staff : CTH
 GW Qualifies : Not reported
 Max MTBE Soil : Not reported
 Soil Qualifies : Not reported
 Hydr Basin #: Not reported
 Operator : Not reported
 Oversight Prgm: RB Lead Underground Storage Tank

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FELTON ALUMINUM COMPANY (Continued)

S104162746

Oversight Prgm : UST
Review Date : 1/5/1999
Stop Date : 2/25/1985
Work Suspended N
Responsible Party BLANK RP
RP Address: Not reported
Global Id: T0608500607
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 5007.1424731802899557817108414
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0570
Entered Date: 02/03/1985
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 0
Maximum Groundwater Impact: 3000
County : Santa Clara
Current Benzene: 14
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O331
Transfer Date: 09/24/1990
Closed Date: 05/15/1996
SCVWD Id: 06S1W34H01f

CORTESE:

Reg Id: 43-0570
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

137
NNE
1/2-1
2720
Lower

JRW ENTERPRISES
850 ALDO AVE
SANTA CLARA, CA 95054

LUST S103177359
Cortese N/A

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0766
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency : 43099
Case Type: Soil only
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

JRW ENTERPRISES (Continued)

S103177359

Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 5/3/1991
Release Date: 1/22/1986
Cleanup Fund Id : Not reported
Discover Date : 1/22/1986
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 2/2/1986
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case # : 06S1W26E02
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 7/1/1990
Stop Date : 1/22/1986
Work Suspended N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500789
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mibe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 1233.4113998157840957869430642
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0766
Entered Date: 02/02/1986
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 72
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

JRW ENTERPRISES (Continued)

S103177359

MTBE Detected in Soil: Not reported
 MTBE: 0
 MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
 Case Rank: S--
 Transfer Date: Not reported
 Closed Date: 05/03/1991
 SCVWD Id: 06S1W26E02f

CORTESE:

Reg Id: 43-0766
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

138
 SSW
 1/2-1
 2730
 Higher

T & D TILE CO., INC.
 1180 WALSH AVENUE
 SANTA CLARA, CA 95050

HAZNET S101594469
LUST N/A
Cortese
CA FID UST

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1432
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Pollution characterization
 County: Santa Clara
 Abate Method: No Action Taken - no action has as yet been taken at the site
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: Not reported
 Release Date: 3/30/1988
 Cleanup Fund Id: Not reported
 Discover Date: 4/4/1988
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 4/10/1988
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: No
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: 7/27/2001
 Max MTBE GW: 87
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case #: 06S1W34G01
 Beneficial: Not reported
 Staff: CTH
 GW Qualifies: =
 Max MTBE Soil: Not reported
 Soil Qualifies: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

T & D TILE CO., INC. (Continued)

S101594469

Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 2/1/2001
Stop Date: 4/4/1988
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501404
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 2
Mibe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 4988.4908454900283121298892984
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1432
Entered Date: 04/10/1988
Facility Status: Pollution characterization
Maximum Soil Concentration: 2400
Maximum Groundwater Impact: 62000
County: Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 87
MTBE Detected in Soil: Not reported
MTBE: 87
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O341
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W34G01f

HAZNET:

Gepaid: CAL000216329
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .2293
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: T&D TILE CO INC
Telephone: (408) 727-6778
Mailing Address: 1180 WALSH AVE
SANTA CLARA, CA 95050
County: Santa Clara

CORTESE:

Reg Id: 43-1432
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

T & D TILE CO., INC. (Continued)

S101594469

FID:

Facility ID:	43001418	Regulate ID:	Not reported
Reg By:	Inactive Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(408) 727-6778
Status:	Inactive		
Mail To:	Not reported		
	1180 WALSH AVENUE		
	SANTA CLARA, CA 95050		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

**A1139
 NW
 1/2-1
 2837
 Higher**

**PAUL MUNROE HYDRAULICS
 THOMAS RD
 SANTA CLARA, CA 95054
 Site 1 of 2 in cluster AI**

**RCRIS-SQG 1000274672
 FINDS CAD981165939
 HAZNET
 LUST
 Cortese
 CA SLIC
 HIST UST**

RCRIS:

Owner: T&M JOINT VENTURE
 (415) 555-1212
 EPA ID: CAD981165939
 Contact: ENVIRONMENTAL MANAGER
 (408) 988-1333

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDf Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	5/30/1987
Case Number:	43-1826	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Waste Oil		
Lead Agency:	Regional Board		
Local Agency :	43099		
Case Type:	Other ground water affected		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	No Action Taken - no action has as yet been taken at the site		
Review Date:	Not reported		
Workplan:	5/30/1987		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	5/19/1993		
Release Date:	3/13/1987		
Cleanup Fund Id :	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PAUL MUNROE HYDRAULICS (Continued)

1000274672

Discover Date : 3/13/1987
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 3/13/1987
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case # : 06S1W27C01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 7/25/1997
Stop Date : 3/13/1987
Work Suspended N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501753
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 4003.033338786343650747624758
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1826
Entered Date: 03/13/1987
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 6500
Maximum Groundwater Impact: 9999999
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PAUL MUNROE HYDRAULICS (Continued)

1000274672

HAZNET:

Gepaid: CAD981165939
Tepaid: CAD083166728
Gen County: Santa Clara
Tsd County: Stanislaus
Tons: .3002
Category: Oil/water separation sludge
Disposal Method: Not reported
Contact: PAUL MUNROE HYD
Telephone: (000) 000-0000
Mailing Address: 3701 THOMAS RD
SANTA CLARA, CA 95054 - 2042
County Santa Clara

Gepaid: CAD981165939
Tepaid: CAD083166728
Gen County: Santa Clara
Tsd County: Stanislaus
Tons: 2.8981
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: PAUL MUNROE HYD
Telephone: (000) 000-0000
Mailing Address: 3701 THOMAS RD
SANTA CLARA, CA 95054 - 2042
County Santa Clara

Gepaid: CAD981165939
Tepaid: CAD083166728
Gen County: Santa Clara
Tsd County: Stanislaus
Tons: .3002
Category: Oil/water separation sludge
Disposal Method: Recycler
Contact: PAUL MUNROE HYD
Telephone: (000) 000-0000
Mailing Address: 3701 THOMAS RD
SANTA CLARA, CA 95054 - 2042
County Santa Clara

Gepaid: CAD981165939
Tepaid: CAD083166728
Gen County: Santa Clara
Tsd County: Stanislaus
Tons: .5629
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: PAUL MUNROE HYD
Telephone: (000) 000-0000
Mailing Address: 3701 THOMAS RD
SANTA CLARA, CA 95054 - 2042
County Santa Clara

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PAUL MUNROE HYDRAULICS (Continued)

1000274672

Gepaid: CAD981165939
 Tepaid: CAD083166728
 Gen County: Santa Clara
 Tsd County: Stanislaus
 Tons: .5421
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: PAUL MUNROE HYD
 Telephone: (000) 000-0000
 Mailing Address: 3701 THOMAS RD
 SANTA CLARA, CA 95054 - 2042
 County: Santa Clara

The CA HAZNET database contains 8 additional records for this site.
 Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 43-1826
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

SLIC Region 2:

Facility ID:	43S0239		
Region:	2		
Facility Status:	Closed - No Further Action		Not reported
Staff:	MEJ		Not reported
Last Site Update:	04/12/19		
NPL Status:	Not an NPL site	Discovery Date:	08/13/1987
Case List:	SLIC	Imaged:	No
Date Closed:	Not reported	Cost Recovery:	No
Abate Method:	Not reported	Substance:	Not reported
Case Type:	TK	Sample Date:	01/10/1989
Contamination:	DRAINAGE SUMP AND HYDRAULIC OIL		
Lead:	2189.8289 RWQCB		
Contamination Level:	0		
Number of Municipal Wells Contaminated by Site:	0		
Number of Private Wells Contaminated by Site:	0		
Soil Removal Action Taken/Needed:	Yes		
Soil Removal or Contaminant Action Started:	10/31/1986		
Soil Removal or Contaminant Action Completed:			
On-Site Groundwater Extraction or Containment is Needed:	Not Determined		
On-Site Groundwater Extraction or Containment Started:			
Off-Site Groundwater Extraction or Containment is Needed:	Not Determined		
Off-Site Groundwater Extraction or Containment Started:			
Length of Contamination Plume (Feet):	70		
Depth of Contamination Plume (Feet):	25		
Wells Closed Due To Contamination of Site:			
Date of Wells Closure:			
Nearest Public or Private Drinking Water Well (Feet):	0		
Under Jurisdiction of Lead Agency Date:	1/1/88		
Latitude/Longitude:	37 / -122		
Flow Rate:	0		
Flow Date:			
Percent of Contaminants Contained:	0		
Contaminant Type:			
EPA ID:			
Stages of Site Investigation Process Initiated:			
Begun Characterization :	Yes		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PAUL MUNROE HYDRAULICS (Continued)

1000274672

Completed Characterization : No
Begun Remediation: No
Completed Remediation: No
Submitted Remediation Plan: No
Approved Remediation Plan: No
Begun Final Remedial Action: No
Completed Final Remedial Action: No

Facility Desc: HYDRAULIC REPAIR SHOP
Comment: Not reported

UST HIST:

Facility ID: 54288
Tank Num: 1
Tank Capacity: 1000
Tank Used for: WASTE
Type of Fuel: Not Reported
Leak Detection: Visual
Contact Name: GHIGLERI, NORM
Total Tanks: 4
Facility Type: Not reported
Container Num: ONE
Year Installed: 1979
Tank Construction: 4 inches
Telephone: (213) 692-6912
Region: STATE
Other Type: HYDRAULIC DISTRIBUTO

Facility ID: 54288
Tank Num: 2
Tank Capacity: 620
Tank Used for: WASTE
Type of Fuel: Not Reported
Leak Detection: Visual
Contact Name: GHIGLERI, NORM
Total Tanks: 4
Facility Type: Not reported
Container Num: ONE
Year Installed: 1984
Tank Construction: 4 inches
Telephone: (213) 692-6912
Region: STATE
Other Type: HYDRAULIC DISTRIBUTO

Facility ID: 54288
Tank Num: 3
Tank Capacity: 500
Tank Used for: WASTE
Type of Fuel: Not Reported
Leak Detection: Visual
Contact Name: GHIGLERI, NORM
Total Tanks: 4
Facility Type: Not reported
Container Num: ONE
Year Installed: 1975
Tank Construction: 4 inches
Telephone: (213) 692-6912
Region: STATE
Other Type: HYDRAULIC DISTRIBUTO

Facility ID: 54288
Tank Num: 4
Tank Capacity: 750
Tank Used for: WASTE
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: GHIGLERI, NORM
Total Tanks: 4
Facility Type: Not reported
Container Num: 1
Year Installed: 1983
Tank Construction: 10 gauge
Telephone: (213) 692-6912
Region: STATE
Other Type: HYDRAULIC DISTRIBUTO

Facility ID: 54288
Tank Num: 5
Tank Capacity: 1000
Tank Used for: WASTE
Type of Fuel: Not Reported
Leak Detection: Visual
Contact Name: GHIGLERI, NORM
Container Num: ONE
Year Installed: Not reported
Tank Construction: 4 inches
Telephone: (213) 692-6912

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

PAUL MUNROE HYDRAULICS (Continued)

1000274672

Total Tanks:	4	Region:	STATE
Facility Type:	Not reported	Other Type:	HYDRAULIC DISTRIBUTO

AI140
 NW
 1/2-1
 2837
 Higher

PAUL MUNROE HYDRAULICS INCORPORATED
 3701 THOMAS ROAD
 SANTA CLARA, CA 95054

Cal-Sites S100941981
 N/A

Site 2 of 2 in cluster AI

CAL-SITES:

Facility ID	43760003	
Status:	REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD	
Status Date:	12/28/1990	
Lead:	Not reported	
Region:	2 - BERKELEY	
Branch:	NC - NORTH COAST	
File Name:	Not reported	
Status Name:	PROPERTY/SITE REFERRED TO RWQCB	
Lead Agency:	N/A	Not reported
NPL:	Not reported	
SIC:	76 MISCELLANEOUS REPAIR SERVICES	
Facility Type:	N/A	
Type Name:	Not reported	
Staff Member Responsible for Site:	Not reported	
Supervisor Responsible for Site:	Not reported	
Region Water Control Board:	SF - SAN FRANCISCO BAY	
Access:	Not reported	
Cortese:	Not reported	
Hazardous Ranking Score:	Not reported	
Date Site Hazard Ranked:	Not reported	
Groundwater Contamination:	Not reported	
No. of Contamination Sources:	0	
Lat/Long:	0° 0' 0.00" / 0° 0' 0.00"	
Lat/long Method:	Not reported	
State Assembly District Code:	Not reported	
State Senate District:	Not reported	

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

141
 South
 1/2-1
 2889
 Higher

2655 LAFAYETTE ST.
 SANTA CLARA, CA 95050

CHMIRS S100217875
 N/A

CHMIRS:

OES Control Number:	8908516	DOT ID:	Not reported
DOT Hazard Class:	Corrosives		
Chemical Name:	ACID, HYDROCHLORIC		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	50
Environmental Contamination:	Ground	Property Use:	Not reported
Incident Date:	17-OCT-89	Date Completed:	17-OCT-89

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

142 NATKIN COMPANY
 NNE 807 ALDO AVE
 1/2-1 SANTA CLARA, CA 95054
 2926
 Lower

LUST S103473138
 Cortese N/A

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	4/16/1985
Case Number:	43-0974	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Regional Board		
Local Agency :	43099		
Case Type:	Soil only		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Review Date:	Not reported		
Workplan:	4/16/1985		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	8/16/1991		
Release Date:	2/5/1985		
Cleanup Fund Id :	Not reported		
Discover Date :	2/7/1985		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	2/15/1985		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.		
Priority:	Not reported		
Local Case # :	06S1W26E01		
Beneficial:	Not reported		
Staff :	CTH		
GW Qualifies :	Not reported		
Max MTBE Soil :	Not reported		
Soil Qualifies :	Not reported		
Hydr Basin #:	Not reported		
Operator :	Not reported		
Oversight Prgm:	RB Lead Underground Storage Tank		
Oversight Prgm :	UST		
Review Date :	1/9/1990		
Stop Date :	2/7/1985		
Work Suspended :	N		
Responsible Party:	BLANK RP		
RP Address:	Not reported		
Global Id:	T0608500974		
Org Name:	Not reported		
Contact Person:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

NATKIN COMPANY (Continued)

S103473138

MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 1142.3880915185167728452546935
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0974
Entered Date: 02/15/1985
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 340
Maximum Groundwater Impact: 0
County: Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O432
Transfer Date: Not reported
Closed Date: 08/16/1991
SCVWD Id: 06S1W26E01f

CORTESE:

Reg Id: 43-0974
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

143
NNE
1/2-1
3035
Lower

**701 ALDO UNIT 39
SANTA CLARA, CA 95050**

**CHMIRS S100275134
N/A**

CHMIRS:

OES Control Number: 8908172 DOT ID: 1050
DOT Hazard Class: Not Reported
Chemical Name: HYDROGEN CHLORIDE
Extent of Release: Not reported
CAS Number: 7647-01-0 Quantity Released: 1
Environmental Contamination: Ground Property Use: Manufacturing
Incident Date: 02-OCT-89 Date Completed: 02-OCT-89

144
SSW
1/2-1
3052
Higher

**COLLISHAW CORPORATION
1515 WALSH AVE
SANTA CLARA, CA 95050**

**Cortese S101304310
N/A**

CORTESE:

Reg Id: 43-0393
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

AJ145 **UNOCAL**
SE **2495 DE LA CRUZ BLVD**
1/2-1 **SANTA CLARA, CA 95050**
3069
Higher **Site 1 of 2 in cluster AJ**

LUST **S104541842**
Cortese **N/A**

LUST Region SC:
 Region: Santa Clara
 Case Rank: O2-3
 Transfer Date: Not reported
 Closed Date: Not reported
 SCVWD Id: 06S1W35K06f

CORTESE:
 Reg Id: 43-0496
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

AK146 **MBL INC**
ENE **3165 DE LA CRUZ BLVD**
1/2-1 **SANTA CLARA, CA 95052**
3118
Higher **Site 1 of 2 in cluster AK**

LUST **S105032496**
Cortese **N/A**

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number 43-0871
 Reg Board: San Francisco Bay Region
 Chemical: Diesel
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 1/6/1998
 Release Date: 1/10/1991
 Cleanup Fund Id : Not reported
 Discover Date : 1/28/1991
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 1/18/1991
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : Not reported
 Max MTBE GW : Not reported
 MTBE Tested: Not Required to be Tested.
 Priority: Not reported
 Local Case # : 06S1W26K03
 Beneficial: Not reported
 Staff : CTH
 GW Qualifies : Not reported

Confirm Leak: Not reported
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number

MBL INC (Continued)

S105032496

Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 4/16/1991
Stop Date : 1/28/1991
Work Suspended N
Responsible Party BLANK RP
RP Address: Not reported
Global Id: T0608500882
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2978.1919317144593624111352349
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0871
Entered Date: 01/18/1991
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 9000
Maximum Groundwater Impact: 1500
County : Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

CORTESE:

Reg Id: 43-0871
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AK147
ENE
1/2-1
3118
Higher

3175 DE LA CRUZ BLVD.
SANTA CLARA, CA 95054

Site 2 of 2 in cluster AK

CHMIRS S100278754
N/A

CHMIRS:

OES Control Number: 8800964 DOT ID: 1760
DOT Hazard Class: Corrosives
Chemical Name: CORROSIVE LIQUID
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: Not reported
Environmental Contamination: Air Property Use: Manufacturing
Incident Date: 23-MAR-88 Date Completed: 23-MAR-88

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

AL148 SAFETY-KLEEN
NNE 3461 WOODWARD AVE
1/2-1 SANTA CLARA, CA 95050
3137
Lower Site 1 of 2 in cluster AL

RCRIS-SQG 1000224242
FINDS CAD077187888
Cortese
RCRIS-TSD
CA SLIC
CORRACTS
CERC-NFRAP

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
 Non NPL Code: NFRAP
 Ownership Status: Private

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: PRELIMINARY ASSESSMENT
 Assessment: SITE INSPECTION

Completed: 05/01/1986
 Completed: 12/01/1987
 Completed: 05/01/1988
 Completed: 05/29/1990

CORRACTS Data:

EPA Id: CAD077187888
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 04/15/1992
 Corrective Action: CA750YE - Migration of Contaminated Groundwater under Control , Yes, Migration of Contaminated Groundwater Under Control has been verified

EPA Id: CAD077187888
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 05/01/1988
 Corrective Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority

EPA Id: CAD077187888
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 08/01/1994
 Corrective Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority

EPA Id: CAD077187888
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 03/18/1987
 Corrective Action: CA100 - RFI Imposition

EPA Id: CAD077187888

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SAFETY-KLEEN (Continued)

1000224242

Region: 9
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 03/18/1987
Corrective Action: CA150 - RFI Workplan Approved

The CORRACTS database contains 5 additional records for this site.
Please contact your EDR Account Executive for more information.

RCRIS Corrective Action Summary:

Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.
Event Date: 08/01/1994

Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
Event Date: 08/01/1994

Event: Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.
Event Date: 04/15/1992

Event: RFI Approved
Event Date: 09/29/1989

Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.
Event Date: 06/09/1989

Event: Stabilization Construction Completed
Event Date: 08/11/1988

Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.
Event Date: 05/01/1988

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SAFETY-KLEEN (Continued)

1000224242

Event: RFI Imposition
 Event Date: 03/18/1987

Event: RFI Workplan Approved
 Event Date: 03/18/1987

Event: Stabilization Measures Implemented, Primary measure is source removal and/or
 treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site
 treatment).
 Event Date: 03/31/1986

RCRIS:

Owner: SAFETY KLEEN CORP
 (312) 697-8460

EPA ID: CAD077187888

Contact: JEFFREY SIMPSON
 (312) 697-8460

Rank Status: 1
 Rank Date: 08/27/1992
 Classification: Handler transports wastes, but commercial status is unknown, TSDF
 Used Oil Recyc: No
 TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: Not reported
 Area of Violation: TSD-OTHER REQUIREMENTS
 Date Violation Determined: 04/26/1990
 Actual Date Achieved Compliance: 02-OCT-90

Enforcement Action: FINAL JUDICIAL ORDERS
 Enforcement Action Date: 05/10/1990
 Penalty Type: Not reported

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 08/27/1990
 Penalty Type: Not reported

Regulation Violated: Not reported
 Area of Violation: TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
 Date Violation Determined: 04/25/1989
 Actual Date Achieved Compliance: 26-JUN-89

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 05/18/1989
 Penalty Type: Not reported

Regulation Violated: Not reported
 Area of Violation: TSD-OTHER REQUIREMENTS
 Date Violation Determined: 04/14/1989
 Actual Date Achieved Compliance: 02-OCT-90

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 05/09/1989
 Penalty Type: Not reported

Enforcement Action: FINAL JUDICIAL ORDERS
 Enforcement Action Date: 05/10/1990
 Penalty Type: Not reported

Regulation Violated: Not reported
 Area of Violation: TSD-MANIFEST REQUIREMENTS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SAFETY-KLEEN (Continued)

1000224242

Date Violation Determined:	01/29/1987
Actual Date Achieved Compliance:	14-APR-89
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/22/1987
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS
Date Violation Determined:	01/29/1987
Actual Date Achieved Compliance:	02-OCT-90
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/22/1987
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	01/29/1987
Actual Date Achieved Compliance:	14-APR-89
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/22/1987
Penalty Type:	Not reported

There are 6 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	02-OCT-90
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	26-JUN-89
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	02-OCT-90
Compliance Evaluation Inspection	TSD-MANIFEST REQUIREMENTS	14-APR-89
	TSD-OTHER REQUIREMENTS	02-OCT-90
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	14-APR-89

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 AIRS Facility System (AIRS/AFS)
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CORTESE:

Reg Id: 3125
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

SLIC Region 2:

Facility ID:	43S0105	
Region:	2	
Facility Status:	Closed - No Further Action	Not reported
Staff:	JEB	Not reported
Last Site Update:	01/11/19	
NPL Status:	Not an NPL site	Discovery Date: 04/10/1984
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: No
Abate Method:	Not reported	Substance: Not reported
Case Type:	TK	Sample Date: 12/18/1989
Contamination:	UNDERGROUND SOLVENT STOR. TANK, 2 @ 1M GL EA/SPILL	
Lead:	2189.8166 RWQCB	
Contamination Level:	750	

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SAFETY-KLEEN (Continued)

1000224242

Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Yes
 Soil Removal or Contaminant Action Started: 04/01/1986
 Soil Removal or Contaminant Action Completed: 11/1/91
 On-Site Groundwater Extraction or Containment is Needed: Yes
 On-Site Groundwater Extraction or Containment Started: 08/22/1988
 Off-Site Groundwater Extraction or Containment is Needed: Not Determined
 Off-Site Groundwater Extraction or Containment Started: 11/1/91
 Length of Contamination Plume (Feet): 300
 Depth of Contamination Plume (Feet): 20
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date: 5/1/84
 Latitude/Longitude: 37 / -122
 Flow Rate: 1
 Flow Date: 11/01/1991
 Percent of Contaminants Contained: 3
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes
 Begun Remediation: Yes
 Completed Remediation: Yes
 Submitted Remediation Plan: Yes
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: SOLVENT RECYCLING (NEW TENANT/OWNER)
 Comment: Not reported

AL149
 NNE
 1/2-1
 3137
 Lower

SAFETY-KLEEN CORPORATION
3461 WOODWARD AVENUE
SANTA CLARA, CA 95054

Cal-Sites S100183057
 N/A

Site 2 of 2 in cluster AL

CAL-SITES:

Facility ID: 43280128
 Status: REFR - DOES NOT REQUIRE DTSC ACTION. REFERRED TO RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) LEAD
 Status Date: 06/08/1994
 Lead: Not reported
 Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RCRA
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 28 MANU - CHEMICALS & ALLIED PRODUCTS
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: Not reported
 Access: Not reported
 Cortese: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SAFETY-KLEEN CORPORATION (Continued)

S100183057

Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

150
 West
 1/2-1
 3156
 Higher

**3033 SCOTT BLVD.
 SANTA CLARA, CA 95054**

CHMIRS S100219736
 N/A

CHMIRS:
 OES Control Number: 9010398 DOT ID: 1830
 DOT Hazard Class: Corrosives
 Chemical Name: ACID, SULFURIC
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 10
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 19-APR-90 Date Completed: 19-APR-90

AJ151
 SE
 1/2-1
 3179
 Higher

**CALIFORNIA COMPACT RENT A
 2470 DE LA CRUZ
 SANTA CLARA, CA**

LUST S103880774
 Cortese N/A

Site 2 of 2 in cluster AJ

LUST Region SC:
 Region: Santa Clara
 Case Rank: O231 Closed Date: 06/27/2000
 Transfer Date: Not reported SCVWD Id: 06S1W35L02f

CORTESE:
 Reg Id: 43-0228
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

152
 WNW
 1/2-1
 3216
 Higher

**EXXON
 2181 LAURELWOOD RD
 SANTA CLARA, CA 95054**

LUST S105034162
 Cortese N/A

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0524
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

EXXON (Continued)

S105034162

Case Type: Other ground water affected -
Status: Post remedial action monitoring in progress
County: Santa Clara
Abate Method: No Action Taken - no action has as yet been taken at the site
Review Date: Not reported Confirm Leak: Not reported
Workplan: 7/17/1987 Prelim Assess: 7/17/1987
Pollution Char: Not reported Remed Plan: Not reported
Remed Action: 1/2/1965 Monitoring: 1/2/1965
Close Date: Not reported
Release Date: 1/30/1987
Cleanup Fund Id : Not reported
Discover Date : 1/30/1987
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 2/10/1987
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : 9/30/1999
Max MTBE GW : 1010
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case # : 06S1W27F01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 3/6/2001
Stop Date : 1/30/1987
Work Suspended : N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500568
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 4157.3808970886465505901407942
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0524
Entered Date: 02/10/1987
Facility Status: Post remedial action monitoring in progress
Maximum Soil Concentration: 1000

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

EXXON (Continued)

S105034162

Maximum Groundwater Impact: 45000
 County : Santa Clara
 Current Benzene: 16
 MTBE Detected in GW: 1010
 MTBE Detected in Soil: Not reported
 MTBE: 150
 MTBE Qualify: Not reported

CORTESE:

Reg Id: 43-0524
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

AM153
 SE
 1/2-1
 3226
 Higher

RELIANCE STEEL & ALUMINUM COMPANY
 2460 DE LA CRUZ BLVD
 SANTA CLARA, CA 95050

HAZNET S101304234
LUST N/A
 Cortese

Site 1 of 3 in cluster AM

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1108
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)

Review Date:	Not reported	Confirm Leak:	Not reported
Workplan:	6/6/1984	Prelim Assess:	6/6/1984
Pollution Char:	Not reported	Remed Plan:	Not reported
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	6/29/1995		
Release Date:	1/30/1986		
Cleanup Fund Id :	Not reported		
Discover Date :	1/30/1986		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	7/10/1989		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.		
Priority:	Not reported		
Local Case # :	06S1W35L01		
Beneficial:	Not reported		
Staff :	CTH		
GW Qualifies :	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

RELIANCE STEEL & ALUMINUM COMPANY (Continued)

S101304234

Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 7/10/1995
Stop Date : 1/30/1986
Work Suspended : N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501100
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mibe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3405.3440041220736053783603958
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1108
Entered Date: 07/10/1989
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 8420
Maximum Groundwater Impact: 107000
County : Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

HAZNET:

Gepaid: CAC001024392
Tepaid: CAD004771168
Gen County: Santa Clara
Tsd County: San Francisco
Tons: 2.0750
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: RELIANCE STEEL & ALUMINUM
Telephone: (510) 829-0661
Mailing Address: 2460 DE LA CRUZ BLVD
SANTA CLARA, CA 95050
County: Santa Clara

CORTESE:

Reg Id: 43-1108
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AM154 INTERSTATE BRANDS CORPORATION
SE 2450 DE LA CRUZ
1/2-1 SANTA CLARA, CA 95120
3268
Higher Site 2 of 3 in cluster AM

HAZNET S103970097
LUST N/A
Cortese

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

INTERSTATE BRANDS CORPORATION (Continued)

S103970097

State LUST:
Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-2341
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 10/7/1999
Release Date: 1/4/1999
Cleanup Fund Id: Not reported
Discover Date: 1/14/1999
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 10/20/1999
Funding: Not reported
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: Not reported
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date: 1/2/1965
Max MTBE GW: 0
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: 14-485
Beneficial: Not reported
Staff: CTH
GW Qualifies: Not reported
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 10/20/1999
Stop Date: 1/14/1999
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608502150
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 5212.4429188187495131927019662
Waste Discharge Global ID: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

INTERSTATE BRANDS CORPORATION (Continued)

S103970097

Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
 Facility Id: 43-2341
 Entered Date: 10/20/1999
 Facility Status: Signed off, remedial action completed or deemed unnecessary
 Maximum Soil Concentration: 0
 Maximum Groundwater Impact: 85000
 County: Santa Clara
 Current Benzene: 0
 MTBE Detected in GW: No
 MTBE Detected in Soil: Not reported
 MTBE: 0
 MTBE Qualify: ND

LUST Region SC:

Region: Santa Clara
 Case Rank: O3-2
 Transfer Date: Not reported
 Closed Date: 10/07/1999
 SCVWD Id: 06S1W35L08f

HAZNET:

Gepaid: CAL000008592
 Tepaid: CAD980887418
 Gen County: Santa Clara
 Tsd County: 1
 Tons: .2710
 Category: Waste oil and mixed oil
 Disposal Method: Recycler
 Contact: CONTINENTAL BAKING
 Telephone: (415) 552-0950
 Mailing Address: PO BOX 2709
 POMONA, CA 91769 - 2709
 County: Santa Clara

CORTESE:

Reg Id: 43-2341
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AM155
 SE
 1/2-1
 3268
 Higher**

**2450 DELA CRUZ BLVD.
 SANTA CLARA, CA 95050**

Site 3 of 3 in cluster AM

**CHMIRS S100220331
 N/A**

CHMIRS:

OES Control Number: 9012437 DOT ID: 1993
 DOT Hazard Class: Flammable liquid
 Chemical Name: DIESEL FUEL
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 40
 Environmental Contamination: Ground Property Use: Mercantile, Business
 Incident Date: 16-AUG-90 Date Completed: 16-AUG-90

**AN156
 SW
 1/2-1
 3332
 Higher**

**STREET CORPORATION YARD
 1700 WALSH AVE
 SANTA CLARA, CA**

Site 1 of 2 in cluster AN

**Cortese S101309473
 N/A**

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

STREET CORPORATION YARD (Continued)

S101309473

CORTESE:
 Reg Id: 43-1676
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

157
 South
 1/2-1
 3344
 Higher

PACIFIC NURSERY POTS INC
 1015 MARTIN AVE
 SANTA CLARA, CA 95050

RCRIS-SQG 1000250555
FINDS CAD009166984
LUST
 Cortese
CERC-NFRAP
HIST UST

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
 Non NPL Code: NFRAP
 Ownership Status: Unknown

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT

Completed: 05/01/1986

Completed: 11/01/1987

RCRIS:

Owner: PACIFIC NURSERY POTS INC.
 (415) 555-1212
 EPA ID: CAD009166984
 Contact: ENVIRONMENTAL MANAGER
 (408) 727-3585

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1787
 Reg Board: San Francisco Bay Region
 Chemical: Misc. Motor Vehicle Fuels
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Undefined
 Status: Preliminary site assessment workplan submitted
 County: Santa Clara
 Abate Method: No Action Taken - no action has as yet been taken at the site
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 12/3/2001
 Release Date: 1/8/1990
 Cleanup Fund Id: Not reported
 Discover Date: 1/8/1990
 Enforcement Dt: Not reported

Confirm Leak: Not reported
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

PACIFIC NURSERY POTS INC (Continued)

1000250555

Enf Type: Not reported
Enter Date : 7/1/1991
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case # : 06S1W34H02
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 12/16/1993
Stop Date : 1/8/1990
Work Suspended N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501716
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 4498.8903127439556233759092722
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Cross Street: Not reported
Qty Leaked: Not reported
Case Number 43-2151
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency : 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: Pump and Treat Ground Water - generally employed to remove dissolved
contaminants

Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 9/29/1998
Release Date: 1/10/1996

Confirm Leak: Not reported
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC NURSERY POTS INC (Continued)

1000250555

Cleanup Fund Id : Not reported
Discover Date : 1/10/1996
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 11/7/1996
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : 1/2/1965
Max MTBE GW : 7
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case # : 07S1W34H03
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 9/29/1998
Stop Date : 1/10/1996
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608501975
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3898.6069873861324100229864101
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: U-31
Transfer Date: Not reported
Closed Date: 12/03/2001
SCVWD Id: 06S1W34H02f

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: 09/29/1998
SCVWD Id: 07S1W34H03f

CORTESE:

Reg Id: 43-1787
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 43-2151
Region: CORTESE

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

PACIFIC NURSERY POTS INC (Continued)

1000250555

Reg By: Leaking Underground Storage Tanks

UST HIST:

Facility ID: 2906
Tank Num: 1
Tank Capacity: 10000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Leak Detection:
Contact Name: RICK TERSINI
Total Tanks: 6
Facility Type: 2
Container Num: 1
Year Installed: 1975
Tank Construction: 1/4" inches
Telephone: (408) 727-3585
Region: STATE
Other Type: MANUFACTURING

Facility ID: 2906
Tank Num: 2
Tank Capacity: 3500
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Leak Detection: None
Contact Name: RICK TERSINI
Total Tanks: 6
Facility Type: 2
Container Num: 2
Year Installed: 1963
Tank Construction: 3/8" inches
Telephone: (408) 727-3585
Region: STATE
Other Type: MANUFACTURING

Facility ID: 2906
Tank Num: 3
Tank Capacity: 1000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Leak Detection: Stock Inventor
Contact Name: RICK TERSINI
Total Tanks: 6
Facility Type: 2
Container Num: 3
Year Installed: 1963
Tank Construction: 1/4" inches
Telephone: (408) 727-3585
Region: STATE
Other Type: MANUFACTURING

Facility ID: 2906
Tank Num: 4
Tank Capacity: 300
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Leak Detection: Stock Inventor
Contact Name: RICK TERSINI
Total Tanks: 6
Facility Type: 2
Container Num: 4
Year Installed: 1963
Tank Construction: 1/4 inches
Telephone: (408) 727-3585
Region: STATE
Other Type: MANUFACTURING

Facility ID: 2906
Tank Num: 5
Tank Capacity: 10000
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: GW Monitoring Well
Contact Name: RICK TERSINI
Total Tanks: 6
Facility Type: 2
Container Num: 5
Year Installed: 1975
Tank Construction: 1/4" inches
Telephone: (408) 727-3585
Region: STATE
Other Type: MANUFACTURING

Facility ID: 2906
Tank Num: 6
Tank Capacity: 10000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Num: 6
Year Installed: 1975
Tank Construction: 1/4" inches

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

PACIFIC NURSERY POTS INC (Continued)

1000250555

Leak Detection:	Stock Inventor	Telephone:	(408) 727-3585
Contact Name:	RICK TERSINI	Region:	STATE
Total Tanks:	6	Other Type:	MANUFACTURING
Facility Type:	2		

158
NW
1/2-1
3348
Higher

SAFEWAY STEEL COMPANY
3601 THOMAS RD
SANTA CLARA, CA 95054

LUST S100235579
Cortese N/A

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	1/17/1990
Case Number:	43-1163	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	43099		
Case Type:	Other ground water affected		
Status:	Pollution characterization		
County:	Santa Clara		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Review Date:	Not reported		
Workplan:	1/17/1990		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	Not reported		
Release Date:	2/12/1990		
Cleanup Fund Id :	Not reported		
Discover Date :	12/13/1989		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	2/22/1990		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	1/2/1965		
Max MTBE GW :	100		
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected		
Priority:	Not reported		
Local Case # :	06S1W27B04		
Beneficial:	Not reported		
Staff :	CTH		
GW Qualifies :	Not reported		
Max MTBE Soil :	Not reported		
Soil Qualifies :	Not reported		
Hydr Basin #:	Not reported		
Operator :	Not reported		
Oversight Prgm:	Local Oversight Program UST		
Oversight Prgm :	LOP		
Review Date :	2/20/1990		
Stop Date :	12/13/1989		
Work Suspended :	N		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SAFEWAY STEEL COMPANY (Continued)

S100235579

Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608501153
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 3247.8002573993832901809229153
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1163
Entered Date: 02/22/1990
Facility Status: Pollution characterization
Maximum Soil Concentration: 6100
Maximum Groundwater Impact: 9999999
County: Santa Clara
Current Benzene: 3500
MTBE Detected in GW: 100
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W27B04f

CORTESE:

Reg Id: 43-1163
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

159
SW
1/2-1
3368
Higher

2750 SCOTT
SANTA CLARA, CA 95050

CHMIRS S100219330
N/A

CHMIRS:

OES Control Number: 9000705 DOT ID: Not reported
DOT Hazard Class: Not Reported
Chemical Name: SODIUM HYDROXIDE
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: Not reported
Environmental Contamination: Ground Property Use: Manufacturing
Incident Date: 08-MAR-90 Date Completed: 08-MAR-90

160
NNW
1/2-1
3382
Same

AIR PRODUCTS MANUFACTURING CORPORATION
1515 NORMAN AVE
SANTA CLARA, CA 95054

HAZNET 1000725915
Cortese N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

AIR PRODUCTS MANUFACTURING CORPORATION (Continued)

1000725915

HAZNET:

Gepaid: CAD010941565
Tepaid: CAD053044053
Gen County: Santa Clara
Tsd County: 1
Tons: .3793
Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method: Transfer Station
Contact: AIR PRODUCTS AND CHEMICALS INC
Telephone: (610) 481-5154
Mailing Address: 1515 NORMAN AVE
SANTA CLARA, CA 95054 - 2029
County: Santa Clara

Gepaid: CAD010941565
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: 3.1275
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: AIR PRODUCTS AND CHEMICALS INC
Telephone: (610) 481-5154
Mailing Address: 1515 NORMAN AVE
SANTA CLARA, CA 95054 - 2029
County: Santa Clara

Gepaid: CAD010941565
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .1459
Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Contact: AIR PRODUCTS AND CHEMICALS INC
Telephone: (610) 481-5154
Mailing Address: 1515 NORMAN AVE
SANTA CLARA, CA 95054 - 2029
County: Santa Clara

Gepaid: CAD010941565
Tepaid: CAL000048571
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 2.2935
Category:
Disposal Method: Recycler
Contact: AIR PRODUCTS AND CHEMICALS INC
Telephone: (610) 481-5154
Mailing Address: 1515 NORMAN AVE
SANTA CLARA, CA 95054 - 2029
County: Santa Clara

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

AIR PRODUCTS MANUFACTURING CORPORATION (Continued)

1000725915

Gepaid: CAD010941565
 Tepad: CAL000048571
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: 1.4052
 Category: Waste oil and mixed oil
 Disposal Method: Recycler
 Contact: AIR PRODUCTS AND CHEMICALS INC
 Telephone: (610) 481-5154
 Mailing Address: 1515 NORMAN AVE
 SANTA CLARA, CA 95054 - 2029
 County Santa Clara

The CA HAZNET database contains 35 additional records for this site.
 Please contact your EDR Account Executive for more information.

CORTESE:
 Reg Id: 43-0037
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AO161
 NNW
 1/2-1
 3386
 Lower**

**PRO FLAME INC
 1390 NORMAN AVE
 SANTA CLARA, CA**

**Cortese S101309455
 N/A**

Site 1 of 2 in cluster AO

CORTESE:
 Reg Id: 43-1079
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AP162
 West
 1/2-1
 3388
 Higher**

**VARIAN ASSOCIATES
 3100 JAY ST
 SANTA CLARA, CA 95050**

**Cal-Sites 1000245626
 RCRIS-SQG CAT000617605
 FINDS
 CERC-NFRAP**

Site 1 of 2 in cluster AP

CERCLIS-NFRAP Classification Data:
 Site Incident Category: Not reported
 Non NPL Code: NFRAP
 Ownership Status: Private
CERCLIS-NFRAP Assessment History:
 Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT
CERCLIS-NFRAP Alias Name(s):
 PREVIOUS EPA ID# CAD982400129

Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Completed: 04/01/1988
Completed: 02/25/1991

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

VARIAN ASSOCIATES (Continued)

1000245626

RCRIS:

Owner: VARIAN ASSOCIATES INC
 (415) 493-4000
 EPA ID: CAT000617605
 Contact: DENISE KATO
 (650) 424-5471

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 AIRS Facility System (AIRS/AFS)
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CAL-SITES:

Facility ID: 43480001
 Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
 Status Date: 03/31/1995
 Lead: Not reported
 Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 48 COMMUNICATIONS
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: Not reported
 Access: Not reported
 Cortese: Not reported
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: 22
 State Senate District: 13

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

AP163 SCR-VARIAN-3100 JAY STREE
 West 3100 JAY
 1/2-1 SANTA CLARA, CA 95050
 3388
 Higher Site 2 of 2 in cluster AP

Cortese S101542372
 CA SLIC N/A

CORTESE:
 Reg Id: 2 438190N02

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

SCR-VARIAN-3100 JAY STREE (Continued)

S101542372

Region: CORTESE
 Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

SLIC Region 2:

Facility ID:	43S0173	
Region:	2	
Facility Status:	Active	Not reported
Staff:	VAC	Not reported
Last Site Update:	01/30/19	
NPL Status:	Not an NPL site	Discovery Date: 07/31/1984
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: YES
Abate Method:	Not reported	Substance: Not reported
Case Type:	NT	Sample Date: 12/10/1993
Contamination:	TCA SPILL RESULTING FROM ABOVE GROUND PIPE RUPTURE	
Lead:	2189.8190 RWQCB	
Contamination Level:	NOT SAMPLED	
Number of Municipal Wells Contaminated by Site:	0	
Number of Private Wells Contaminated by Site:	0	
Soil Removal Action Taken/Needed:	Yes	
Soil Removal or Contaminant Action Started:	08/01/1985	
Soil Removal or Contaminant Action Completed:	12/1/85	
On-Site Groundwater Extraction or Containment is Needed:	Yes	
On-Site Groundwater Extraction or Containment Started:	03/30/1985	
Off-Site Groundwater Extraction or Containment is Needed:	No	
Off-Site Groundwater Extraction or Containment Started:		
Length of Contamination Plume (Feet):	150	
Depth of Contamination Plume (Feet):	20	
Wells Closed Due To Contamination of Site:	NA	
Date of Wells Closure:		
Nearest Public or Private Drinking Water Well (Feet):	0	
Under Jurisdiction of Lead Agency Date:	9/14/84	
Latitude/Longitude:	37 / -122	
Flow Rate:	9	
Flow Date:	07/31/1991	
Percent of Contaminants Contained:	3	
Contaminant Type:		
EPA ID:		
Stages of Site Investigation Process Initiated:		
Begun Characterization :	Yes	
Completed Characterization :	Yes	
Begun Remediation:	Yes	
Completed Remediation:	Yes	
Submitted Remediation Plan:	No	
Approved Remediation Plan:	No	
Begun Final Remedial Action:	No	
Completed Final Remedial Action:	No	
Facility Desc:	ELECTRONICS PLANT	
Comment:	Not reported	

AO164
 NNW
 1/2-1
 3390
 Lower

1375 NORMAN
 SANTA CLARA, CA 95054

Site 2 of 2 in cluster AO

CORTESE:
 Reg Id: 43-0661

CHMIRS S100222365
 Cortese N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

(Continued)

S100222365

Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

CHMIRS:
 OES Control Number: 9991167 DOT ID: 1789
 DOT Hazard Class: Corrosives
 Chemical Name: ACID, HYDROCHLORIC
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 1
 Environmental Contamination: None Reported Property Use: Manufacturing
 Incident Date: 14-JUL-88 Date Completed: 14-JUL-88

165
 SE
 1/2-1
 3390
 Higher

CARLETON-JAMES PRESS
 2433 DE LA CRUZ BLVD
 SANTA CLARA, CA 00000

HAZNET S101304233
 LUST N/A
 Cortese

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0351
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Review Date: 12/6/1990	Confirm Leak: 12/6/1990
Workplan: 12/7/1993	Prelim Assess: 12/7/1993
Pollution Char: Not reported	Remed Plan: Not reported
Remed Action: Not reported	Monitoring: Not reported

Close Date: 7/23/1998
 Release Date: 5/29/1990
 Cleanup Fund Id: Not reported
 Discover Date: 5/29/1990
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 6/21/1990
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: Not reported
 Max MTBE GW: Not reported
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
 Priority: Not reported
 Local Case #: 06S1W35K01
 Beneficial: Not reported
 Staff: CTH
 GW Qualifies: Not reported
 Max MTBE Soil: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

CARLETON-JAMES PRESS (Continued)

S101304233

Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 7/23/1998
Stop Date : 5/29/1990
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500407
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3335.6849752586262304042259789
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0351
Entered Date: 06/21/1990
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 220
Maximum Groundwater Impact: 25000
County : Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O131
Transfer Date: Not reported
Closed Date: 07/23/1998
SCVWD Id: 06S1W35K01f

HAZNET:

Gepaid: CAL000050216
Tepaid: CAD981161367
Gen County: Santa Clara
Tsd County: Marin
Tons: .1876
Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: 2433 DE LA CRUZ BLVD
SANTA CLARA, CA 00000
County Santa Clara

CORTESE:

Reg Id: 43-0351
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID Direction Distance Distance (ft.) Elevation	Site	Database(s)	EDR ID Number EPA ID Number
--	------	-------------	--------------------------------

166 NNW 1/2-1 3393 Same	J P MACHINE MANUFACTURING 1600 NORMAN AVE SANTA CLARA, CA 95054	HAZNET Cortese	S103971295 N/A
-------------------------------------	--	-------------------	-------------------

HAZNET:

Gepaid: CAL000189701
 Tepaid: CAL000161741
 Gen County: Santa Clara
 Tsd County: 1
 Tons: .1668
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: YOUNG OH PAK/PRES OWNER
 Telephone: (000) 000-0000
 Mailing Address: 1600 NORMAN AVE
 SANTA CLARA, CA 95054
 County: Santa Clara

CORTESE:

Reg Id: 43-1887
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

AN167 SW 1/2-1 3408 Higher	C & N PUMP 1745 WALSH AVE SANTA CLARA, CA 95050 Site 2 of 2 in cluster AN	LUST Cortese	S103880765 N/A
--	---	-----------------	-------------------

LUST Region SC:

Region:	Santa Clara	Closed Date:	08/16/1996
Case Rank:	O131	SCVWD Id:	06S1W34G02f
Transfer Date:	Not reported		

CORTESE:

Reg Id: 43-0222
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

AQ168 ENE 1/2-1 3431 Higher	UNOCAL SERVICE STATION #6429 2591 SEABOARD AVE SAN JOSE, CA 95131 Site 1 of 2 in cluster AQ	HAZNET Cortese	S100947572 N/A
---	---	-------------------	-------------------

HAZNET:

Gepaid: CAD982058612
 Tepaid: CAD083166728
 Gen County: Santa Clara
 Tsd County: Stanislaus
 Tons: 1.5011
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: UNION OIL COMPANY OF CALIFORNI
 Telephone: (714) 428-6560
 Mailing Address: PO BOX 25376
 SANTA ANA, CA 92799 - 5376
 County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

UNOCAL SERVICE STATION #6429 (Continued)

S100947572

Gepaid: CAD982058612
Tepaid: CAD053166728
Gen County: Santa Clara
Tsd County: 0
Tons: .0417
Category: Unspecified oil-containing waste
Disposal Method: Not reported
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Santa Clara

Gepaid: CAD982058612
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .4586
Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Santa Clara

Gepaid: CAD982058612
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .3710
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Santa Clara

Gepaid: CAD982058612
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: 2.0641
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Not reported
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Santa Clara

The CA HAZNET database contains 3 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 43-1548
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID Direction Distance Distance (ft.) Elevation	Site	Database(s)	EDR ID Number EPA ID Number
--	------	-------------	--------------------------------

AR169 NNE 1/2-1 3443 Lower	TRANSCON TRUCK LINES 650 ALDO AVE SANTA CLARA, CA Site 1 of 2 in cluster AR CORTESE: Reg Id: 43-0416 Region: CORTESE Reg By: Leaking Underground Storage Tanks	Cortese	S100235480 N/A
--	--	---------	-------------------

AR170 NNE 1/2-1 3443 Lower	MUMFORD PROPERTY 651 ALDO SANTA CLARA, CA 95054 Site 2 of 2 in cluster AR CORTESE: Reg Id: 2787 Region: CORTESE Reg By: Leaking Underground Storage Tanks	Cortese	S105026423 N/A
--	---	---------	-------------------

171 NNW 1/2-1 3451 Lower	FABRICATED CIRCUITS INC 1196 NORMAN AVE SANTA CLARA, CA 95050	FINDS RCRIS-LQG RCRIS-TSD CORRACTS CERC-NFRAP	1000360797 CAD082898180
--------------------------------------	--	---	----------------------------

CERCLIS-NFRAP Classification Data: Site Incident Category: Not reported Non NPL Code: DR Ownership Status: Private		Federal Facility: Not a Federal Facility NPL Status: Not on the NPL
CERCLIS-NFRAP Assessment History: Assessment: DISCOVERY Assessment: PRELIMINARY ASSESSMENT		Completed: 03/01/1991 Completed: 09/12/1991

CORRACTS Data:

EPA Id:	CAD082898180
Region:	9
State:	Not reported
Area Name:	ENTIRE FACILITY
Original Scheduled Date:	Not reported
New Scheduled Date:	Not reported
Actual Date:	08/30/1991
Corrective Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

EPA Id:	CAD082898180
Region:	9
State:	Not reported
Area Name:	ENTIRE FACILITY
Original Scheduled Date:	Not reported
New Scheduled Date:	Not reported
Actual Date:	12/26/1991
Corrective Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FABRICATED CIRCUITS INC (Continued)

1000360797

RCRIS Corrective Action Summary:

Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;
Event Date: 06/30/1999
Event: CA Prioritization, Facility or area was assigned a low corrective action
priority.
Event Date: 12/26/1991
Event: CA Prioritization, Facility or area was assigned a low corrective action
priority.
Event Date: 08/30/1991

RCRIS:

Owner: FABRICATED CIRCUITS INC.
(408) 988-7775
EPA ID: CAD082898180
Contact: ENVIRONMENTAL MANAGER
(408) 988-7775

Rank Status: 3
Rank Date: 08/27/1992
Classification: Large Quantity Generator, TSD
Used Oil Recyc: No
TSD Activities: Not reported

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	GENERATOR-OTHER REQUIREMENTS
Date Violation Determined:	04/22/1991
Actual Date Achieved Compliance:	05-FEB-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/19/1991
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-LAND BAN REQUIREMENTS
Date Violation Determined:	06/27/1989
Actual Date Achieved Compliance:	25-SEP-91
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/11/1989
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-LAND BAN REQUIREMENTS
Date Violation Determined:	06/27/1989
Actual Date Achieved Compliance:	25-SEP-91
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/11/1989
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS
Date Violation Determined:	06/27/1989
Actual Date Achieved Compliance:	28-SEP-91
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/11/1989
Penalty Type:	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

FABRICATED CIRCUITS INC (Continued)

1000360797

Regulation Violated:	Not reported
Area of Violation:	TSD-MANIFEST REQUIREMENTS
Date Violation Determined:	06/27/1989
Actual Date Achieved Compliance:	25-SEP-91
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/11/1989
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS
Date Violation Determined:	06/18/1987
Actual Date Achieved Compliance:	28-SEP-91
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/07/1987
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	04/22/1988
Penalty Type:	Final Monetary Penalty
Enforcement Action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	08/31/1988
Penalty Type:	Final Monetary Penalty
Enforcement Action:	CIVIL ACTION FOR COMPLIANCE
Enforcement Action Date:	08/01/1991
Penalty Type:	Final Monetary Penalty

There are 6 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-OTHER REQUIREMENTS	05-FEB-92
Compliance Evaluation Inspection	TSD-LAND BAN REQUIREMENTS	25-SEP-91
	GENERATOR-LAND BAN REQUIREMENTS	25-SEP-91
	TSD-OTHER REQUIREMENTS	28-SEP-91
	TSD-MANIFEST REQUIREMENTS	25-SEP-91
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	28-SEP-91

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

AQ172
 East
 1/2-1
 3462
 Higher

ESREY SUPPLY COMPANY
2578 SEABOARD AVE
SAN JOSE, CA 95131

LUST S100235347
 Cortese N/A

Site 2 of 2 in cluster AQ

State LUST:

Cross Street:	Not reported
Qty Leaked:	Not reported
Case Number	43-0510
Reg Board:	San Francisco Bay Region
Chemical:	Xylene
Lead Agency:	Local Agency
Local Agency :	43099
Case Type:	Soil only
Status:	Signed off, remedial action completed or deemed unnecessary

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ESREY SUPPLY COMPANY (Continued)

S100235347

County: Santa Clara
Abate Method: No Action Taken - no action has as yet been taken at the site
Review Date: Not reported Confirm Leak: Not reported
Workplan: Not reported Prelim Assess: Not reported
Pollution Char: Not reported Remed Plan: Not reported
Remed Action: Not reported Monitoring: Not reported
Close Date: 6/3/1996
Release Date: 1/26/1990
Cleanup Fund Id : Not reported
Discover Date : 1/23/1990
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 9/14/1990
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case # : 06S1E26K02
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin # : Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 9/14/1990
Stop Date : 1/23/1990
Work Suspended : N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500555
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 4640.3394365648098475140792772
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0510
Entered Date: 09/14/1990
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 440
Maximum Groundwater Impact: 0
County : Santa Clara

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

ESREY SUPPLY COMPANY (Continued)

S100235347

Current Benzene: Not reported
 MTBE Detected in GW: Not reported
 MTBE Detected in Soil: Not reported
 MTBE: 0
 MTBE Qualify: Not reported

LUST Region SC:

Region:	Santa Clara	Closed Date:	06/03/1996
Case Rank:	O331	SCVWD Id:	06S1W26K02f
Transfer Date:	Not reported		

CORTESE:

Reg Id: 43-0510
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AS173
 NW
 1/2-1
 3488
 Higher**

**EXPRESS-IT COURIER SERVICES
 1855 NORMAN AVE
 SANTA CLARA, CA 95054**

**HAZNET S103637820
 Cortese N/A**

Site 1 of 2 in cluster AS

HAZNET:

Gepaid: CAL000112505
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .6880
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: EXPRESS-IT COURIERS
 Telephone: (408) 988-1200
 Mailing Address: 1855 NORMAN AVE
 SANTA CLARA, CA 95054 - 2029
 County Santa Clara

CORTESE:

Reg Id: 43-0738
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

**AS174
 NW
 1/2-1
 3513
 Higher**

**3555 THOMAS ROAD MONTAGUE
 SANTA CLARA, CA 95050**

**CHMIRS S100277751
 N/A**

Site 2 of 2 in cluster AS

CHMIRS:

OES Control Number:	9117500	DOT ID:	Not reported
DOT Hazard Class:	Not Reported		
Chemical Name:	DIESEL		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	50
Environmental Contamination:	Ground	Property Use:	Industrial, Utility
Incident Date:	10-JUN-91	Date Completed:	10-JUN-91

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s)
 EDR ID Number
 EPA ID Number

175 LEVIN WESTERN METALS & ST Cortese S102432623
 South 2556 LAFAYETTE N/A
 1/2-1 SANTA CLARA, CA
 3524
 Higher

CORTESE:
 Reg Id: 43-0814
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

176 J & B ENTERPRISES FINDS 1000112713
 NE 342 LAUREL WOOD RD. RCRIS-LQG CAD069138899
 1/2-1 SANTA CLARA, CA 95050 CORRACTS
 3651 CERC-NFRAP
 Same

CERCLIS-NFRAP Classification Data:
 Site Incident Category: Not reported Federal Facility: Not a Federal Facility
 Non NPL Code: DR NPL Status: Not on the NPL
 Ownership Status: Private
 CERCLIS-NFRAP Assessment History:
 Assessment: DISCOVERY Completed: 04/08/1992
 Assessment: PRELIMINARY ASSESSMENT Completed: 06/22/1992

CORRACTS Data:

EPA Id: CAD069138899
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 06/20/1992
 Corrective Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

EPA Id: CAD069138899
 Region: 9
 State: Not reported
 Area Name: ENTIRE FACILITY
 Original Scheduled Date: Not reported
 New Scheduled Date: Not reported
 Actual Date: 06/25/1992
 Corrective Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

RCRIS Corrective Action Summary:

Event: CA Prioritization, Facility or area was assigned a low corrective action priority.
 Event Date: 06/25/1992

Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
 Event Date: 06/25/1992

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

J & B ENTERPRISES (Continued)

1000112713

Event: CA Prioritization, Facility or area was assigned a low corrective action priority.
 Event Date: 06/20/1992

RCRIS:

Owner: J&B ENTERPRISES
 (408) 988-7900
 EPA ID: CAD069138899
 Contact: ENVIRONMENTAL MANAGER
 Rank Status: 2
 Rank Date: 08/27/1992
 Classification: Large Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D002	15068.54	D003	206051.09
D004	237458.27	D006	236866.27
D007	205562.43	D008	237791.27
D011	26742.50	F006	624.00
F007	624.00	F008	624.00
F009	624.00		

Violation Status: Violations exist

Regulation Violated:	264.10-18.B
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	08/08/2000
Actual Date Achieved Compliance:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/03/2000
Penalty Type:	Not reported
Regulation Violated:	264.10-18.B
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	04/12/1995
Actual Date Achieved Compliance:	25-APR-95
Regulation Violated:	268.7
Area of Violation:	GENERATOR-LAND BAN REQUIREMENTS
Date Violation Determined:	06/18/1993
Actual Date Achieved Compliance:	25-APR-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/18/1993
Penalty Type:	Not reported
Regulation Violated:	264.140-150.H
Area of Violation:	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
Date Violation Determined:	06/18/1993
Actual Date Achieved Compliance:	25-APR-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/18/1993
Penalty Type:	Not reported
Regulation Violated:	264.10-18.B
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

J & B ENTERPRISES (Continued)

1000112713

Date Violation Determined: 11/13/1991
 Actual Date Achieved Compliance: 30-DEC-92

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 04/23/1993
 Penalty Type: Not reported

Regulation Violated: 264.140-150.H
 Area of Violation: TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
 Date Violation Determined: 11/13/1991
 Actual Date Achieved Compliance: 30-DEC-92

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 04/23/1993
 Penalty Type: Not reported

Regulation Violated: 264.110-120.G
 Area of Violation: TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
 Date Violation Determined: 11/13/1991
 Actual Date Achieved Compliance: 30-DEC-92

Enforcement Action: WRITTEN INFORMAL
 Enforcement Action Date: 04/23/1993
 Penalty Type: Not reported

There are 7 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	25-APR-95
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	25-APR-95
Compliance Evaluation Inspection	GENERATOR-LAND BAN REQUIREMENTS	25-APR-95
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	25-APR-95
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	30-DEC-92
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	30-DEC-92
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	30-DEC-92

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Biennial Reporting System (BRS)
 Facility Registry System (FRS)
 National Emissions Trends (NET)
 National Toxics Inventory (NTI)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

AT177
 NNE
 1/2-1
 3679
 Lower

555 ALDO AVENUE
 SANTA CLARA, CA 95054

CHMIRS S100220254
 N/A

Site 1 of 3 in cluster AT

CHMIRS:

OES Control Number: 9012205 DOT ID: 1295
 DOT Hazard Class: Not Reported
 Chemical Name: TRICHLOROSILANE
 Extent of Release: Not reported
 CAS Number: 10025-78-2 Quantity Released: 2
 Environmental Contamination: Air Property Use: Manufacturing
 Incident Date: 02-AUG-90 Date Completed: 02-AUG-90

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s) EDR ID Number
 EPA ID Number

AU178
WNW 2201 LAURELWOOD
 1/2-1 SANTA CLARA, CA 95054
 3700
 Higher **Site 1 of 2 in cluster AU**

CHMIRS S100275287
Cortese N/A

CORTESE:
 Reg Id: 2 438291N01
 Region: CORTESE
 Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

CHMIRS:
 OES Control Number: 8910163 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: HYDROGEN
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: Not reported
 Environmental Contamination: None Reported Property Use: Manufacturing
 Incident Date: 27-FEB-89 Date Completed: 27-FEB-89

AU179
WNW SILICONIX INC
 1/2-1 2201 LAURELWOOD RD
 3700 SANTA CLARA, CA 95050
 Higher **Site 2 of 2 in cluster AU**

Cal-Sites 1000247350
CERCLIS 95054SLCNX22
FINDS
RCRIS-LQG
TRIS
CA SLIC
CA WDS

CERCLIS Classification Data:
 Site Incident Category: Not reported Federal Facility: Not a Federal Facility
 Non NPL Status: SI Start Needed
 Ownership Status: Unknown NPL Status: Not on the NPL
CERCLIS Assessment History:
 Assessment: DISCOVERY Completed: 07/01/1988
 Assessment: PRELIMINARY ASSESSMENT Completed: 12/09/1989
CERCLIS Site Status:
 Low

RCRIS:
 Owner: SILICONIX INC
 (415) 555-1212
 EPA ID: CAD009131392
 Contact: ENVIRONMENTAL MANAGER
 Classification: Large Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

BIENNIAL REPORTS:
 Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D001	7846.75	D002	140098.75
D004	784.00	D007	2.00
D008	42.00	D009	141.78
D022	6096.75	F001	91.74
F003	5532.58	F005	3790.58
F006	774.00		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SILICONIX INC (Continued)

1000247350

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	11/10/1994
Actual Date Achieved Compliance:	Not reported
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	05/25/1994
Actual Date Achieved Compliance:	27-JUN-94

There are 2 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	27-JUN-94

NY MANIFEST

Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRS Facility System (AIRS/AFS)
- Biennial Reporting System (BRS)
- Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS)
- Facility Registry System (FRS)
- National Emissions Trends (NET)
- National Toxics Inventory (NTI)
- Resource Conservation and Recovery Act Information system (RCRAINFO)
- Toxic Chemical Release Inventory System (TRIS)

CAL-SITES:

Facility ID	43380018	
Status:	REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD	
Status Date:	12/09/1989	
Lead:	Not reported	
Region:	2 - BERKELEY	
Branch:	NC - NORTH COAST	
File Name:	Not reported	
Status Name:	PROPERTY/SITE REFERRED TO RWQCB	
Lead Agency:	N/A	Not reported
NPL:	Not reported	
SIC:	38 MANU - INSTRUMENTS & RELATED PRODUCTS	
Facility Type:	N/A	
Type Name:	Not reported	
Staff Member Responsible for Site:	Not reported	
Supervisor Responsible for Site:	Not reported	
Region Water Control Board:	Not reported	
Access:	Not reported	
Cortese:	Not reported	
Hazardous Ranking Score:	Not reported	
Date Site Hazard Ranked:	Not reported	
Groundwater Contamination:	Not reported	
No. of Contamination Sources:	0	
Lat/Long:	0° 0' 0.00" / 0° 0' 0.00"	
Lat/long Method:	Not reported	
State Assembly District Code:	Not reported	

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SILICONIX INC (Continued)

1000247350

State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

SLIC Region 2:

• Facility ID: 43S0236
Region: 2
Facility Status: Active Not reported
Staff: DIB Not reported
Last Site Update: 02/20/19
NPL Status: Not an NPL site Discovery Date: 02/16/1988
Case List: SLIC Imaged: No
Date Closed: Not reported Cost Recovery: YES
Abate Method: 13 Substance: Solvents
Case Type: TK Sample Date: 04/15/1991
Contamination: NOT DETERMINED
Lead: 2189.8291 RWQCB
Contamination Level: 0
Number of Municipal Wells Contaminated by Site: 0
Number of Private Wells Contaminated by Site: 0
Soil Removal Action Taken/Needed:
Soil Removal or Contaminant Action Started:
Soil Removal or Contaminant Action Completed:
On-Site Groundwater Extraction or Containment is Needed: Not Determined
On-Site Groundwater Extraction or Containment Started:
Off-Site Groundwater Extraction or Containment is Needed: Not Determined
Off-Site Groundwater Extraction or Containment Started:
Length of Contamination Plume (Feet): 0
Depth of Contamination Plume (Feet): 0
Wells Closed Due To Contamination of Site:
Date of Wells Closure:
Nearest Public or Private Drinking Water Well (Feet): 0
Under Jurisdiction of Lead Agency Date: 1/6/88
Latitude/Longitude: 37 / -122
Flow Rate: 0
Flow Date:
Percent of Contaminants Contained: 0
Contaminant Type:
EPA ID:
Stages of Site Investigation Process Initiated:
Begun Characterization : Yes
Completed Characterization : No
Begun Remediation: No
Completed Remediation: No
Submitted Remediation Plan: No
Approved Remediation Plan: No
Begun Final Remedial Action: No
Completed Final Remedial Action: No
Facility Desc: SEMI-CONDUCTOR WATER FABRICATION PLANT
Comment: Not reported

WDS:

Facility ID: San Francisco Bay 438291002
Facility Contact: GEORGE BREEIN Facility Telephone: Not reported
SIC Code: Not reported SIC Code 2: Not reported
Agency Name: SILICONIX, INC./VISHAY
Agency Address: 2201 LAURELWOOD RD

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SILICONIX INC (Continued)

1000247350

SANTA CLARA 95054
 Agency Contact: GEORGE BREEIN Agency Phone: 0
 Design Flow: 0 Million Gal/Day Baseline Flow: Not reported
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
 Agency Type: Private
 Waste Type: Contaminated Ground Water - Hazardous/Influent or Solid Wastes that contain toxic, corrosive, ignitable or reactive substances and must be managed according to applicable DOHS standards.
 Threat to Water: N
 Complexity: Category B - Any facility having a physical, chemical, or biological waste treatment system (except for septic systems with subsurface disposal), or any Class II or III disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum products, solid wastes, and sewage pump out facilities.
 Reclamation: No reclamation requirements associated with this facility.
 POTW: DIB
 NPDES Number: CAG912003 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
 Subregion: 2
 Frequency of Reporting to Regional Board: Quarterly Submittal
 Resource Conservation and Recovery Act (RCRA) Facility: No
 Project Official's Initials: 2

180
 SE
 1/2-1
 3737
 Higher

QUALITY FORK LIFT
 2375 DE LA CRUZ BLVD
 SANTA CLARA, CA 95050

LUST S101309427
 Cortese N/A

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1506
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: No Action Taken - no action has as yet been taken at the site
 Review Date: Not reported Confirm Leak: Not reported
 Workplan: Not reported Prelim Assess: Not reported
 Pollution Char: Not reported Remed Plan: Not reported
 Remed Action: Not reported Monitoring: Not reported
 Close Date: 7/13/2000
 Release Date: 12/30/1991
 Cleanup Fund Id: Not reported
 Discover Date: 12/15/1990
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 1/16/1992
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

QUALITY FORK LIFT (Continued)

S101309427

How Stopped: Close Tank
Interim : No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : 1/2/1965
Max MTBE GW : 100
• MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case # : 06S1W35K04
Beneficial: Not reported
Staff : CTH
GW Qualifies : <
Max MTBE Soil : 13
Soil Qualifies : <
Hydr Basin # : Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 8/10/2000
Stop Date : 12/15/1990
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608501476
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 2
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3197.185164868098785061865283
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1506
Entered Date: 01/16/1992
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 1700
Maximum Groundwater Impact: 34000
County : Santa Clara
Current Benzene: 120
MTBE Detected in GW: 100
MTBE Detected in Soil: 13
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: S121
Transfer Date: Not reported
Closed Date: 07/13/2000
SCVWD Id: 06S1W35K04f

CORTESE:

Reg Id: 43-1506
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s) EDR ID Number
 EPA ID Number

AT181 **PATTON BROTHER INC**
NNE **530 ALDO AVE**
1/2-1 **SANTA CLARA, CA 95054**
3738
Lower **Site 2 of 3 in cluster AT**

LUST **S104162769**
Cortese **N/A**

State LUST:

- Cross Street: Not reported
- Qty Leaked: Not reported
- Case Number: 43-1041
- Reg Board: San Francisco Bay Region
- Chemical: Gasoline
- Lead Agency: Local Agency
- Local Agency: 43099
- Case Type: Other ground water affected
- Status: Pollution characterization
- County: Santa Clara
- Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
- Review Date: Not reported
- Workplan: 7/20/1988
- Pollution Char: Not reported
- Remed Action: Not reported
- Close Date: Not reported
- Release Date: 9/19/1988
- Cleanup Fund Id: Not reported
- Discover Date: 2/19/1987
- Enforcement Dt: Not reported
- Enf Type: Not reported
- Enter Date: 9/29/1988
- Funding: Federal Funds
- Staff Initials: UNK
- How Discovered: Tank Closure
- How Stopped: Close Tank
- Interim: Yes
- Leak Cause: Structure Failure
- Leak Source: Tank
- MTBE Date: Not reported
- Max MTBE GW: Not reported
- MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
- Priority: Not reported
- Local Case #: 06S1W26C01
- Beneficial: Not reported
- Staff: CTH
- GW Qualifies: Not reported
- Max MTBE Soil: Not reported
- Soil Qualifies: Not reported
- Hydr Basin #: Not reported
- Operator: Not reported
- Oversight Prgm: Local Oversight Program UST
- Oversight Prgm: LOP
- Review Date: 2/26/1993
- Stop Date: 2/19/1987
- Work Suspended: N
- Responsible Party: BLANK RP
- RP Address: Not reported
- Global Id: T0608501035
- Org Name: Not reported
- Contact Person: Not reported

Confirm Leak: Not reported
 Prelim Assess: 7/20/1988
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PATTON BROTHER INC (Continued)

S104162769

MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 1466.3870088852142627435470208
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1041
Entered Date: 09/29/1988
Facility Status: Pollution characterization
Maximum Soil Concentration: 1500
Maximum Groundwater Impact: 400000
County: Santa Clara
Current Benzene: 0
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

CORTESE:

Reg Id: 43-1041
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AT182
NNE
1/2-1
3773
Lower

FINISHERS
517 ALDO AVENUE
SANTA CLARA, CA 95054

Cal-Sites S103770865
HAZNET N/A

Site 3 of 3 in cluster AT

CAL-SITES:

Facility ID 43340083
Status: CERT - CERTIFIED AS HAVING BEEN REMEDIED SATISFACTORILY UNDER DTSC
OVERSIGHT
Status Date: 06/06/2000
Lead: DTSC
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: FINISHERS
Status Name: CERTIFIED
Lead Agency: DEPT OF TOXIC SUBSTANCES CONTROL Not reported
NPL: Not Listed
SIC: 34 MANU - FABRICATED METAL PRODUCTS
Facility Type: VOLUNTARY CLEANUP PROGRAM
Type Name: VCP
Staff Member Responsible for Site: VLASKY
Supervisor Responsible for Site: DTSUJI
Region Water Control Board: SF - SAN FRANCISCO BAY
Access: Controlled
Cortese: C
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Unknown
No. of Contamination Sources: 0
Lat/Long: 37° 23' 9.00" / 121° 56' 34.00"
Lat/long Method: TEALE
State Assembly District Code: 20

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

FINISHERS (Continued)

S103770865

State Senate District: 13

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

HAZNET:

Gepaid: CAL000016088
 Tepaid: CAT080013352
 Gen County: Santa Clara
 Tsd County: Los Angeles
 Tons: 6.5510
 Category: Oil/water separation sludge
 Disposal Method: Recycler
 Contact: PANSKY EMIL J
 Telephone: (000) 000-0000
 Mailing Address: 517 ALDO AVENUE
 SANTA CLARA, CA 95054
 County: Santa Clara

Gepaid: CAL000016088
 Tepaid: CAD099452708
 Gen County: Santa Clara
 Tsd County: Los Angeles
 Tons: 6.1507
 Category: Oil/water separation sludge
 Disposal Method: Transfer Station
 Contact: PANSKY EMIL J
 Telephone: (000) 000-0000
 Mailing Address: 517 ALDO AVENUE
 SANTA CLARA, CA 95054
 County: Santa Clara

Gepaid: CAC002226417
 Tepaid: CAT000646117
 Gen County: Santa Clara
 Tsd County: Kings
 Tons: 75.8520
 Category: Contaminated soil from site clean-ups
 Disposal Method: Disposal, Land Fill
 Contact: PAUL BRENNER
 Telephone: (000) 000-0000
 Mailing Address: 931 WILMINGTON WAY
 REDWOOD CITY, CA 94062
 County: Santa Clara

183
 NE
 1/2-1
 3842
 Lower

SAFETY SPECIALISTS INC
 3284 EDWARD AVENUE
 SANTA CLARA, CA 95050

FINDS 1000224241
RCRIS-LQG CAD010917805
RCRIS-TSD
CA SLIC
CORRACTS
CERC-NFRAP

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
 Non NPL Code: DR
 Ownership Status: Private

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
 Assessment: PRELIMINARY ASSESSMENT

Completed: 06/12/1990

Completed: 08/28/1990

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

SAFETY SPECIALISTS INC (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000224241

Contamination: Not reported
 Lead: RWQCB
 Contamination Level:
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: 0
 Soil Removal or Contaminant Action Started:
 Soil Removal or Contaminant Action Completed: 0
 On-Site Groundwater Extraction or Containment is Needed: 0
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed:
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 0
 Depth of Contamination Plume (Feet): 0
 Wells Closed Due To Contamination of Site:
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 0
 Under Jurisdiction of Lead Agency Date:
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Not reported
 Completed Characterization : Not reported
 Begun Remediation: Not reported
 Completed Remediation: Not reported
 Submitted Remediation Plan: Not reported
 Approved Remediation Plan: Not reported
 Begun Final Remedial Action: Not reported
 Completed Final Remedial Action: Not reported
 Facility Desc: HAZARDOUS WASTE TREATMENT & STORAGE FACILITY
 Comment: Not reported

184
 NNE
 1/2-1
 3854
 Lower

3495 DELA CRUZ BLVD
 SANTA CLARA, CA 95054

CHMIRS S100275294
 N/A

CHMIRS:
 OES Control Number: 8910188 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: NICKEL SULFAMATE
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 25
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 07-MAR-89 Date Completed: 07-MAR-89

185
 South
 1/2-1
 3941
 Higher

MURRY'S AUTO BODY
 970 MARTIN
 SANTA CLARA, CA 95050

LUST S101309449
 Cortese N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MURRY'S AUTO BODY (Continued)

S101309449

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0966
Reg Board: San Francisco Bay Region
Chemical: Mineral Spirits
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Pump and Treat Ground Water - generally employed to remove dissolved contaminants

Review Date: Not reported
Workplan: 5/5/1989
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 9/13/1999
Release Date: 2/10/1987
Cleanup Fund Id: Not reported
Discover Date: 2/2/1990
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 2/20/1987
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: 8/12/1999
Max MTBE GW: 5
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: 06S1W34J02
Beneficial: Not reported
Staff: CTH
GW Qualifies: <
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 9/29/1999
Stop Date: 2/2/1990
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500969
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 0
Water System Name: Not reported

Confirm Leak: Not reported
Prelim Assess: 5/5/1989
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MURRY'S AUTO BODY (Continued)

S101309449

Well Name: Not reported
Distance To Lust: 3764.1495806056699001356052787
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0966
Entered Date: 02/20/1987
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 1966
Maximum Groundwater Impact: 620000
County: Santa Clara
Current Benzene: 130
MTBE Detected in GW: 5
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O331
Transfer Date: Not reported
Closed Date: 09/13/1999
SCVWD Id: 06S1W34J02f

CORTESE:

Reg Id: 43-0966
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AV186
South
1/2-1
3946
Higher

1036 MARTIN AVENUE
SANTA CLARA, CA 95050

CHMIRS S100277203
N/A

Site 1 of 2 in cluster AV

CHMIRS:

OES Control Number: 9115262 DOT ID: Not reported
DOT Hazard Class: Not Reported
Chemical Name: USED MOTOR OIL
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: 20
Environmental Contamination: Ground Property Use: Manufacturing
Incident Date: 03-FEB-91 Date Completed: 03-FEB-91

AV187
South
1/2-1
3952
Higher

1061 MARTIN AVE. #A
SANTA CLARA, CA

CHMIRS S100280807
N/A

Site 2 of 2 in cluster AV

CHMIRS:

OES Control Number: 9991164 DOT ID: 1005
DOT Hazard Class: Gases
Chemical Name: AMMONIA
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: 10
Environmental Contamination: None Reported Property Use: Manufacturing
Incident Date: 09-JUL-88 Date Completed: 09-JUL-88

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

188 KILPATRICK BAKERY
 South 1090 MARTIN
 1/2-1 SANTA CLARA, CA 95050
 3959
 Higher

HAZNET S102432217
 LUST N/A
 Cortese

State LUST:

* Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1429
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 4/9/1999
 Release Date: 11/24/1992
 Cleanup Fund Id : Not reported
 Discover Date : 11/24/1992
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 12/14/1992
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : 1/2/1965
 Max MTBE GW : 50
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case # : 06S1W34J09
 Beneficial: Not reported
 Staff : CTH
 GW Qualifies : <
 Max MTBE Soil : Not reported
 Soil Qualifies : Not reported
 Hydr Basin #: Not reported
 Operator : Not reported
 Oversight Prgm: Local Oversight Program UST
 Oversight Prgm : LOP
 Review Date : 5/24/1999
 Stop Date : 11/24/1992
 Work Suspended : N
 Responsible Party: BLANK RP
 RP Address: Not reported
 Global Id: T0608501401
 Org Name: Not reported
 Contact Person: Not reported
 Confirm Leak: Not reported
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

KILPATRICK BAKERY (Continued)

S102432217

MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3724.6306649466142101498332834
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1429
Entered Date: 12/14/1992
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 930
Maximum Groundwater Impact: 24000
County: Santa Clara
Current Benzene: 26
MTBE Detected in GW: 50
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O131
Transfer Date: Not reported
Closed Date: 04/09/1999
SCVWD Id: 06S1W34J09f

HAZNET:

Gepaid: CAL000030597
Tepaid: CAD028409019
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 1.6250
Category: Other organic solids
Disposal Method: Transfer Station
Contact: KILPATRIKS BAKERY
Telephone: (000) 000-0000
Mailing Address: P O BOX 2093
OAKLAND, CA 94604
County: Santa Clara
Gepaid: CAL000030597
Tepaid: CAD028409019
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .9174
Category: Unspecified organic liquid mixture
Disposal Method: Treatment, Tank
Contact: KILPATRIKS BAKERY
Telephone: (000) 000-0000
Mailing Address: P O BOX 2093
OAKLAND, CA 94604
County: Santa Clara

CORTESE:

Reg Id: 43-1429
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

189 1X ALHAMBRA WATER CO
NNE 480 ALDO AVE
1/2-1 SANTA CLARA, CA 95050
3979
Lower

HAZNET S100849199
Cortese N/A

HAZNET:
Gepaid: CAC000045765
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .0834
Category: Unspecified organic liquid mixture
Disposal Method: Disposal, Other
Contact: EMERG/LARRY MONETTE/FIRE DEPT
Telephone: (000) 000-0000
Mailing Address: 480 ALDO AVE
SANTA CLARA, CA 95050
County Santa Clara
Gepaid: CAC000045765
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1500
Category: Other organic solids
Disposal Method: Disposal, Other
Contact: EMERG/LARRY MONETTE/FIRE DEPT
Telephone: (000) 000-0000
Mailing Address: 480 ALDO AVE
SANTA CLARA, CA 95050
County Santa Clara
Gepaid: CAC000045765
Tepaid: CAL000048571
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .2293
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: EMERG/LARRY MONETTE/FIRE DEPT
Telephone: (000) 000-0000
Mailing Address: 480 ALDO AVE
SANTA CLARA, CA 95050
County Santa Clara
Gepaid: CAC000045765
Tepaid: CAT080014079
Gen County: Santa Clara
Tsd County: 7
Tons: .0000
Category:
Disposal Method: Transfer Station
Contact: EMERG/LARRY MONETTE/FIRE DEPT
Telephone: (000) 000-0000
Mailing Address: 480 ALDO AVE
SANTA CLARA, CA 95050
County Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

1X ALHAMBRA WATER CO (Continued)

S100849199

Gepaid: CAC000045765
Tepaid: CAT080014079
Gen County: Santa Clara
Tsd County: 7
Tons: .5838
• Category: Liquids with pH <UN> 2
Disposal Method: Not reported
Contact: EMERG/LARRY MONETTE/FIRE DEPT
Telephone: (000) 000-0000
Mailing Address: 480 ALDO AVE
SANTA CLARA, CA 95050
County Santa Clara

CORTESE:
Reg Id: 43-2057
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

190
SW
1/2-1
4049
Higher

SANMINA PLANT 3
SCOTT BLVD
SANTA CLARA, CA 95050

FINDS 1000455748
HAZNET 95050SNMNC25
Cortese
RCRIS-LQG
TRIS

RCRIS:
Owner: SANMINA CORPORATION
(415) 555-1212
EPA ID: CAD982429615
Contact: ENVIRONMENTAL MANAGER
(408) 983-3334

Classification: Large Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D002	27980000.00	D004	576000.00
D007	576000.00	D008	27402000.00
F006	790000.00	F007	0.00

Violation Status: Violations exist

Regulation Violated: Not reported
Area of Violation: GENERATOR-PRE-TRANSPORT REQUIREMENTS
Date Violation Determined: 06/28/1999
Actual Date Achieved Compliance: Not reported
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 07/28/1999
Penalty Type: Not reported

There are 1 violation record(s) reported at this site:

Evaluation Area of Violation Date of Compliance
Compliance Evaluation Inspection GENERATOR-PRE-TRANSPORT REQUIREMENTS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SANMINA PLANT 3 (Continued)

1000455748

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRS Facility System (AIRS/AFS)
- Biennial Reporting System (BRS)
- Enforcement Docket System (DOCKET)
- Facility Registry System (FRS)
- National Emissions Trends (NET)
- Resource Conservation and Recovery Act Information system (RCRAINFO)
- Toxic Chemical Release Inventory System (TRIS)

HAZNET:

Gepaid: CAD982429615
Tepaid: CAD008488025
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 109.2535
Category: Unspecified alkaline solution
Disposal Method: Recycler
Contact: SANMINA CORP
Telephone: (408) 435-8444
Mailing Address: 355 E TRIMBLE RD
SAN JOSE, CA 95131 - 1218
County Santa Clara

Gepaid: CAD982429615
Tepaid: CAD008488025
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 19.2654
Category: Unspecified alkaline solution
Disposal Method: Not reported
Contact: SANMINA CORP
Telephone: (408) 435-8444
Mailing Address: 355 E TRIMBLE RD
SAN JOSE, CA 95131 - 1218
County Santa Clara

Gepaid: CAD982429615
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: 52.2536
Category: Other inorganic solid waste
Disposal Method: Disposal, Land Fill
Contact: SANMINA CORP
Telephone: (408) 435-8444
Mailing Address: 355 E TRIMBLE RD
SAN JOSE, CA 95131 - 1218
County Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

SUMMIT INDUSTRIAL EQUIPMENT (Continued)

S100945913

LUST Region SC:

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: 09/20/1995
SCVWD Id: 06S1W27L01f

HAZNET:

Gepaid: CAL000106191
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: 1.8765
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: MORIN CLIFFORD J
Telephone: (000) 000-0000
Mailing Address: 2030 DUANE AVE
SANTA CLARA, CA 95054

County Santa Clara

Gepaid: CAL000106191
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .0500
Category: Empty containers less than 30 gallons
Disposal Method: Recycler
Contact: MORIN CLIFFORD J
Telephone: (000) 000-0000
Mailing Address: 2030 DUANE AVE
SANTA CLARA, CA 95054

County Santa Clara

Gepaid: CAL000106191
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .2293
Category: Unspecified solvent mixture Waste
Disposal Method: Disposal, Other
Contact: MORIN CLIFFORD J
Telephone: (000) 000-0000
Mailing Address: 2030 DUANE AVE
SANTA CLARA, CA 95054

County Santa Clara

Gepaid: CAL000106191
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: 1.7514
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: MORIN CLIFFORD J
Telephone: (000) 000-0000
Mailing Address: 2030 DUANE AVE
SANTA CLARA, CA 95054

County Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SUMMIT INDUSTRIAL EQUIPMENT (Continued)

S100945913

Gepaid: CAL000106191
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .0000
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Not reported
Contact: MORIN CLIFFORD J
Telephone: (000) 000-0000
Mailing Address: 2030 DUANE AVE
SANTA CLARA, CA 95054
County: Santa Clara

CORTESE:

Reg Id: 43-1408
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

192
SSE
1/2-1
4067
Higher

FMC CORPORATION
651 MARTIN AVE
SANTA CLARA, CA 95050

LUST S101304273
Cortese N/A

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0626
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Preliminary site assessment underway
County: Santa Clara
Abate Method: No Action Taken - no action has as yet been taken at the site
Review Date: Not reported
Workplan: 4/15/1990
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 10/10/1990
Cleanup Fund Id: Not reported
Discover Date: 10/10/1990
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 11/20/1990
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: 06S1W35E03

Confirm Leak: Not reported
Prelim Assess: 4/15/1990
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FMC CORPORATION (Continued)

S101304273

Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 2/19/1991
Stop Date : 10/10/1990
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500660
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3852.4357615054982871896260973
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0626
Entered Date: 11/20/1990
Facility Status: Preliminary site assessment underway
Maximum Soil Concentration: 14493
Maximum Groundwater Impact: 181000
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O342
Transfer Date: Not reported
Closed Date: 09/13/2001
SCVWD Id: 06S1W35E03f

CORTESE:

Reg Id: 43-0626
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

193
NE
1/2-1
4085
Lower

FIVE MILE HOUSE
3363 EDWARD
SANTA CLARA, CA 95050

Cortese S105026430
N/A

CORTESE:

Reg Id: 2826
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s) EDR ID Number
 EPA ID Number

194
 SSE
 1/2-1
 4152
 Higher

1X POLLACK CONSTRUCTION CO
570 MARTIN AVE
SANTA CLARA, CA 95050

HAZNET **S103947557**
Cortese **N/A**

HAZNET:

• Gepaid: CAC001007184
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: 1.8348
 Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
 Disposal Method: Recycler
 Contact: ROBERT POLLACK
 Telephone: (000) 000-0000
 Mailing Address: 1670 NEWHALL ST
 SANTA CLARA, CA 95050
 County Santa Clara

Gepaid: CAC001007184
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .4587
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: ROBERT POLLACK
 Telephone: (000) 000-0000
 Mailing Address: 1670 NEWHALL ST
 SANTA CLARA, CA 95050
 County Santa Clara

CORTESE:

Reg Id: 43-0436
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

195
 SE
 1/2-1
 4185
 Higher

INTEX AUTO PARTS
2290 DE LA CRUZ BLVD
SANTA CLARA, CA 95050

Cortese **S101304232**
 N/A

CORTESE:

Reg Id: 43-0696
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

196
 NNW
 1/2-1
 4237
 Lower

RMC LONESTAR
1555 RUSSELL AVE
SANTA CLARA, CA 95052

Cortese **1000222474**
 N/A

CORTESE:

Reg Id: 43-0826
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

 Reg Id: 3259

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

VICTORY UPHOLSTERY (Continued)

S101309444

Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608501559
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtb Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3647.0505896675409068344450995
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1604
Entered Date: 02/28/1988
Facility Status: Pollution characterization
Maximum Soil Concentration: 3200
Maximum Groundwater Impact: 5000
County : Santa Clara
Current Benzene: 381
MTBE Detected in GW: No
MTBE Detected in Soil: Not reported
MTBE: 16
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O231
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W34J10f

CORTESE:

Reg Id: 43-1604
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AX200
NE
1/2-1
4317
Lower

KINETIC SYSTEMS INC
430 ALDO AVE
SANTA CLARA, CA 95054

Cortese S105026434
N/A

Site 1 of 3 in cluster AX

CORTESE:

Reg Id: 43-0787
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AX201
NE
1/2-1
4349
Lower

THERMAL MECHANICAL
425 ALDO AVE
SANTA CLARA, CA 95050

Cortese S105033494
N/A

Site 2 of 3 in cluster AX

CORTESE:

Reg Id: 43-1464
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site _____ Database(s) _____ EDR ID Number _____
 _____ EPA ID Number _____

202
 NNE
 1/2-1
 4355
 Lower

3575 DE LA CRUZ
 SANTA CLARA, CA 95054

CHMIRS S100219825
 Cortese N/A

CORTESE:
 Reg Id: 43-0490
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

CHMIRS:
 OES Control Number: 9010713 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: CHROMIUM COMPOUNDS
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 2000
 Environmental Contamination: Other Property Use: County/City Road
 Incident Date: 08-MAY-90 Date Completed: 08-MAY-90

AY203
 South
 1/2-1
 4399
 Higher

RIGGING INTERNATIONAL
 970 RICHARD AVE
 SANTA CLARA, CA 95050

LUST S100235564
 Cortese N/A

Site 1 of 3 in cluster AY

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1115
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)

Review Date: Not reported Confirm Leak: Not reported
 Workplan: 10/3/1985 Prelim Assess: 10/3/1985
 Pollution Char: Not reported Remed Plan: Not reported
 Remed Action: Not reported Monitoring: Not reported
 Close Date: 12/5/1995
 Release Date: 3/25/1985
 Cleanup Fund Id: Not reported
 Discover Date: 4/8/1985
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 4/5/1985
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: Not reported
 Max MTBE GW: Not reported
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SERENDIPITY LAND YACHTS (Continued)

S103987413

Gepaid: CAL000138632
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 0.2085
Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Contact: MARTY PETERS
Telephone: (000) 000-0000
Mailing Address: 1051 RICHARD AVE
SANTA CLARA, CA 95050 - 2815
County: Santa Clara

CORTESE:
Reg Id: 43-1025
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

**AZ208
South
1/2-1
4408
Higher**

**PACIFIC BELL
1021 RICHARD AVE
SANTA CLARA, CA 95050
Site 2 of 2 in cluster AZ**

**RCRIS-SQG 1000251357
FINDS CAT080022007
HAZNET
Cortese
HIST UST**

RCRIS:
Owner: PACIFIC BELL
(510) 823-9823
EPA ID: CAT080022007
Contact: ENVIRONMENTAL MANAGER
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

HAZNET:

Gepaid: CAL000107662
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .2500
Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC BELL (Continued)

1000251357

Gepaid: CAL000107662
Tepaid: CAD982444481
Gen County: Santa Clara
Tsd County: San Bernardino
Tons: .2500
• Category: Other organic solids
Disposal Method: Transfer Station
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

Gepaid: CAL000107662
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: 3.8571
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

Gepaid: CAL000107662
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .4587
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

Gepaid: CAL000107662
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .3753
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Contact: PACIFIC BELL
Telephone: (925) 823-6161
Mailing Address: RM 3E000
SAN RAMON, CA 94583 - 0995
County Santa Clara

The CA HAZNET database contains 21 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:
Reg Id: 2470
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PACIFIC BELL (Continued)

1000251357

UST HIST:

Facility ID:	16378	Container Num:	G-81-10K
Tank Num:	1	Year Installed:	1981
Tank Capacity:	10000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(415) 542-6758
* Type of Fuel:	UNLEADED	Region:	STATE
Leak Detection:	None	Other Type:	PHONE CO.
Contact Name:	E. J. KOEHLER		
Total Tanks:	1		
Facility Type:	2		

BA209
South
1/2-1
4419
Higher

MAESTRI PROPERTY
1100 RICHARD AVE
SANTA CLARA, CA 95161

LUST **S103473162**
Cortese **N/A**

Site 1 of 2 in cluster BA

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	Not reported
Case Number:	43-0042	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	43099		
Case Type:	Other ground water affected		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Review Date:	Not reported		
Workplan:	Not reported		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	6/27/1996		
Release Date:	7/11/1991		
Cleanup Fund Id :	Not reported		
Discover Date :	1/22/1991		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	3/7/1991		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.		
Priority:	Not reported		
Local Case # :	06S1W34J01		
Beneficial:	Not reported		
Staff :	CTH		
GW Qualifies :	Not reported		
Max MTBE Soil :	Not reported		
Soil Qualifies :	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MAESTRI PROPERTY (Continued)

S103473162

Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 7/2/1996
Stop Date : 1/22/1991
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500112
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3278.401860754919632853653913
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0042
Entered Date: 03/07/1991
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 1300
Maximum Groundwater Impact: 220
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O111
Transfer Date: Not reported
Closed Date: 06/27/1996
SCVWD Id: 06S1W34J01f

CORTESE:

Reg Id: 43-0042
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

AW210
South
1/2-1
4421
Higher

BAY EQUIPMENT COMPANY
2390 LAFAYETTE ST
SANTA CLARA, CA 95050

LUST S103880766
Cortese N/A

Site 2 of 2 in cluster AW

LUST Region SC:

Region: Santa Clara
Case Rank: O131
Transfer Date: Not reported
Closed Date: 08/11/1994
SCVWD Id: 06S1W34J05f

CORTESE:

Reg Id: 43-0153
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s) EDR ID Number
 EPA ID Number

BA211 **MONARCH TILE**
South **1129 RICHARD AVE**
1/2-1 **SANTA CLARA, CA 95050**
4427
Higher **Site 2 of 2 in cluster BA**

LUST **S100235562**
Cortese **N/A**

State LUST:

- Cross Street: Not reported
- Qty Leaked: Not reported
- Case Number: 43-0946
- Reg Board: San Francisco Bay Region
- Chemical: Gasoline
- Lead Agency: Local Agency
- Local Agency: 43099
- Case Type: Other ground water affected
- Status: Signed off, remedial action completed or deemed unnecessary
- County: Santa Clara
- Abate Method: No Action Taken - no action has as yet been taken at the site
- Review Date: Not reported
- Workplan: Not reported
- Pollution Char: Not reported
- Remed Action: Not reported
- Close Date: 4/4/2001
- Release Date: 8/16/1989
- Cleanup Fund Id: Not reported
- Discover Date: 8/3/1989
- Enforcement Dt: Not reported
- Enf Type: Not reported
- Enter Date: 8/22/1989
- Funding: Federal Funds
- Staff Initials: UNK
- How Discovered: Tank Closure
- How Stopped: Close Tank
- Interim: No
- Leak Cause: Structure Failure
- Leak Source: Tank
- MTBE Date: 1/2/1965
- Max MTBE GW: 44
- MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
- Priority: Not reported
- Local Case #: 06S1W34J07
- Beneficial: Not reported
- Staff: CTH
- GW Qualifies: Not reported
- Max MTBE Soil: 3
- Soil Qualifies: <
- Hydr Basin #: Not reported
- Operator: Not reported
- Oversight Prgm: Local Oversight Program UST
- Oversight Prgm: LOP
- Review Date: 4/17/2001
- Stop Date: 8/3/1989
- Work Suspended: N
- Responsible Party: BLANK RP
- RP Address: Not reported
- Global Id: T0608500951
- Org Name: Not reported
- Contact Person: Not reported
- MTBE Conc: 2

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

MONARCH TILE (Continued)

S100235562

Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3346.5431433741652054825689642
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:
Region: 2
Facility Id: 43-0946
Entered Date: 08/22/1989
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 70
Maximum Groundwater Impact: 44
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 44
MTBE Detected in Soil: 3
MTBE: 44
MTBE Qualify: Not reported

LUST Region SC:
Region: Santa Clara
Case Rank: O-31
Transfer Date: Not reported
Closed Date: 04/04/2001
SCVWD Id: 06S1W34J07f

CORTESE:
Reg Id: 43-0946
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

212
South
1/2-1
4446
Higher

LOWERY & LITTLE INC
1180 RICHARD AVE
SANTA CLARA, CA 95050

LUST S101304293
Cortese N/A

State LUST:
Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0840
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency : 43099
Case Type: Other ground water affected
Status: Pollution characterization
County: Santa Clara
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: 4/4/1986
Workplan: 8/28/1986
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 4/4/1986
Cleanup Fund Id : Not reported
Discover Date : 4/4/1986
Enforcement Dt : Not reported
Enf Type: Not reported

Confirm Leak: 4/4/1986
Prelim Assess: 8/28/1986
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

LOWERY & LITTLE INC (Continued)

S101304293

Enter Date : 2/20/1991
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date : 1/2/1965
Max MTBE GW : 200
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case # : 06S1W34K01
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 11/21/1997
Stop Date : 4/4/1986
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500853
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 3272.0583431457248931440776028
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0840
Entered Date: 02/20/1991
Facility Status: Pollution characterization
Maximum Soil Concentration: 0
Maximum Groundwater Impact: 7777777
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 200
MTBE Detected in Soil: Not reported
MTBE: 97
MTBE Qualify: Not reported

CORTESE:

Reg Id: 43-0840
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EPA ID Number
 EDR ID Number

BB213
SE
1/2-1
4516
Higher

LOMBARDO DIAMOND CORE DRI
2225 DE LA CRUZ
SANTA CLARA, CA 95050

Site 1 of 2 in cluster BB

LUST **S101309425**
Cortese **N/A**

LUST Region SC:

Region: Santa Clara
 Case Rank: S231
 Transfer Date: Not reported

Closed Date: 12/12/1995
 SCVWD Id: 06S1W35Q06f

Region: Santa Clara
 Case Rank: O1-1
 Transfer Date: Not reported

Closed Date: 10/31/2001
 SCVWD Id: 06S1W35Q07f

CORTESE:

Reg Id: 43-0825
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

214
NE
1/2-1
4526
Lower

R E CUDDIE CO
3360 VICTOR CT
SANTA CLARA, CA 95054

HAZNET **S102435721**
LUST **N/A**
Cortese

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-1511
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Regional Board
 Local Agency: 43099
 Case Type: Soil only
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
 Review Date: 2/16/1994
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 3/9/1995
 Release Date: 3/10/1995
 Cleanup Fund Id: Not reported
 Discover Date: 1/27/1994
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 4/5/1994
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Unknown
 Leak Source: Unknown
 MTBE Date: Not reported
 Max MTBE GW: Not reported
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
 Priority: 2A4

Confirm Leak: 2/16/1994
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

R E CUDDIE CO (Continued)

S102435721

Local Case # : 06S1W26B07
Beneficial: Not reported
Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 3/10/1995
Stop Date : 1/27/1994
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608501481
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 1499.0610770151470177727384494
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-1511
Entered Date: 04/05/1994
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 1300
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: S231
Transfer Date: Not reported
Closed Date: 03/09/1995
SCVWD Id: 06S1W26B07f

HAZNET:

Gepaid: CAC000877136
Tepaid: CAD009466392
Gen County: Santa Clara
Tsd County: 7
Tons: 1.0000
Category: Other empty containers 30 gallons or more
Disposal Method: Not reported
Contact: R E CUDDIE CO
Telephone: (000) 000-0000
Mailing Address: 3360 VICTOR CT
SANTA CLARA, CA 95054
County: Santa Clara

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

R E CUDDIE CO (Continued)

S102435721

Gepaid: CAC000877136
 Tepaid: CAD043260702
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: 5.6295
 Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: R E CUDDIE CO
 Telephone: (000) 000-0000
 Mailing Address: 3360 VICTOR CT
 SANTA CLARA, CA 95054
 County: Santa Clara

CORTESE:

Reg Id: 43-1511
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

215
SW
1/2-1
4536
Higher

2160 WALSH AVE.
SANTA CLARA, CA

CHMIRS S100222351
N/A

CHMIRS:

OES Control Number:	9991153	DOT ID:	1789
DOT Hazard Class:	Corrosives		
Chemical Name:	ACID, HYDROCHLORIC		
Extent of Release:	Not reported		
CAS Number:	7647-01-0	Quantity Released:	Not reported
Environmental Contamination:	Air	Property Use:	Manufacturing
Incident Date:	26-MAY-88	Date Completed:	26-MAY-88

216
West
1/2-1
4540
Higher

APPLIED MATERIALS BLDG 78
LAWSON LANE
SANTA CLARA, CA 95054

RCRIS-SQG 1000146438
FINDS CAD982461782
HAZNET
Cortese

RCRIS:

Owner: APPLIED MATERIALS
 (408) 524-0964
 EPA ID: CAD982461782
 Contact: ENVIRONMENTAL MANAGER
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

APPLIED MATERIALS BLDG 78 (Continued)

1000146438

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRS Facility System (AIRS/AFS)
- Facility Registry System (FRS)
- Resource Conservation and Recovery Act Information system (RCRAINFO)

HAZNET:

Gepaid: CAD982461782
Tepaid: CAL000048571
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .2293
Category: Waste oil and mixed oil
Disposal Method: Not reported
Contact: APPLIED MATERIALS INC
Telephone: (408) 235-6364
Mailing Address: 3050 BOWERS AVE M/S 0101
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAD982461782
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 2.5500
Category: Other organic solids
Disposal Method: Transfer Station
Contact: APPLIED MATERIALS INC
Telephone: (408) 235-6364
Mailing Address: 3050 BOWERS AVE M/S 0101
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAD982461782
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1175
Category: Waste oil and mixed oil
Disposal Method: Disposal, Other
Contact: APPLIED MATERIALS INC
Telephone: (408) 235-6364
Mailing Address: 3050 BOWERS AVE M/S 0101
SANTA CLARA, CA 95054
County: Santa Clara

Gepaid: CAD982461782
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1750
Category: Liquids with pH <UN> 2 with metals
Disposal Method: Disposal, Other
Contact: APPLIED MATERIALS INC
Telephone: (408) 235-6364
Mailing Address: 3050 BOWERS AVE M/S 0101
SANTA CLARA, CA 95054

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

APPLIED MATERIALS BLDG 78 (Continued)

1000146438

County Santa Clara
Gepaid: CAD982461782
Tepaid: CAD059494310
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 2.9605
Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Contact: APPLIED MATERIALS INC
Telephone: (408) 235-6364
Mailing Address: 3050 BOWERS AVE M/S 0101
SANTA CLARA, CA 95054
County Santa Clara

The CA HAZNET database contains 12 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2441
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

217
ENE
1/2-1
4545
Same

350 W TRIMBLE RD. - HEWLETT PACKARD
SAN JOSE, CA

CHMIRS S100235459
N/A

CHMIRS:

OES Control Number: 8904457 DOT ID: Not reported
DOT Hazard Class: Poisonous and etiologic (infectious) material
Chemical Name: GALLIUM ARSENIDE
Extent of Release: Not reported
CAS Number: 1303000 Quantity Released: 4
Environmental Contamination: Other Property Use: Manufacturing
Incident Date: 11-JAN-89 Date Completed: 11-JAN-89

BB218
SE
1/2-1
4586
Higher

398 MARTIN
SANTA CLARA, CA 95050

CHMIRS S100274971
N/A

Site 2 of 2 in cluster BB

CHMIRS:

OES Control Number: 8906488 DOT ID: 1580
DOT Hazard Class: Poisonous and etiologic (infectious) material
Chemical Name: CHLOROPICRIN
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: Not reported
Environmental Contamination: Air Property Use: Manufacturing
Incident Date: 25-MAY-89 Date Completed: 25-MAY-89

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

219
 SSW
 1/2-1
 4597
 Higher

1415 RICHARD
 SANTA CLARA, CA 95050

CHMIRS S100275227
 N/A

CHMIRS:

• OES Control Number: 8909266 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: COPPER SULFATE
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 2
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 06-DEC-89 Date Completed: 06-DEC-89

220
 SSW
 1/2-1
 4688
 Higher

SANTA CLARA CIRCUITS#
 1881 MARTIN AVE
 SANTA CLARA, CA 95050

Cal-Sites 1000299776
 RCRIS-SQG CAD069138832
 FINDS

RCRIS:

Owner: MACK ROBERT L
 (415) 555-1212
 EPA ID: CAD069138832
 Contact: ENVIRONMENTAL MANAGER
 (408) 727-4323

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: Not reported
 Area of Violation: GENERATOR-GENERAL REQUIREMENTS
 Date Violation Determined: 04/26/1995
 Actual Date Achieved Compliance: 26-MAY-95
 Regulation Violated: Not reported
 Area of Violation: GENERATOR-GENERAL REQUIREMENTS
 Date Violation Determined: 06/02/1993
 Actual Date Achieved Compliance: Not reported

There are 2 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	26-MAY-95
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CAL-SITES:

Facility ID: 43360007
 Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
 Status Date: 03/21/1995
 Lead: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

SANTA CLARA CIRCUITS# (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000299776

Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 36 MANU - ELECTRONIC & OTHER ELECTRIC EQUIP
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: SF - SAN FRANCISCO BAY
 Access: Not reported
 Cortese: Not reported
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: 22
 State Senate District: 13

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

221
 NNW
 1/2-1
 4698
 Lower

REED & GRAHAM INC
3800 BASSETT ST
SANTA CLARA, CA 95050

LUST S103880733
Cortese N/A

LUST Region SC:

Region: Santa Clara
 Case Rank: O332 Closed Date: 10/18/1995
 Transfer Date: Not reported SCVWD Id: 06S1W27B08f

CORTESE:

Reg Id: 43-1779
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

222
 WNW
 1/2-1
 4699
 Higher

3601 JULIEFFE LANE
SANTA CLARA, CA 95054

CHMIRS S100218298
N/A

CHMIRS:

OES Control Number: 8910172 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: SILANE
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 1
 Environmental Contamination: Other Property Use: Manufacturing
 Incident Date: 02-MAR-89 Date Completed: 02-MAR-89

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site Database(s) EDR ID Number
 EPA ID Number

BC223 **SAN JOSE VALLEY VEAL** **Cortese** **S105033586**
SSW **1820 RICHARD AVE** **N/A**
1/2-1 **SANTA CLARA, CA 95050**
4754
Higher **Site 1 of 2 in cluster BC**

CORTESE:
 Reg Id: 43-0693
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

BC224 **ROMAN SAUSAGE CO** **HAZNET** **S101304294**
SSW **1810 RICHARD AVE** **LUST** **N/A**
1/2-1 **SANTA CLARA, CA 95050** **Cortese**
4781
Higher **Site 2 of 2 in cluster BC**

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0619
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: 2/6/1997
 Release Date: 8/11/1992
 Cleanup Fund Id: Not reported
 Discover Date: 2/12/1993
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 3/1/1993
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: 1/2/1965
 Max MTBE GW: 5
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case #: 06S1W34K03
 Beneficial: Not reported
 Staff: CTH
 GW Qualifies: Not reported
 Max MTBE Soil: Not reported
 Soil Qualifies: Not reported
 Hydr Basin #: Not reported
 Operator: Not reported
 Oversight Prgm: Local Oversight Program UST

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ROMAN SAUSAGE CO (Continued)

S101304294

Oversight Prgm : LOP
Review Date : 11/25/1997
Stop Date : 2/12/1993
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500653
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3583.5068232054209560492975491
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0619
Entered Date: 03/01/1993
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 10000
Maximum Groundwater Impact: 49000
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 5
MTBE Detected in Soil: Not reported
MTBE: 5
MTBE Qualify: Not reported

HAZNET:

Gepaid: CAC001303424
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .5421
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: ROMAN SAUSAGE CO
Telephone: (000) 000-0000
Mailing Address: 1810 RICHARD AVE
SANTA CLARA, CA 95050
County Santa Clara

CORTESE:

Reg Id: 43-0619
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

BD225
WNW
1/2-1
4828
Higher

3601 JULIETTE LANE
SANTA CLARA, CA 95054
Site 1 of 3 in cluster BD

CHMIRS S100280797
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

(Continued)

S100280797

CHMIRS:

OES Control Number: 8904732 DOT ID: 1830
DOT Hazard Class: Corrosives
Chemical Name: ACID, SULFURIC
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: 1
Environmental Contamination: None Reported Property Use: Manufacturing
Incident Date: 20-JAN-89 Date Completed: 20-JAN-89

BD226
WNW
1/2-1
4828
Higher

3601 JULIETTE LANE
SANTA CLARA, CA 95052

CHMIRS S100235517
Cortese N/A

Site 2 of 3 in cluster BD

CORTESE:

Reg Id: 2 438223N02
Region: CORTESE
Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

Reg Id: 43-1956
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

CHMIRS:

OES Control Number: 8904732 DOT ID: 1830
DOT Hazard Class: Corrosives
Chemical Name: ACID, SULFURIC
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: 1
Environmental Contamination: None Reported Property Use: Manufacturing
Incident Date: 20-JAN-89 Date Completed: 20-JAN-89

BD227
WNW
1/2-1
4828
Higher

INTEL CORPORATION, FABRICATION PLANT ONE
3601 JULIETTE LANE
SANTA CLARA, CA 95050

Cal-Sites S101482360
N/A

Site 3 of 3 in cluster BD

CAL-SITES:

Facility ID 43360109
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 03/25/1995
Lead: Not reported
Region: 2 - BERKELEY
Branch: NC - NORTH COAST
File Name: Not reported
Status Name: PROPERTY/SITE REFERRED TO RWQCB
Lead Agency: N/A Not reported
NPL: Not reported
SIC: 36 MANU - ELECTRONIC & OTHER ELECTRIC EQUIP
Facility Type: N/A
Type Name: Not reported
Staff Member Responsible for Site: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

INTEL CORPORATION, FABRICATION PLANT ONE (Continued)

S101482360

Supervisor Responsible for Site: Not reported
Region Water Control Board: SF - SAN FRANCISCO BAY
Access: Not reported
Cortese: Not reported
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Not reported
No. of Contamination Sources: 0
Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
Lat/long Method: Not reported
State Assembly District Code: 22
State Senate District: 13

The CAL-SITES database may contain additional details for this site.
Please contact your EDR Account Executive for more information.

228
NE
1/2-1
4857
Lower

VANDERHULST ASSOCIATES
3300 VICTOR CT
SANTA CLARA, CA 95054

RCRIS-SQG 1000820115
FINDS CAD983661398
HAZNET
Cortese

RCRIS:

Owner: HANK VANDERHULST
(408) 727-1313
EPA ID: CAD983661398
Contact: HANK VANDERHULST
(408) 727-1313

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

HAZNET:

Gepaid: CAD983661398
Tepaid: CAL000048571
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .6880
Category: Unspecified oil-containing waste
Disposal Method: Not reported
Contact: HANK VANDERHULST
Telephone: (000) 000-0000
Mailing Address: 3300 VICTOR CT
SANTA CLARA, CA 95054
County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

VANDERHULST ASSOCIATES (Continued)

1000820115

Gepaid: CAD983661398
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .6880
Category: ***
Disposal Method: Transfer Station
Contact: HANK VANDERHULST
Telephone: (000) 000-0000
Mailing Address: 3300 VICTOR CT
SANTA CLARA, CA 95054
County Santa Clara

Gepaid: CAD983661398
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 1.3760
Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Contact: HANK VANDERHULST
Telephone: (000) 000-0000
Mailing Address: 3300 VICTOR CT
SANTA CLARA, CA 95054
County Santa Clara

Gepaid: CAD983661398
Tepaid: CAD053044053
Gen County: Santa Clara
Tsd County: 1
Tons: .0333
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: HANK VANDERHULST
Telephone: (000) 000-0000
Mailing Address: 3300 VICTOR CT
SANTA CLARA, CA 95054
County Santa Clara

Gepaid: CAD983661398
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: 1.7305
Category: Unspecified oil-containing waste
Disposal Method: Not reported
Contact: HANK VANDERHULST
Telephone: (000) 000-0000
Mailing Address: 3300 VICTOR CT
SANTA CLARA, CA 95054
County Santa Clara

The CA HAZNET database contains 8 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:
Reg Id: 43-1358
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

229
 SE
 1/2-1
 4858
 Higher

RICHARD WEHNER CONST COMP
 390 MARTIN
 SANTA CLARA, CA 95050

Cortese S101304272
 N/A

CORTESE:
 Reg Id: 43-0688
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

230
 SSE
 1/2-1
 4903
 Higher

VARGAS GARDENING SERVICE
 495 ROBERT AVE
 SANTA CLARA, CA

Cortese S101309464
 N/A

CORTESE:
 Reg Id: 43-1662
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

231
 NE
 1/2-1
 4938
 Lower

VIKING FREIGHT SYSTEMS
 3405 VICTOR ST
 SANTA CLARA, CA

Cortese S101309471
 N/A

CORTESE:
 Reg Id: 43-1606
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

232
 SSE
 1/2-1
 5034
 Higher

JENIC
 448 ROBERT AVE
 SANTA CLARA, CA

Cortese S101309463
 N/A

CORTESE:
 Reg Id: 43-0746
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

233
 SE
 1/2-1
 5055
 Higher

GUILIO CHIOINI
 382 MARTIN AVE
 SANTA CLARA, CA 95054

HAZNET S102431082
 Cortese N/A

HAZNET:
 Gepaid: CAC001472512
 Tepaid: CAD981382732
 Gen County: Santa Clara
 Tsd County: 1
 Tons: 5.0568
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: GUILIO CHIOINI

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

GUILIO CHIOINI (Continued)

S102431082

Telephone: (408) 286-6300
Mailing Address: 2294 WALSH
SANTA CLARA, CA 95054
County Santa Clara

CORTESE:

Reg Id: 43-0671
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

234
West
1/2-1
5090
Higher

FILTRONIC SOLID STATE
3251 OLCOTT ST
SANTA CLARA, CA 95054

RCRIS-SQG 1000245627
FINDS CAT000625392
HAZNET
CORRACTS
CERC-NFRAP

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Non NPL Code: DR
Ownership Status: Private
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
Assessment: PRELIMINARY ASSESSMENT
Completed: 04/01/1991
Completed: 09/09/1991

CORRACTS Data:

EPA Id: CAT000625392
Region: 9
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 09/06/1991
Corrective Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

RCRIS Corrective Action Summary:

Event: CA Prioritization, Facility or area was assigned a low corrective action priority.
Event Date: 09/06/1991

RCRIS:

Owner: SOLID STATE FILTRONIC INC
(408) 988-1331
EPA ID: CAT000625392
Contact: ENVIRONMENTAL MANAGER
Rank Status: 3
Rank Date: 08/27/1992
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	TSD-MANIFEST REQUIREMENTS
Date Violation Determined:	08/10/1995
Actual Date Achieved Compliance:	21-SEP-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/10/1995
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-CONTINGENCY PLAN REQUIREMENTS
Date Violation Determined:	08/10/1995
Actual Date Achieved Compliance:	11-SEP-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/10/1995
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	08/10/1995
Actual Date Achieved Compliance:	11-SEP-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/10/1995
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	08/10/1995
Actual Date Achieved Compliance:	18-SEP-95
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	08/10/1995
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	04/05/1994
Actual Date Achieved Compliance:	21-APR-94
Regulation Violated:	Not reported
Area of Violation:	TSD-CONTAINERS REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-CONTINGENCY PLAN REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-OTHER REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-MANIFEST REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
Date Violation Determined:	11/09/1992
Actual Date Achieved Compliance:	15-JUL-93
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

FILTRONIC SOLID STATE (Continued)

1000245627

Regulation Violated:	Not reported
Area of Violation:	TSD-CONTINGENCY PLAN REQUIREMENTS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-CONTAINERS REQUIREMENTS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-MANIFEST REQUIREMENTS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

Regulation Violated:	Not reported
Area of Violation:	GENERATOR-OTHER REQUIREMENTS
Date Violation Determined:	10/22/1991
Actual Date Achieved Compliance:	09-DEC-92
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	11/13/1992
Penalty Type:	Final Monetary Penalty
Enforcement Action:	INITIAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	02/11/1993
Penalty Type:	Final Monetary Penalty
Regulation Violated:	Not reported
Area of Violation:	TSD-OTHER REQUIREMENTS
Date Violation Determined:	07/25/1989
Actual Date Achieved Compliance:	16-OCT-89
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/06/1989
Penalty Type:	Not reported

There are 19 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	TSD-MANIFEST REQUIREMENTS	21-SEP-95
	TSD-CONTINGENCY PLAN REQUIREMENTS	11-SEP-95
	TSD-GENERAL STANDARDS	11-SEP-95
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	18-SEP-95
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	21-APR-94
Compliance Evaluation Inspection	TSD-CONTAINERS REQUIREMENTS	15-JUL-93
	TSD-CONTINGENCY PLAN REQUIREMENTS	15-JUL-93
	TSD-GENERAL STANDARDS	15-JUL-93
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	15-JUL-93
	GENERATOR-OTHER REQUIREMENTS	15-JUL-93
	GENERATOR-MANIFEST REQUIREMENTS	15-JUL-93
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	15-JUL-93
	TSD-CONTINGENCY PLAN REQUIREMENTS	09-DEC-92
	TSD-CONTAINERS REQUIREMENTS	09-DEC-92
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	09-DEC-92
Compliance Evaluation Inspection	TSD-GENERAL STANDARDS	09-DEC-92
	GENERATOR-MANIFEST REQUIREMENTS	09-DEC-92
	GENERATOR-OTHER REQUIREMENTS	09-DEC-92
	TSD-OTHER REQUIREMENTS	16-OCT-89

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRS Facility System (AIRS/AFS)
- Biennial Reporting System (BRS)
- Facility Registry System (FRS)
- National Emissions Trends (NET)
- National Toxics Inventory (NTI)
- Resource Conservation and Recovery Act Information system (RCRAINFO)

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

HAZNET:

Gepaid: CAT000625392
Tepaid: CAD069138899
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .0083
Category: Liquids with cyanides > 1000 mg/l
Disposal Method: Recycler
Contact: SOLID STATE FILTRONIC,PLC
Telephone: (408) 988-1331
Mailing Address: 3251 OLCOTT ST
SANTA CLARA, CA 95054 - 3006
County: Santa Clara

Gepaid: CAT000625392
Tepaid: CAD069138899
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1083
Category: Unspecified aqueous solution
Disposal Method: Recycler
Contact: SOLID STATE FILTRONIC,PLC
Telephone: (408) 988-1331
Mailing Address: 3251 OLCOTT ST
SANTA CLARA, CA 95054 - 3006
County: Santa Clara

Gepaid: CAT000625392
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .0834
Category: Unspecified solvent mixture Waste
Disposal Method: Recycler
Contact: SOLID STATE FILTRONIC,PLC
Telephone: (408) 988-1331
Mailing Address: 3251 OLCOTT ST
SANTA CLARA, CA 95054 - 3006
County: Santa Clara

Gepaid: CAT000625392
Tepaid: CAD050806850
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: 2.1250
Category: Unspecified solvent mixture Waste
Disposal Method: Recycler
Contact: SOLID STATE FILTRONIC,PLC
Telephone: (408) 988-1331
Mailing Address: 3251 OLCOTT ST
SANTA CLARA, CA 95054 - 3006
County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

Gepaid: CAT000625392
Tepaid: CAD050806850
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .0005
Category: Off-specification, aged, or surplus inorganics
Disposal Method: Not reported
Contact: SOLID STATE FILTRONIC,PLC
Telephone: (408) 988-1331
Mailing Address: 3251 OLCOTT ST
SANTA CLARA, CA 95054 - 3006
County: Santa Clara

The CA HAZNET database contains 162 additional records for this site.
Please contact your EDR Account Executive for more information.

BE235
NE
1/2-1
5098
Lower

NORCAL ACOUSTICS
3500 VICTOR ST
SANTA CLARA, CA 95054

LUST S100235582
Cortese N/A

Site 1 of 2 in cluster BE

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0984
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 43099
Case Type: Soil only
Status: Signed off, remedial action completed or deemed unnecessary
County: Santa Clara
Abate Method: No Action Taken - no action has as yet been taken at the site
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 12/16/1996
Release Date: 2/13/1989
Cleanup Fund Id: Not reported
Discover Date: 2/9/1989
Enforcement Dt: 8/27/1991
Enf Type: Not reported
Enter Date: 4/21/1989
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: 06S1W26B05
Beneficial: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NORCAL ACOUSTICS (Continued)

S100235582

Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 5/8/1997
Stop Date : 2/9/1989
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500983
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2764.6291577483017048612950419
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0984
Entered Date: 04/21/1989
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 610
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O131
Transfer Date: Not reported
Closed Date: 12/16/1996
SCVWD Id: 06S1W26B05f

CORTESE:

Reg Id: 43-0984
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

BF236
SSE
1/2-1
5102
Higher

LOMBARDO DIAMOND CORE DRILLING CO., INC.
585 ROBERT AVENUE
SANTA CLARA, CA 95050

Cal-Sites S101482291
N/A

Site 1 of 2 in cluster BF

CAL-SITES:

Facility ID 43160003
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 08/17/1995
Lead: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

LOMBARDO DIAMOND CORE DRILLING CO., INC. (Continued)

S101482291

Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 16 HEAVY CONSTRUCTION, EXCEPT BUILDING
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: SF - SAN FRANCISCO BAY
 Access: Controlled
 Cortese: C
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

BF237
 SSE
 1/2-1
 5102
 Higher

**LOMBARDO DIAMOND CORE
 DRILLING CO., INC.
 SANTA CLARA, CA 95050**
 Site 2 of 2 in cluster BF

**HAZNET S101542321
 Cortese N/A
 CA SLIC**

HAZNET:
 Gepaid: CAD052971587
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .3336
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County: Santa Clara
 Gepaid: CAD052971587
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .2919
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County: Santa Clara

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

LOMBARDO DIAMOND CORE (Continued)

S101542321

Gepaid: CAD052971587
 Tepaid: CAL000161743
 Gen County: Santa Clara
 Tsd County: Santa Clara
 Tons: .1459
 • Category: Unspecified oil-containing waste
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County Santa Clara

Gepaid: CAD052971587
 Tepaid: CAD980887418
 Gen County: Santa Clara
 Tsd County: 1
 Tons: .3544
 Category: Waste oil and mixed oil
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County Santa Clara

Gepaid: CAD052971587
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .3961
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County Santa Clara

The CA HAZNET database contains 3 additional records for this site.
 Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2 438154N01
 Region: CORTESE
 Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

SLIC Region 2:

Facility ID:	43S0158	
Region:	2	
Facility Status:	Active	Not reported
Staff:	VAC	Not reported
Last Site Update:	10/01/19	
NPL Status:	Not an NPL site	Discovery Date: 09/30/1981
Case List:	SLIC	Imaged: No
Date Closed:	Not reported	Cost Recovery: YES
Abate Method:	Not reported	Substance: Not reported
Case Type:	NT	Sample Date: 10/24/1991

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

LOMBARDO DIAMOND CORE (Continued)

S101542321

Contamination: LOCALIZED SPILLS
 Lead: 2189.8154 RWQCB
 Contamination Level: NONE DETECTED
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Yes
 Soil Removal or Contaminant Action Started: 09/01/1983
 Soil Removal or Contaminant Action Completed: 10/1/83
 On-Site Groundwater Extraction or Containment is Needed: Not Determined
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed: Not Determined
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 70
 Depth of Contamination Plume (Feet): 35
 Wells Closed Due To Contamination of Site: NONE
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 1200
 Under Jurisdiction of Lead Agency Date: 3/27/80
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes
 Begun Remediation: Yes
 Completed Remediation: Yes
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: METAL GALVANIZING FACILITY
 Comment: Not reported

238
 SSE
 1/2-1
 5136
 Higher

GANGI BROTHERS
725 MATHEW ST
SANTA CLARA, CA 95050

HAZNET S100274433
Cortese N/A

HAZNET:
 Gepaid: CAC001315528
 Tepaid: CAD990794133
 Gen County: Santa Clara
 Tsd County: San Joaquin
 Tons: .8428
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: GANGI BROTHERS INC
 Telephone: (209) 869-9300
 Mailing Address: PO BOX 830
 RIVERBANK, CA 95367
 County: Santa Clara

CORTESE:
 Reg Id: 43-0627
 Region: CORTESE

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

GANGI BROTHERS (Continued)

Reg By: Leaking Underground Storage Tanks

EDR ID Number
 EPA ID Number

Database(s)

S100274433

BE239
 NE
 1/2-1
 5139
 Lower

ULTRA PHASE SHEET METAL
 3525 VICTOR ST
 SANTA CLARA, CA 95054

Cortese S100850435
 N/A

Site 2 of 2 in cluster BE

CORTESE:

Reg Id: 43-2314
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

240
 South
 1/2-1
 5177
 Higher

COMMERCIAL FUELING SYSTEM
 2265 LAFAYETTE ST
 SANTA CLARA, CA 95050

LUST S105032575
 Cortese N/A

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0396
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency: 43099
 Case Type: Other ground water affected
 Status: Pollution characterization
 County: Santa Clara
 Abate Method: Remove Free Product - remove floating product from water table
 Review Date: Not reported
 Workplan: 5/15/1991
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: Not reported
 Release Date: 10/15/1984
 Cleanup Fund Id: Not reported
 Discover Date: 12/13/1989
 Enforcement Dt: Not reported
 Enf Type: Not reported
 Enter Date: 10/25/1984
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim: Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date: 1/2/1965
 Max MTBE GW: 1600
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case #: 06S1W35N02
 Beneficial: Not reported
 Staff: CTH
 GW Qualifies: Not reported
 Max MTBE Soil: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

FILTRONIC SOLID STATE (Continued)

1000245627

Gepaid: CAT000625392
 Tepaid: CAD050806850
 Gen County: Santa Clara
 Tsd County: Los Angeles
 Tons: .0005
 Category: Off-specification, aged, or surplus inorganics
 Disposal Method: Not reported
 Contact: SOLID STATE FILTRONIC,PLC
 Telephone: (408) 988-1331
 Mailing Address: 3251 OLCOTT ST
 SANTA CLARA, CA 95054 - 3006
 County: Santa Clara

The CA HAZNET database contains 162 additional records for this site.
 Please contact your EDR Account Executive for more information.

BE235
 NE
 1/2-1
 5098
 Lower

NORCAL ACOUSTICS
3500 VICTOR ST
SANTA CLARA, CA 95054

LUST S100235582
Cortese N/A

Site 1 of 2 in cluster BE

State LUST:

Cross Street:	Not reported	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	Not reported
Case Number	43-0984	Remed Plan:	Not reported
Reg Board:	San Francisco Bay Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Regional Board		
Local Agency :	43099		
Case Type:	Soil only		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	Santa Clara		
Abate Method:	No Action Taken - no action has as yet been taken at the site		
Review Date:	Not reported		
Workplan:	Not reported		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	12/16/1996		
Release Date:	2/13/1989		
Cleanup Fund Id :	Not reported		
Discover Date :	2/9/1989		
Enforcement Dt :	8/27/1991		
Enf Type:	Not reported		
Enter Date :	4/21/1989		
Funding:	Federal Funds		
Staff Initials:	UNK		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	No		
Leak Cause:	Structure Failure		
Leak Source:	Tank		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.		
Priority:	Not reported		
Local Case # :	06S1W26B05		
Beneficial:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NORCAL ACOUSTICS (Continued)

S100235582

Staff : CTH
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 5/8/1997
Stop Date : 2/9/1989
Work Suspended : N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500983
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 2764.6291577483017048612950419
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0984
Entered Date: 04/21/1989
Facility Status: Signed off, remedial action completed or deemed unnecessary
Maximum Soil Concentration: 610
Maximum Groundwater Impact: 0
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: Not reported
MTBE Detected in Soil: Not reported
MTBE: 0
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O131
Transfer Date: Not reported
Closed Date: 12/16/1996
SCVWD Id: 06S1W26B05f

CORTESE:

Reg Id: 43-0984
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

BF236
SSE
1/2-1
5102
Higher

LOMBARDO DIAMOND CORE DRILLING CO., INC.
585 ROBERT AVENUE
SANTA CLARA, CA 95050

Cal-Sites S101482291
N/A

Site 1 of 2 in cluster BF

CAL-SITES:

Facility ID 43160003
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 08/17/1995
Lead: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

LOMBARDO DIAMOND CORE DRILLING CO., INC. (Continued)

S101482291

Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 16 HEAVY CONSTRUCTION, EXCEPT BUILDING
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: SF - SAN FRANCISCO BAY
 Access: Controlled
 Cortese: C
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

BF237
 SSE
 1/2-1
 5102
 Higher

**LOMBARDO DIAMOND CORE
 DRILLING CO., INC.
 SANTA CLARA, CA 95050**
 Site 2 of 2 in cluster BF

HAZNET S101542321
 Cortese N/A
 CA SLIC

HAZNET:
 Gepaid: CAD052971587
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .3336
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County: Santa Clara
 Gepaid: CAD052971587
 Tepaid: CAD009452657
 Gen County: Santa Clara
 Tsd County: San Mateo
 Tons: .2919
 Category: Unspecified organic liquid mixture
 Disposal Method: Recycler
 Contact: RICHARD LONG
 Telephone: (000) 000-0000
 Mailing Address: 2225 DE LA CRUZ
 SANTA CLARA, CA 00000
 County: Santa Clara

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

LOMBARDO DIAMOND CORE (Continued)

S101542321

Gepaid: CAD052971587
Tepaid: CAL000161743
Gen County: Santa Clara
Tsd County: Santa Clara
Tons: .1459
• Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: RICHARD LONG
Telephone: (000) 000-0000
Mailing Address: 2225 DE LA CRUZ
SANTA CLARA, CA 00000
County: Santa Clara
Gepaid: CAD052971587
Tepaid: CAD980887418
Gen County: Santa Clara
Tsd County: 1
Tons: .3544
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: RICHARD LONG
Telephone: (000) 000-0000
Mailing Address: 2225 DE LA CRUZ
SANTA CLARA, CA 00000
County: Santa Clara
Gepaid: CAD052971587
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .3961
Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Contact: RICHARD LONG
Telephone: (000) 000-0000
Mailing Address: 2225 DE LA CRUZ
SANTA CLARA, CA 00000
County: Santa Clara

The CA HAZNET database contains 3 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 2 438154N01
Region: CORTESE
Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

SLIC Region 2:

Facility ID: 43S0158
Region: 2
Facility Status: Active Not reported
Staff: VAC Not reported
Last Site Update: 10/01/19
NPL Status: Not an NPL site
Case List: SLIC
Date Closed: Not reported
Abate Method: Not reported
Case Type: NT
Discovery Date: 09/30/1981
Imaged: No
Cost Recovery: YES
Substance: Not reported
Sample Date: 10/24/1991

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

LOMBARDO DIAMOND CORE (Continued)

S101542321

Contamination: LOCALIZED SPILLS
 Lead: 2189.8154 RWQCB
 Contamination Level: NONE DETECTED
 Number of Municipal Wells Contaminated by Site: 0
 Number of Private Wells Contaminated by Site: 0
 Soil Removal Action Taken/Needed: Yes
 Soil Removal or Contaminant Action Started: 09/01/1983
 Soil Removal or Contaminant Action Completed: 10/1/83
 On-Site Groundwater Extraction or Containment is Needed: Not Determined
 On-Site Groundwater Extraction or Containment Started:
 Off-Site Groundwater Extraction or Containment is Needed: Not Determined
 Off-Site Groundwater Extraction or Containment Started:
 Length of Contamination Plume (Feet): 70
 Depth of Contamination Plume (Feet): 35
 Wells Closed Due To Contamination of Site: NONE
 Date of Wells Closure:
 Nearest Public or Private Drinking Water Well (Feet): 1200
 Under Jurisdiction of Lead Agency Date: 3/27/80
 Latitude/Longitude: 37 / -122
 Flow Rate: 0
 Flow Date:
 Percent of Contaminants Contained: 0
 Contaminant Type:
 EPA ID:
 Stages of Site Investigation Process Initiated:
 Begun Characterization : Yes
 Completed Characterization : Yes
 Begun Remediation: Yes
 Completed Remediation: Yes
 Submitted Remediation Plan: No
 Approved Remediation Plan: No
 Begun Final Remedial Action: No
 Completed Final Remedial Action: No
 Facility Desc: METAL GALVANIZING FACILITY
 Comment: Not reported

238
 SSE
 1/2-1
 5136
 Higher

GANGI BROTHERS
725 MATHEW ST
SANTA CLARA, CA 95050

HAZNET S100274433
Cortese N/A

HAZNET:
 Gepaid: CAC001315528
 Tepaid: CAD990794133
 Gen County: Santa Clara
 Tsd County: San Joaquin
 Tons: .8428
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: GANGI BROTHERS INC
 Telephone: (209) 869-9300
 Mailing Address: PO BOX 830
 RIVERBANK, CA 95367
 County: Santa Clara

CORTESE:
 Reg Id: 43-0627
 Region: CORTESE

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

GANGI BROTHERS (Continued)

S100274433

Reg By: Leaking Underground Storage Tanks

BE239
NE
1/2-1
5139
Lower

ULTRA PHASE SHEET METAL
3525 VICTOR ST
SANTA CLARA, CA 95054

Cortese S100850435
N/A

Site 2 of 2 in cluster BE

CORTESE:

Reg Id: 43-2314
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

240
South
1/2-1
5177
Higher

COMMERCIAL FUELING SYSTEM
2265 LAFAYETTE ST
SANTA CLARA, CA 95050

LUST S105032575
Cortese N/A

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 43-0396
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 43099
Case Type: Other ground water affected
Status: Pollution characterization
County: Santa Clara
Abate Method: Remove Free Product - remove floating product from water table
Review Date: Not reported
Workplan: 5/15/1991
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 10/15/1984
Cleanup Fund Id: Not reported
Discover Date: 12/13/1989
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 10/25/1984
Funding: Federal Funds
Staff Initials: UNK
How Discovered: Tank Closure
How Stopped: Close Tank
Interim: Yes
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: 1/2/1965
Max MTBE GW: 1600
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: 06S1W35N02
Beneficial: Not reported
Staff: CTH
GW Qualifies: Not reported
Max MTBE Soil: Not reported

Confirm Leak: Not reported
Prelim Assess: 5/15/1991
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

COMMERCIAL FUELING SYSTEM (Continued)

S105032575

Soil Qualifies : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 11/21/1997
Stop Date : 12/13/1989
Work Suspended :N
Responsible Party:BLANK RP
RP Address: Not reported
Global Id: T0608500447
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 3018.3981521252137010088693639
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0396
Entered Date: 10/25/1984
Facility Status: Pollution characterization
Maximum Soil Concentration: 350
Maximum Groundwater Impact: 9999999
County : Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 1600
MTBE Detected in Soil: Not reported
MTBE: 1600
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O431
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W35N02f

CORTESE:

Reg Id: 43-0396
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

241
NE
1/2-1
5178
Lower

L & O FLOORS
3545 65 VICTOR ST
SANTA CLARA, CA 95054

LUST S104397035
Cortese N/A

State LUST:

Cross Street: Not reported
Qty Leaked: Not reported
Case Number 43-2276
Reg Board: San Francisco Bay Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency : 43099
Case Type: Other ground water affected

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

L & O FLOORS (Continued)

S104397035

Status: Preliminary site assessment workplan submitted
 County: Santa Clara
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Close Date: Not reported
 Release Date: 2/5/1986
 Cleanup Fund Id : Not reported
 Discover Date : 2/5/1986
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 10/16/1998
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : Not reported
 Leak Cause: Unknown
 Leak Source: Unknown
 MTBE Date : 1/2/1965
 Max MTBE GW : 120
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case # : 06S1W23Q01
 Beneficial: Not reported
 Staff : CTH
 GW Qualifies : Not reported
 Max MTBE Soil : 5
 Soil Qualifies : Not reported
 Hydr Basin #: Not reported
 Operator : Not reported
 Oversight Prgm: Local Oversight Program UST
 Oversight Prgm : LOP
 Review Date : 2/1/2001
 Stop Date : 2/5/1986
 Work Suspended :N
 Responsible Party:BLANK RP
 RP Address: Not reported
 Global Id: T0608502091
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 2
 Mtbe Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Lust: 2482.1075084712970039820517625
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 2:
 Region: 2
 Facility Id: 43-2276
 Entered Date: 10/16/1998
 Facility Status: Preliminary site assessment workplan submitted
 Maximum Soil Concentration: 0
 Maximum Groundwater Impact: 120
 County : Santa Clara

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

L & O FLOORS (Continued)

S104397035

Current Benzene: Not reported
 MTBE Detected in GW: 120
 MTBE Detected in Soil: 5
 MTBE: 120
 MTBE Qualify: Not reported

CORTESE:

Reg Id: 43-2276
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

242
 WSW
 1/2-1
 5181
 Higher

PACIFIC MAINTENANCE
2294 WALSH AVE
SANTA CLARA, CA 95050

LUST S101304311
Cortese N/A

State LUST:

Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number: 43-0664
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Signed off, remedial action completed or deemed unnecessary
 County: Santa Clara
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Review Date: Not reported	Confirm Leak: Not reported
Workplan: Not reported	Prelim Assess: Not reported
Pollution Char: Not reported	Remed Plan: Not reported
Remed Action: Not reported	Monitoring: Not reported

Close Date: 12/8/1997
 Release Date: 2/5/1992
 Cleanup Fund Id : Not reported
 Discover Date : 2/7/1992
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 2/20/1992
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : Yes
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : 1/2/1965
 Max MTBE GW : 5
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: Not reported
 Local Case # : 06S1W34E01
 Beneficial: Not reported
 Staff : CTH
 GW Qualifies : <
 Max MTBE Soil : Not reported
 Soil Qualifies : Not reported
 Hydr Basin #: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MEMOREX DR LLC (Continued)

S103977072

Gepaid: CAC001267280
Tepaid: CAD028409019
Gen County: Santa Clara
Tsd County: Los Angeles
Tons: .2500
Category: Other organic solids
Disposal Method: Transfer Station
Contact: MEMOREX DR LLC
Telephone: (000) 000-0000
Mailing Address: 4966 EL CAMINO REAL STE 209
LOS ALTOS, CA 94022
County Santa Clara
Gepaid: CAC001267280
Tepaid: CAT000646117
Gen County: Santa Clara
Tsd County: Kings
Tons: .1498
Category: Polychlorinated biphenyls and material containing PCB's
Disposal Method: Disposal, Land Fill
Contact: MEMOREX DR LLC
Telephone: (000) 000-0000
Mailing Address: 4966 EL CAMINO REAL STE 209
LOS ALTOS, CA 94022
County Santa Clara

CORTESE:

Reg Id: 2 438116N01
Region: CORTESE
Reg By: Cleanup or abatement orders that concern the discharge of wastes that are hazardous materials

BG247
South
1/2-1
5270
Higher

1200 MEMOREX DR.
SANTA CLARA, CA 95050
Site 2 of 6 in cluster BG

CHMIRS S100275599
N/A

CHMIRS:

OES Control Number: 8905556 DOT ID: Not reported
DOT Hazard Class: Not Reported
Chemical Name: CYCLOHEXANONE
Extent of Release: Not reported
CAS Number: Not reported Quantity Released: Not reported
Environmental Contamination: None Reported Property Use: Manufacturing
Incident Date: 07-APR-89 Date Completed: 07-APR-89

BG248
South
1/2-1
5270
Higher

MEMOREX DRIVE COMPLEX
1200 MEMOREX DRIVE
SANTA CLARA, CA 95052
Site 3 of 6 in cluster BG

Cal-Sites S100580915
N/A

CAL-SITES:

Facility ID 43380017
Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD
Status Date: 08/09/1996

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

MEMOREX DRIVE COMPLEX (Continued)

S100580915

Lead: Not reported
 Region: 2 - BERKELEY
 Branch: NC - NORTH COAST
 File Name: Not reported
 Status Name: PROPERTY/SITE REFERRED TO RWQCB
 Lead Agency: N/A Not reported
 NPL: Not reported
 SIC: 38 MANU - INSTRUMENTS & RELATED PRODUCTS
 Facility Type: N/A
 Type Name: Not reported
 Staff Member Responsible for Site: Not reported
 Supervisor Responsible for Site: Not reported
 Region Water Control Board: Not reported
 Access: Not reported
 Cortese: Not reported
 Hazardous Ranking Score: Not reported
 Date Site Hazard Ranked: Not reported
 Groundwater Contamination: Not reported
 No. of Contamination Sources: 0
 Lat/Long: 0° 0' 0.00" / 0° 0' 0.00"
 Lat/long Method: Not reported
 State Assembly District Code: Not reported
 State Senate District: Not reported

The CAL-SITES database may contain additional details for this site.
 Please contact your EDR Account Executive for more information.

BG249
 South
 1/2-1
 5270
 Higher

**1200 MEMOREX DR.
 SANTA CLARA, CA 95051**

Site 4 of 6 in cluster BG

**CHMIRS S100235543
 N/A**

CHMIRS:
 OES Control Number: 8905556 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: CYCLOHEXANONE
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: Not reported
 Environmental Contamination: None Reported Property Use: Manufacturing
 Incident Date: 07-APR-89 Date Completed: 07-APR-89

BG250
 South
 1/2-1
 5271
 Higher

**1155 MEMOREX DRIVE
 SANTA CLARA, CA 95050**

Site 5 of 6 in cluster BG

**CHMIRS S100275844
 N/A**

CHMIRS:
 OES Control Number: 9011655 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: MASTIC REMOVER
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 40
 Environmental Contamination: Ground Property Use: Manufacturing
 Incident Date: 13-JUN-90 Date Completed: 13-JUN-90

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

BG251 **BYINGTON STEEL TREATING, INC**
South **1225 MEMOREX DR**
1/2-1 **SANTA CLARA, CA 95050**
5278
Higher **Site 6 of 6 in cluster BG**

RCRIS-SQG **1000315381**
FINDS **CAD981171440**
HAZNET
LUST
Cortese
HIST UST

RCRIS:
 Owner: BYINTON STEEL TREATING, INC
 (415) 555-1212
 EPA ID: CAD981171440
 Contact: ENVIRONMENTAL MANAGER
 (408) 727-6630
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:
 Other Pertinent Environmental Activity Identified at Site:
 AIRS Facility System (AIRS/AFS)
 Facility Registry System (FRS)
 National Emissions Trends (NET)
 National Toxics Inventory (NTI)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

State LUST:
 Cross Street: Not reported
 Qty Leaked: Not reported
 Case Number 43-0220
 Reg Board: San Francisco Bay Region
 Chemical: Gasoline
 Lead Agency: Local Agency
 Local Agency : 43099
 Case Type: Other ground water affected
 Status: Preliminary site assessment underway
 County: Santa Clara
 Abate Method: No Action Taken - no action has as yet been taken at the site
 Review Date: Not reported Confirm Leak: Not reported
 Workplan: 1/2/1965 Prelim Assess: 1/2/1965
 Pollution Char: Not reported Remed Plan: Not reported
 Remed Action: Not reported Monitoring: Not reported
 Close Date: Not reported
 Release Date: 7/10/1987
 Cleanup Fund Id : Not reported
 Discover Date : 7/10/1987
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 7/20/1987
 Funding: Federal Funds
 Staff Initials: UNK
 How Discovered: Tank Closure
 How Stopped: Close Tank
 Interim : No
 Leak Cause: Structure Failure
 Leak Source: Tank
 MTBE Date : 1/2/1965
 Max MTBE GW : 25

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BYINGTON STEEL TREATING, INC (Continued)

1000315381

MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: 06S1W34R01
Beneficial: Not reported
Staff: CTH
GW Qualifies: Not reported
Max MTBE Soil: Not reported
Soil Qualifies: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm: LOP
Review Date: 2/1/2001
Stop Date: 7/10/1987
Work Suspended: N
Responsible Party: BLANK RP
RP Address: Not reported
Global Id: T0608500280
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 2777.8327953048854218945007524
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 2:

Region: 2
Facility Id: 43-0220
Entered Date: 07/20/1987
Facility Status: Preliminary site assessment underway
Maximum Soil Concentration: 950
Maximum Groundwater Impact: 25
County: Santa Clara
Current Benzene: Not reported
MTBE Detected in GW: 25
MTBE Detected in Soil: Not reported
MTBE: 25
MTBE Qualify: Not reported

LUST Region SC:

Region: Santa Clara
Case Rank: O141
Transfer Date: Not reported
Closed Date: Not reported
SCVWD Id: 06S1W34R01f

HAZNET:

Gepaid: CAD981171440
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .2293
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Not reported
Contact: BYINGTON STEEL TREATING INC
Telephone: (408) 727-6630
Mailing Address: 1225 MEMOREX DR
SANTA CLARA, CA 95050 - 2811

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

BYINGTON STEEL TREATING, INC (Continued)

1000315381

County Santa Clara
Gepaid: CAD981171440
Tepaid: CAD009452657
Gen County: Santa Clara
Jsd County: San Mateo
Tons: 2.7519
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Disposal, Other
Contact: BYINGTON STEEL TREATING INC
Telephone: (408) 727-6630
Mailing Address: 1225 MEMOREX DR
 SANTA CLARA, CA 95050 - 2811

County Santa Clara
Gepaid: CAD981171440
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .4587
Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Contact: BYINGTON STEEL TREATING INC
Telephone: (408) 727-6630
Mailing Address: 1225 MEMOREX DR
 SANTA CLARA, CA 95050 - 2811

County Santa Clara
Gepaid: CAD981171440
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: .4586
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Recycler
Contact: BYINGTON STEEL TREATING INC
Telephone: (408) 727-6630
Mailing Address: 1225 MEMOREX DR
 SANTA CLARA, CA 95050 - 2811

County Santa Clara
Gepaid: CAD981171440
Tepaid: CAD009452657
Gen County: Santa Clara
Tsd County: San Mateo
Tons: 2.2933
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Recycler
Contact: BYINGTON STEEL TREATING INC
Telephone: (408) 727-6630
Mailing Address: 1225 MEMOREX DR
 SANTA CLARA, CA 95050 - 2811

County Santa Clara

The CA HAZNET database contains 8 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:
Reg Id: 43-0220
Region: CORTESE

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

AMERICAN CAN PACKAGING INC (Continued)

1000360798

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported

Federal Facility: Not a Federal Facility

Non NPL Code: NFRAP

Ownership Status: Unknown

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY

Completed: 08/01/1980

Assessment: PRELIMINARY ASSESSMENT

Completed: 12/01/1987

CERCLIS-NFRAP Alias Name(s):

BARSTOW USCM LOGISTICS BASE-NEBO

**OWENS CORNING FIBERGLAS CORP
LOS ESTERRAS
SAN JOSE, CA 95050**

**CERC-NFRAP 1003878544
CAD980637334**

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported

Federal Facility: Not a Federal Facility

Non NPL Code: NFRAP

Ownership Status: Unknown

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY

Completed: 06/01/1981

Assessment: PRELIMINARY ASSESSMENT

Completed: 03/01/1987

Assessment: PRELIMINARY ASSESSMENT

Completed: 05/01/1988

**OWENS-CORNING FIBERGLAS CORP LDFL-ALVISO
LOS ESTEROS RD
SAN JOSE, CA 95134**

**Cal-Sites S100186305
N/A**

CAL-SITES:

Facility ID: 43490055

Status: REFRW - DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROLBOARD (RWQCB) LEAD

Status Date: 04/24/1987

Lead: Not reported

Region: 2 - BERKELEY

Branch: NC - NORTH COAST

File Name: Not reported

Status Name: PROPERTY/SITE REFERRED TO RWQCB

Lead Agency: N/A

Not reported

NPL: Not reported

SIC: 49 ELECTRIC, GAS & SANITARY SERVICES

Facility Type: N/A

Type Name: Not reported

Staff Member Responsible for Site: Not reported

Supervisor Responsible for Site: Not reported

Region Water Control Board: SF - SAN FRANCISCO BAY

Access: Controlled

Cortese: C

Hazardous Ranking Score: Not reported

Date Site Hazard Ranked: Not reported

Groundwater Contamination: Not reported

No. of Contamination Sources: 0